- Submit plugging report (CP-4) after plugging is completed;
- Obtain written approval before disposing or injecting salt water.

Mail to: Conservation Division, 200 Colorado Derby Building, 202 W. First St., Wichita, Kansas 67202-1286.

File Drill Pit Application (form CDP-1) with Intent to Drill;
 File Completion Form ACO-1 within 120 days of spud date;

File acreage attribution plat according to field proration orders;

REMEMBER TO:

- Notify appropriate district office 48 hours prior to workover or re-entry;

IN ALL CASES PLOT THE INTENTED WELL ON THE PLAT BELOW .

PLAT OF ACREAGE ATTRIBUTABLE TO A WELL IN A PRORATED OR SPACED FIELD

If the intented well is in a prorated or spaced field, please fully complete this side of the form. If the intented well is in a prorated or spaced field complete the plat below showing that the well will be properly located in relationship to other wells producing from the common source of—supply. Please show all the wells within 1 mile of the boundaries of the proposed acreage attribution unit for gas wells and within 1/2 mile of the boundaries of the proposed acreage attribution unit for oil wells.

API NO. 15-		
OPERATOR Pi	ckrell Drilling Co. Inc.	LOCATION OF WELL: COUNTY Ness
LEASE Dui	mler "U"	1650 feet from south north line of section
WELL NUMBER	1	1470 feet from east west line of section
· · · · · · · · · · · · · · · · · · ·	ansada	SECTION 14 TWP 17S RG 26W
		<u> </u>
NUMBER OF ACRES	ES ATTRIBUTABLE TO WELL	IS SECTION X REGULAR or IRREGULAR
QTR/QTR/QTR OF	ACREAGE	IF SECTION IS IRREGULAR, LOCATE WELL FROM NEAREST
,		CORNER BOUNDARY.
		Section corner used: NE X NW SE SW
		PLAT
(Show location of the well and shade attributable acreage for prorated or spaced wells.)		
(Show footage to the nearest lease or unit boundary line.)		
		, , , ,
		
4		
ļ ļ		
<u> </u>		••••
	1650	
		— EXAMPLE
4 1470		
		G 4 / /980 -
		40
	14	3300 - ACRES
1 1		ED unissolu
\' <u>_</u>		SEWARD CO.
1 • 1		AEORATIO A AM
		COBPC 1994
		SEWARD CO. RECEIVE COMMISSION RECEIVE COMMISSION OCT 1 2 1994 Pro- OCT 1 2 1994 P
] "		OCT CHISTO
<u>.</u> .	* *	"IATON KE
		MEERINGHIT A.

In plotting the proposed location of the well, you must show:

ONE SECTION

- 1) The manner in which you are using the depicted plat by identifying section lines, i.e. 1 section, 1 section with 8 surrounding sections, 4 sections, etc.;
- 2') the distance of the proposed drilling location from the section's south/north and east/west lines; and
- 3) the distance to the nearest lease or unit boundary line.