KANSAS STATE CORPORATION COMMISSION

4-12-61

CONSERVATION DIVISION AGENT'S REPORT

| Jewel M. Ogden, Director | CIVISION CONTRACTOR |
|---|-----------------------------|
| 500 Insurance Building 212 North Market | THE SECOND |
| | |
| File No County: Twp Name of Field: Tot | / |
| Location: Sec. 14 Twp | |
| Name of Field:Tot | al Depth: 4528 |
| I have this date completed supervision of plugging of: | |
| Derator's Full Name: Juin Ally Co | Well No/ |
| Operator's Full Name: June Ally Co | |
| Complete Address: 1005 Cent Bed - Much | ta Kano. |
| Plugging Contractor: | ' 1 |
| Plugging Contractor: Address: | License No. |
| Oil Well Gas Well Input Well S | WD Well D & A |
| Other well as hereafter indicated: | |
| Was any delay in plugging operations caused by Conservation | on Division Agent? Yes No 💹 |
| If yes how long? Reason: | |
| • | |
| | |
| Operation Completed: Hour 20M. Day 31 | Month March Year 1961 |
| The above well was plugged as follows: | |
| 1.11-4525-858-202-4/2-4523- | Perfs 4567 + 4436 |
| Sand to 4425 topped with 20 sa | Lowent Shot 4/2" |
| Sipe and sulled same out of | lale Sisland much |
| Som sitt to 200 and desplaced | 20 sal coment P.H. |
| Smed to 40' built rock bridge an | d displaced 10 sal |
| conent, comenting to base of cellar. | |
| | |
| | |
| 1 | 1 |
| Signed: | theit P. Like |
| | Conservation Division Agent |
| Reviewed: Lustes Broke Field Supervisor | |
| Remarks: | INVOICED |

INVOICED

INV. NO. 2939-W