

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
800 BITTING BUILDING
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM

Lease Owner SHADE & BERRY Address 401 Ritz Building
(Applicant) Tulsa, Oklahoma
Lease (Farm Name) Weistrell Unit Well No. 1

Well Location 2650/S: 330/E Sec. 9 Twp. 11 Rge. 18 (E)-(W) ext

County Ellis Field Name (if any) wildcat

Total Depth 3563 Oil Gas Dry Hole X

Was well log filed with application? yes. If not, explain:

Date and hour plugging is desired to begin At Once

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission, or with the approval of the following exceptions: Explain fully any exceptions desired.

(Use an additional sheet if necessary)

Name of the person on the lease in charge of well for owner

J. C. Dinger, Jr. Address Great Bend, Kansas

Name of Plugging Contractor Transit Corporation

Address 1516 Liberty Bank Building, Oklahoma City, Oklahoma

Invoice covering assessment for plugging this well should be sent to

Shade & Berry Address 401 Ritz Bldg., Tulsa, Okla.

and payment will be guaranteed by applicant.

RECEIVED
STATE CORPORATION COMMISSION

Shade & Berry

BY: [Signature]
Applicant or Acting Agent

CONSERVATION DIVISION
Wichita, Kansas

Date July 13, 1956

7-25-56

PLUGGING
FILE SEC. 9 T. 11 R. 18W
BOOK PAGE 80 LINE 1



STATE OF KANSAS
 STATE CORPORATION COMMISSION
 CONSERVATION DIVISION
 211 NORTH BROADWAY
 WICHITA, KANSAS

July 13, 1956

Well No.	1
Lease	Metstrell
Description	SE SE NE 9-11-18W
County	Ellis
File No.	CC-1

Shade F Perry
 101 Fifth Building
 Tulsa, Oklahoma

Gentlemen.

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. Milton Galyardt, Box 145, Bus Hill, Kansas.

STATE CORPORATION COMMISSION
 CONSERVATION DIVISION

By S. S. Greider
 S. S. Greider
 WELL PLUGGING SUPERVISOR

cc:
 District Plugging Supervisor