FORM CP-4

STATE OF KANSAS STATE COMPONATION COMMISSION COMMERVATION DEVISION P. O. BOX 17027 VICHITA, KANSAS 67317

## WELL PLUGGING RECORD

		Ness	Count	y. Sec. 13 T	wp 19 Rge	$25 (E) (W)_X$
NORTH	Location as "NI	E/CNWKSWXT	or footage fro	m linesC	/SE/SE	<u> </u>
! !	Lease Owner  Lease Name			·		Well No. 1
	Lease Name	ON Edward	at Matt	Blda W		
	Office Address 801 First Natil. Bldg., Wichita, Kansas 67202  Character of Well (completed as Oil, Gas or Dry Hole)					
		Date well completed 19.				
l i l i	Application for		·		March	
	Application for					· 19
i i i	Plugging comme				March	4, 19 75
	Plugging comple					31, 19.75
	Reason for abandonment of well or producing formationDepleted					
	If a producing	well is abandor	ned, date of la	st production_	<del> </del>	19
Locate well correctly on above			n the Conserv	ation Division o	or its agents before	plugging was com-
Section Plat	menced?		o Massey		· · · · · · · · · · · · · · · · · · ·	
aine of Conservation Agent who sup-	ervised plugging of this	· ~ · · · · · · · · · · · · · · · · · ·	<u></u>			- /200 1/2
roducing formation.	D	epth to top	Botton		Total Depth of W	ell 4399 1/4•••
how depth and tlackness of all water	r, oil and gas formation	5.				
OIL, CAS OR WATER RECORD	DS	•			CA	SING RECORD
FORMATION	CONTENT	FROM	ТО	SIZE	arr m	BHILES OUT
r u sma pies	SOULEM!	7,007	1	<del>                                     </del>	452	PULLED OUT
	<u> </u>	· · · · · · · · · · · · · · · · · · ·	+	8 5/8 51/2	4399	2395.901
<del></del>	<del> </del>	<u> </u>	<del> </del>	21/2	4377	2393.90.
			+	<del> </del>	<del>                                     </del>	<del></del>
<del></del>			1	<del></del>	<del> </del>	
		· · · ·	+		<del>                                     </del>	<del></del>
	1					
_	nent or other plugs we					nod or methods used
fintroducing it into the bole. If cenfect for each plug at the bole in the bol	T.D. Dumped	sandto 43	he character of	5 sacks ce	h placed, from  ment Shot	feet to
Introducing it into the bole. If cen fect for each plug a  Measured casing at 4000 and 24251. Pu	T.D. Dumped 1, 3800, 3720, 11ed a total	sandto 43 3500, 32 of 67 joi	1901 and	5 sacks ce 2800, 20	ament Shot	
Measured  casing at 4000 and 24251. Pu  well with 1 sa	T.D. Dumped 3800, 3720, 11ed a total ck hulls, 25	sandto 43 3500, 32 of 67 joi	1901 and	5 sacks ce 2800, 20	ament Shot	feet to
Measured casing at 4000 and 24251. Pu	T.D. Dumped 3800, 3720, 11ed a total ck hulls, 25	sandto 43 3500, 32 of 67 joi	1901 and	5 sacks ce 2800, 20	ament Shot	feet to
Measured casing at 4000 and 24251. Pu well with 1 sa	T.D. Dumped 3800, 3720, 11ed a total ck hulls, 25	sandto 43 3500, 32 of 67 joi	1901 and	5 sacks ce 2800, 20	ament Shot	feet to
Measured casing at 4000 and 24251. Pu well with 1 sa	T.D. Dumped 1. 3800, 3720, 11ed a total ck hulls, 25 gel.	sandto 43 3500, 32 of 67 joi sacks gel	901 and 000 3000 nts of 5	5 sacks ce 2800, 20 1/2" cas: sacks 50	ament Shot	feet to
Measured casing at 4000 and 24251. Pu well with 1 sa with 6% added	T.D. Dumped 1. 3800, 3720, 11ed a total ck hulls, 25 gel.	sandto 43 3500, 32 of 67 joi sacks gel	1901 and 1903 and 1903 3000 nts of 5 and 120	5 sacks ce 2800, 20 1/2" cas: sacks 50	ament Shot	feet to
Measured casing at 4000 and 24251. Pu well with 1 sa with 6% added	T.D. Dumped 1. 3800, 3720, 11ed a total ck hulls, 25 gel.  (Wadditonal Rockhold	sandto 43 3500, 32 of 67 joi sacks gel	1901 and 1903 and 190	5 sacks ce 2800, 20 1/211 cas; sacks 50	ament Shot	feet to
Measured casing at 4000 and 24251. Pu well with 1 sa with 6% added	T.D. Dumped 3800, 3720, 11ed a total ck hulls, 25 gel.	sandto 43 3500, 32 of 67 joi sacks gel	1901 and 1903 and 190	5 sacks ce 2800, 20 1/2" cas: sacks 50	ament Shot	feet to
Measured casing at 4000 and 24251. Pu well with 1 sa with 6% added  ame of Plugging Contractor ddress P. 0	T.D. Dumped 1 3800, 3720, 11ed a total ck hulls, 25 gel.  (If additional Rockhold Box 698, Green.	sandto 43 3500, 32 of 67 joi sacks gel description is nece Engineeri	1901 and 1900 and 190	5 sacks ce 2800, 20 1/211 cas; sacks 50	h placed, from  Short  Short	d
Measured casing at 4000 and 24251. Pu well with 1 sa with 6% added  ame of Plugging Contractor ddress P. 0	T.D. Dumped 1. 3800, 3720, 11ed a total ck hulls, 25 gel.  (If additional Rockhold Box 698, Green James W. Rock	sandto 43 3500, 32 of 67 joi sacks gel description is nece Engineeri eat Bend,	901 and 000 3000 nts of 5 and 120 mg, Inc. Kansas  Barton	5 sacks ce 2800, 20 1/2" cas: sacks 50 (of this shoet) 67530	h placed, from  Shot 600, 2500 ing. Plugge 750 Pozmix	d
Measured casing at 4000 and 24251. Pu well with 1 sa with 6% added  TATE OF Kansas	T.D. Dumped 1. 3800, 3720, 11ed a total ck hulls, 25 gel.  (If additional Rockhold Box 698, Green Lames W. Rossys: That I have have	sandto 43 3500, 32 of 67 joi sacks gel  description is nece Engineeri eat Bend,	901 and 000 3000 nts of 5 and 120 mg, Inc. Kansas  Barton (employee of 6	5 sacks ce 2800, 20 1/2" cas: sacks 50 of this sheet) 67530	h placed, from  Shot 600, 2500 ing. Plugge 750 Pozmix	d d
Measured casing at 4000 and 24251. Pu well with 1 sa with 6% added  Came of Plugging Contractor ddress P. 0  TATE OF Kansas  CATHY NOTARY	T.D. Dumped 3800, 3720, 11ed a total ck hulls, 25 gel.  (If additional Rockhold Box 698, Gre  James W. Ro says: That I have but the same are true an	sandto 43 3500, 32 of 67 joi sacks gel  description is nece Engineeri eat Bend,	901 and 000 3000 nts of 5 and 120 mg, Inc. Kansas  Barton (employee of 6 facts, statements)	5 sacks ce 2800, 20 1/2" cas: sacks 50 of this sheet) 67530	ment. Shot 500 2500 ing. Plugge 750 Pozmix	the above-described and the log of the
Measured casing at 4000 and 24251. Pu well with 1 sa with 6% added  Came of Plugging Contractor Address P. 0  TATE OF Kansas  CATHY NOTARY	T.D. Dumped 3800, 3720, 11ed a total ck hulls, 25 gel.  (If additional Rockhold Box 698, Gre  James W. Ro says: That I have but the same are true an	sandto 43 3500, 32 of 67 joi sacks gel description is nece Engineeri eat Bend, NTY 01 ockhold (owledge of the	901 and 000 3000 nts of 5 and 120 mg, Inc. Kansas  Barton (employee of 6 facts, statements)	5 sacks ce 2800, 20 1/2" cas; sacks 50 cof this shoet) 67530	ment. Shot 600 2500 ing. Plugge 750 Pozmix	the above-described and the log of the
Measured casing at 4000 and 24251. Pu well with 1 sa with 6% added  Came of Plugging Contractor Diddress P. O  TATE OF Kansas  CATHY NOTARY Barton Co	T.D. Dumped 1. 3800, 3720, 11ed a total ck hulls, 25 gel.  (If additional Rockhold Box 698, Green Box 698, Gree	sandto 43 3500, 32 of 67 joi sacks gel  description is nec Engineeri eat Bend,  NTY 01 ockhold owledge of the d correct. So (Signature)	901 and 100, 3000 nts of 5 and 120 mg. Inc. Kansas  Barton (employee of 6 facts, statements) belo me Cod.	5 sacks ce 2800, 20 1/2" cas; sacks 50  cof this shoet) 67530	h placed, from  Ament. Shot  600, 2500  ing. Plugge  /50 Pozmix  Active  67530  Addres)	the above-described and the log of the mes W. Rockhol
Measured casing at 4000 and 24251. Pu well with 1 sa with 6% added  Came of Plugging Contractor Address P. 0  TATE OF Kansas  CATHY NOTARY	T.D. Dumped 1. 3800, 3720, 11ed a total ck hulls, 25 gel.  (If additional Rockhold Box 698, Green Box 698, Gree	sandto 43 3500, 32 of 67 joi sacks gel  description is nec Engineeri eat Bend,  NTY 01 ockhold owledge of the d correct. So (Signature)	901 and 100, 3000 nts of 5 and 120 mg. Inc. Kansas  Barton (employee of 6 facts, statements) belo me Cod.	5 sacks ce 2800, 20 1/2" cas; sacks 50  cof this shoet) 67530	ment. Shot 600, 2500 ing. Plugge 750 Pozmix  EXEMPTED CONTROL OF 67530 Ja  Addres) 1975	the above-described and the log of the mes W. Rockhol
Measured casing at 4000 and 24251. Pu well with 1 sa with 6% added  Came of Plugging Contractor Diddress P. O  TATE OF Kansas  CATHY NOTARY Barton Co	T.D. Dumped 1. 3800, 3720, 11ed a total ck hulls, 25 gel.  (If additional Rockhold Box 698, Green Box 698, Gree	sandto 43 3500, 32 of 67 joi sacks gel  description is nec Engineeri eat Bend,  NTY 01 ockhold owledge of the d correct. So (Signature)	901 and 100, 3000 nts of 5 and 120 mg. Inc. Kansas  Barton (employee of 6 facts, statements) belo me Cod.	5 sacks ce 2800, 20 1/2" cas; sacks 50  cof this shoet) 67530	h placed, from  Ament. Shot  600, 2500  ing. Plugge  /50 Pozmix  Active  67530  Addres)	the above-described and the log of the mes W. Rockhol
Measured  Casing at 4000 and 24251. Pu  Well with 1 sa  With 6% added  Came of Plugging Contractor  Address P. O  TATE OF Kansas  CATHY  NOTARY  Barton Co	T.D. Dumped 1. 3800, 3720, 11ed a total ck hulls, 25 gel.  (If additional Rockhold Box 698, Green Box 698, Gree	sandto 43 3500, 32 of 67 joi sacks gel  description is nec Engineeri eat Bend,  NTY 01 ockhold owledge of the d correct. So (Signature) Box	901 and 900 and 900 and 100 3000 nts of 5 and 120 mg. Inc. Kansas  Barton (comployee of 6 facts, statements) belo me Cod.	5 sacks ce 2800, 20 1/2" cas; sacks 50  cof this shoet) 67530	ment. Shot 600, 2500 ing. Plugge 750 Pozmix  Francisco of berein contained 67530  1975	the above-described and the log of the mes W. Rockhol

RECEIVED
STATE CORPORATION COMMISSION

APR 41975 04-04-1975

CONSERVATION DIVISION

## 15-135-20501-00-00 13-19:00

## WELL LOG

Murfin Drilling & Patrick Petroleum COMPANY SEC. 13 T. 198 A. 25W C SE SE FARM Gantz-Holloway HIG. NO. Ness TOTAL DEPTH 43951 COUNTY COMM. 10-16-71 KANSAS 10-27-71 COMP. CONTRACTOR Murfin Drilling Company s 5/8" @ 452' w/275 sxs 15 2332 GL ELEVATION 12 s 1/2" @ 4394' w/100 sxs 13 2337 KB PRODUCTION FIGURES INDICATE SOTTOM OF FORMATIONS 16 B0,00 380 Clay - Shale 860 Shale 1610 Red Shale & Shells 1650 Anhydrite 2325 Shale 3600 Lime & Shale 3800 Lime & Sand 3920 Lime & Shale 4358 Lime 4371 Lime & Chert 4395 Lime RECEIVED STATE COMPORATION COMMISSION LOG TOPS DEPTH SC 1612 CONSERVATION DIVISION B SC 1650 Wichila, Krauss WAB 3237 03-03-1975 HEEB 3712 TOR 3729 LANS 3752 BKC 4037 MARM 4108 PAW 4194 FT S 4270 B CHER LS 4340 4345 CH CONG MISS 4362 RTD 4395 LTD 43995 KANSAS SEDGWICK County of \_\_\_\_ James R. Daniels \_of the Murfin Drilling OR CHES upon cath state that the above and foregoing is a true and correct copy of the log of the Gantz-Holloway #1 CARAPY OF

\*\*\*\* Gomaisipa Bapires: February 7, 1975

Subscribed and sworn to before me this 8th

Brokes

<u>Octóber</u>