

Rev. 6-4-68

CONSERVATION DIVISION ORGENT SIREPOSTATE CORPORATION COMMISSION

APR 141975

133 819/5

P. O. Box 17027

J. Lewis Brock

Wichita, Kansas 67217

CONSERVATION DIVISION Wichita, Kansas

CONSERVATION DIVISION Wichita, Kansas

ease Name	Shauers "E"	We	11 12. Ti	
			11 No. 1	~ · · · · · · · · · · · · · · · · · · ·
ocation	C NE	Sec. 20	Twp. 19 Rge.	(E)(
ounty	Ness		Total Depth 16	681
bandoned Oil Well	Gas Well_	Input Well	SWD Well	D & A
ther well as here	after indicated			
lugging Contractor	•	Co. Tools		
ddress			License No.	
ID 1668 8 5/8	csg set at 290° cwc]			
unned pits, circu	lated heavy mud, set	50 sk cmt plug a	t 550° thru dri	ll pipe
eavy mud to 240°	set 25 sk cmt plug th	oru drill pipe. H	eavy mud to 40.	set solid
ridge & 10 sk cmt	plug to base of cell	ar.		
	· ·			
	×.			
		*		
	bandoned Oil Well ther well as here lugging Contractor ddress peration Complete ne above well was ID 1668 8 5/8 unned pits, circul	bandoned Oil Well Gas Well ther well as hereafter indicated lugging Contractor ddress peration Completed: Hour 1:15 A ne above well was plugged as follows: TD 1668 8 5/8 csg set at 290° cwc unned pits, circulated heavy mud, set	bandoned Oil Well Gas Well Input Well ther well as hereafter indicated lugging Contractor Co. Tools ddress peration Completed: Hour 1:15 A Day 77 h ne above well was plugged as follows: CD 1668 8 5/8 csg set at 290° cwc 160 sk. Plg. Mat	bandoned Oil Well Gas Well Input Well SWD Well ther well as hereafter indicated lugging Contractor Co. Tools ddress License No. peration Completed: Hour 1:15 A Day 7/ Month 4 ne above well was plugged as follows: ID 1668° 8 5/8 csg set at 290° cwc 160 sk. Plg. Mat. 50-50 poz cemuned pits, circulated heavy mud, set 50 sk cmt plug at 550° thru dries avy mud to 240° set 25 sk cmt plug thru drill pipe. Heavy mud to 40°

Well Plugging Supervisor