REMARKS: USED 60/40 POZMIX 6% GEL BY ALLIED. NO CASING RECOVERED.

OAT (DID) OBSERVE THE S-PLUGGING.

SIGNED (TECHNICIAN) FO

FORM CP-2/3

(2)

ACTUAL PLUGGING REPORT FOR OTIS #5 GREELEY COUNTY

Peak Wireline set CIBP @ 5100' with 2 sx cement on top. Key Rocky Mountain ran tubing in hole with 4½ packer set at 2000'. Pressured up to 300# and held. Pulled tubing out of hole. Peak Wireline set CIBP @ 1950'. Perforated at 1600'. Ran tubing in hole open ended to 1915'. Allied pumped 100 sx cement. Circulated to surface. Pulled tubing to 600'. Allied pumped 15 sx cement. Pulled tubing out of hole. Pumped down 4½ squeezed 85 sx cement. Maximum psi @ 1000#. Shut in @ 200#. Pumped down 85% x 5½ annulus 100 sx cement. Maximum psi @ 200#. Shut in @ 100#.

RÉCEIVED

JUL 2 8 1999

CONSERVATION DIVISION Wichita, Kansas