

## 15:051-21466-0000

## State Corporation Commission

## CONSERVATION DIVISION

(Oil, Gas and Water)
245 North Water
WICHITA, KANSAS 67202

## VERBAL PERMIT FORM (To Be Filed By Plugging Agent)

J. Lewis Brock Administrator 245 North Water Wichita, Kansas 67202 SIATE COFFORT TO BIST WINESE VINESE V

Dear Sir:

| Mr.                                                                                           | Kaba        | of_                | John Farmer      | has               | this      |
|-----------------------------------------------------------------------------------------------|-------------|--------------------|------------------|-------------------|-----------|
|                                                                                               |             | permission to pl   |                  |                   |           |
| Mr.                                                                                           | Kaba        | gu                 | arantees payment | of the plugging   | fee.      |
| Mr. Kaba guarantees payment of the plugging fee.  Operator's full Name: Crude Producers, Inc. |             |                    |                  |                   |           |
| Complete Address: Box 55, Russell, Kansas                                                     |             |                    |                  |                   |           |
| Lease Name: Armbrister **B** Well No. 1                                                       |             |                    |                  |                   |           |
| Loca                                                                                          | ation:      | SE NE SW           | Sec. 6. Tw       | p. 11 Rge. (1     | E)(W) 19  |
| County: Total Depth 3745* Oil Well                                                            |             |                    |                  |                   | ∍11       |
| Gas                                                                                           | WellI       | nput WellSWD       | WellD & A        | XX Lost Hole_     |           |
| Mr.                                                                                           | Kaba        | was                | instructed to pl | ug the well as fo | ollows:   |
| Gun pits, circulate heavy mud, set 70 sk cmt plug at 600° thru drill                          |             |                    |                  |                   |           |
| pipe                                                                                          | . Heavy muc | i to 215° set 20 s | sk cmt plug thru | drill pipe. Heav  | <b>'y</b> |
| mud                                                                                           | to 40° set  | solid bridge & 10  | ) sk cmt plug to | base of cellar.   |           |
|                                                                                               |             |                    |                  |                   |           |
|                                                                                               |             |                    |                  |                   |           |

Very truly yours,

Conservation Division Agent