KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

Form CDP-4 April 2004 Form must be Typed

CLOSURE OF SURFACE PIT

07

Operator Name: Shawmar Oil & Gas Co., Inc.	License Number: 5192
Operator Address: PO Box 9, Marion, KS 66861	
Contact Person: Beau J. Cloutier	Phone Number: (620) 382 - 2932
Permit Number (API No. if applicable): 15-115-21368-000	Lease Name & Well No.: V. KOEHN #1-14
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	_ NE/4 _ NE/4 _ NE/4
Settling Pit	Sec. 14 Twp. 22 R. 4 1/2
Workover Pit Haul-Off Pit	330 Feet from North / South Line of Section
	330 Feet from ✓ East / West Line of Section
	County
Date of closure: May 2007	
Was an artificial liner used? ☐ Yes ✓ No	
If no, how were the sides and bottom sealed to prevent downward migration of the pit contents?	
Clay sides and bottom prevent downward migration	DECENTES.
Clay sides and bottom prevent downward migration	RECEIVED KANSAS CORPORATION COMMISSION
Clay sides and bottom prevent downward migration	RECEIVED KANSAS CORPORATION COMMISSION SEP 1 9 2007
Abandonment procedure of pit:	SEP 1 9 2007
	KANSAS CORPORATION COMMISSION
Abandonment procedure of pit:	SEP 1 9 2007 CONSERVATION DIVISION
Abandonment procedure of pit:	SEP 1 9 2007 CONSERVATION DIVISION
Abandonment procedure of pit:	Shawmar Oil & Gas Co. Inc.
Abandonment procedure of pit: Evaporate dry and cover	KANSAS CORPORATION COMMISSION SEP 1 9 2007 CONSERVATION DIVISION WICHITA, KS
Abandonment procedure of pit: Evaporate dry and cover The undersigned hereby certifies that he / she is President	KANSAS CORPORATION COMMISSION SEP 1 9 2007 CONSERVATION DIVISION WICHITA, KS
Abandonment procedure of pit: Evaporate dry and cover The undersigned hereby certifies that he / she is President	KANSAS CORPORATION COMMISSION SEP 1 9 2007 CONSERVATION DIVISION WICHITA, KS
Abandonment procedure of pit: Evaporate dry and cover The undersigned hereby certifies that he / she is President	SEP 1 9 2007 CONSERVATION DIVISION WICHITA, KS for Shawmar Oil & Gas Co. Inc. (Co.), e best of his /her knowledge and belief. Signature of Applicant or Agent
Abandonment procedure of pit: Evaporate dry and cover The undersigned hereby certifies that he / she is	SEP 1 9 2007 CONSERVATION DIVISION WICHITA, KS for Shawmar Oil & Gas Co. Inc. (Co.), e best of his /her knowledge and belief. Signature of Applicant or Agent
Abandonment procedure of pit: Evaporate dry and cover The undersigned hereby certifies that he / she is	SEP 1 9 2007 CONSERVATION DIVISION WICHITA, KS for Shawmar Oil & Gas Co. Inc. (Co.), e best of his /her knowledge and belief. Signature of Applicant or Agent
Abandonment procedure of pit: Evaporate dry and cover The undersigned hereby certifies that he / she is	SEP 1 9 2007 CONSERVATION DIVISION WICHITA, KS for Shawmar Oil & Gas Co. Inc. (Co.), e best of his /her knowledge and belief. Signature of Applicant or Agent