## KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

Form CDP-5 August 2004 Form must be Typed

## EXPLORATION & PRODUCTION WASTETRANSFER

Operator Name: John O. Farmer, Inc.	License Number: 5135
Operator Address: P.O. Box 352, Russell, KS 67665	
Contact Person: Marge Schulte	Phone Number: (785) 483 - 3145, Ext. 214
Permit Number (API No. if applicable): 15-167-23,411	Lease Name: Mudd
Source of Waste:	Well Number: #2
□ Dike □ Emergency Pit □ Settling Pit □ Workover Pit □ Drilling Pit □ Burn Pit □ Haul-off Pit □ Steel Pit □ Spill / Escape	Source Location (QQQQ): SE - SE - NW - NW  Sec. 27 Twp. 12S R. 15 East  West  1280 Feet from North / South Line of Section  1170 Feet from East / West Line of Section  Russell County
Type of waste to be disposed:	Other:
Amount of waste: 1 No. of loads 320 Barrels Tons YDS	
Destination of waste: ☐ Reserve Pit ✓ Disposal Well ☐ Lease Ro.	ad Dike / Berm Other:
If waste is transferred to another reserve pit, is the lease active? Yes No	
Location of waste disposal:	Date of Waste Transfer: 6-20-07 License No.: 31250
Operator Name: KSC Oil	Sec. 35 Twp.13S R. 15 East West
Lease Name: Johnson #2 SWD	
Docket No.: D-20,393	County: Russell
	RECEIVED KANSAS CORPORATION COMMISSION  SEP 1 0 2007  CONSERVATION DIVISION WICHITAL KS
The undersigned herby certifies that he / she is president for John O. Farmer, Inc.  and correct to the best of his / her knowledge and belief.  Subscribed and sworn to before me on this 7th day of Septem MIANY POINT - State of Kansas  My Commission Expires:	ithorized agent, that all information shown hereon is true  1. Figure 11  Agent Signature  Der 2007  Mary Public