

Kansas Corporation Commission
Oil & Gas Conservation Division

1099332

Form COP-1 May 2010 Form must be Typed

APPLICATION FOR SURFACE PIT

Submit in Duplicate

Operator Name: Anadarko Petroleum Corporation			License Number: 4549
Operator Address: PO Box 1330			HOUSTON TX 77251
Contact Person: Brenda Womack			Phone Number: 832-636-1677
Lease Name & Well No.: Kramer 1 #1		1	Pit Location (QQQQ):
Type of Pit: Emergency Pit Burn Pit Settling Pit Drilling Pit Workover Pit Haul-Off Pit (If WP Supply API No. or Year Drilled) 15-189-22693-00-00 Is the pit located in a Sensitive Ground Water A Is the bottom below ground level? Yes No Pit dimensions (all but working pits):	Artificial Liner? How is the pit lined if a plastic liner is not used? Yes X No Earthen Lined		
Distance to nearest water well within one-mile of pit: 2693		Depth to shallowest fresh water 235 feet. Source of information: measured well owner electric log X KDWR Drilling, Workover and Haul-Off Pits ONLY: Type of material utilized in drilling/workover: Fresh water Mud Number of working pits to be utilized: 1 Abandonment procedure: Evaporation & backfill Drill pits must be closed within 365 days of spud date.	
CC OFFICE USE ONLY Liner Steel Pit ☑ RFAC ☐ RFAS Date Received: 10/31/2012 Permit Number: Permit Date: 11/08/2012 Lease Inspection: ☒ Yes ☐ No			

Conservation Division Finney State Office Building 130 S. Market, Rm. 2078 Wichita, KS 67202-3802



Phone: 316-337-6200 Fax: 316-337-6211 http://kcc.ks.gov/

Sam Brownback, Governor

Mark Sievers, Chairman Thomas E. Wright, Commissioner Shari Feist Albrecht, Commissioner

November 08, 2012

Brenda Womack Anadarko Petroleum Corporation PO Box 1330 HOUSTON, TX 77251-1300

Re: Drilling Pit Application Kramer 1 #1 Sec.01-34S-38W Stevens County, Kansas

Dear Brenda Womack:

District staff has inspected the above referenced location and has determined that the Workover pit shall be constructed <u>without slots</u>, the bottom shall be flat and reasonably level, and the free fluids must be removed. The fluids are to be removed from the Workover pit within 48 hours of completion of drilling operations.

NO completion fluids or non-exempt wastes shall be placed in the Workover pit.

The fluids should be taken to an authorized disposal well. Please call the District Office at (620) 225-8888 when the fluids have been removed. Please file form CDP-5 (August 2008), Exploration and Production Waste Transfer, through KOLAR within 30 days of fluid removal.

If you have any questions or concerns please feel free to contact the District Office at (620) 225-8888.