

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
211 NORTH BROADWAY
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM
File One Copy

Lease Owner S.A. BERWICK DRILLING ^{CO.} Address 1105 Williams, Great Bend, Kansas
(Applicant)
Lease (Farm Name) Darnes Well No. C #1

Well Location SW/SW/SW Sec. 19 Twp. 31S Rge. 8W (E) (W)

County Harper County, Kansas Field Name (if any) _____

Total Depth 1380' Oil Gas Dry Hole X

Was well log filed with application? _____ If not, explain: _____

Well Log is enclosed

Date and hour plugging is desired to begin November 30, 1956 8:00 A.M.

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission.

Name of the person on the lease in charge of well for owner _____

J.O. Forbes Address Great Bend, Kansas

Plugging Contractor J.O. Forbes d/b/a Forbes Casing Pulling Co.

Plugging Contractor's License No. No. 49

Address P.O. Box 221, Great Bend, Kansas

Invoice covering assessment for plugging this well should be sent to _____

Our Company check No. 4674 Address _____
dated November 26, 1956.

and payment will be guaranteed by applicant.

RECEIVED
STATE CORPORATION COMMISSION
11-27-56

J.O. Forbes
Applicant or Acting Agent

Date November 26, 1956

PLUGGING
FILE SEC. 19 T. 31 R. 8W
BOOK PAGE 112 LINE 35

CONSERVATION DIVISION
Wichita, Kansas



STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
211 NORTH BROADWAY
WICHITA, KANSAS

November 27, 1956

Well No. C #1
Lease Larnes
Description SW SW SW 19-31-8W
County Harper
File No. 119-35

S. A. Borwick Drilling Company
1105 Williams
Great Bend, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. H. A. Rives, Box 8, Pratt, Kansas.

STATE CORPORATION COMMISSION
CONSERVATION DIVISION

BY S. S. Greider
S. S. Greider
WELL PLUGGING SUPERVISOR

cc:
District Plugging Supervisor