KCC OIL/GAS REGULATORY OFFICES

Date: <u>02/05/13</u>	District: <u>01</u>
	New Situation Lease Inspection
	Response to Request Complaint
	Follow-Up Field Report
Operator License No: 4058	API Well Number: 15-135-25,505-00-00
Op Name: American Warrior	Spot: SE-SW-SE-SE Sec 31 Twp 18 S Rng 21 E / W
Address 1: P.O. Box 399	∩ (38) Feet from N/✓ S Line of Section
Address 2: P.O. Box 783188	940 (950) Feet from Feet from VE/W Line of Section
City: Garden City	GPS: Lat: 38.43664 Long: 99.68162 Date: 2/5/13
State: Kansas Zip Code: <u>67846 -0399</u>	Lease Name: V Strecker Well #: 3-31
Operator Phone #: <u>(620) 587-3224</u>	County: Ness
Reason for Investigation:	
Witness Alt.II	
Problem:	
None, cement circulated to surface	
Persons Contacted:	· · · · · · · · · · · · · · · · · · ·
Findings:	
Findings: 8-5/8" @ 227'W/150sxs cement	
8-5/8" @ 227'W/150sxs cement TD @ 4268'	· · · · · · · · · · · · · · · · · · ·
8-5/8" @ 227'W/150sxs cement TD @ 4268' 5-1/2" @ 4266'W/175sxs cement	
8-5/8" @ 227'W/150sxs cement TD @ 4268'	nd-1/4# flo seal-2%cc-15sxs went to pit
8-5/8" @ 227'W/150sxs cement TD @ 4268' 5-1/2" @ 4266'W/175sxs cement	nd-1/4# flo seal-2%cc-15sxs went to pit
8-5/8" @ 227'W/150sxs cement TD @ 4268' 5-1/2" @ 4266'W/175sxs cement	nd-1/4# flo seal-2%cc-15sxs went to pit RECEIVED FEB 1 1 20to
8-5/8" @ 227'W/150sxs cement TD @ 4268' 5-1/2" @ 4266'W/175sxs cement	RECEIVED FEB 1 1 2013
8-5/8" @ 227'W/150sxs cement TD @ 4268' 5-1/2" @ 4266'W/175sxs cement	nd-1/4# flo seal-2%cc-15sxs went to pit RECEIVED FEB 1 1 2013 KCC WICHITA
8-5/8" @ 227'W/150sxs cement TD @ 4268' 5-1/2" @ 4266'W/175sxs cement Port Collar @ 1357' cemented with 135sxs-sr	RECEIVED FEB 1 1 2013
8-5/8" @ 227'W/150sxs cement TD @ 4268' 5-1/2" @ 4266'W/175sxs cement Port Collar @ 1357' cemented with 135sxs-sr	RECEIVED FEB 1 1 2013 KCC WICHITA
8-5/8" @ 227'W/150sxs cement TD @ 4268' 5-1/2" @ 4266'W/175sxs cement Port Collar @ 1357' cemented with 135sxs-sr	RECEIVED FEB 1 1 2013 KCC WICHITA
8-5/8" @ 227'W/150sxs cement TD @ 4268' 5-1/2" @ 4266'W/175sxs cement Port Collar @ 1357' cemented with 135sxs-sr	RECEIVED FEB 1 1 2013 KCC WICHITA
8-5/8" @ 227'W/150sxs cement TD @ 4268' 5-1/2" @ 4266'W/175sxs cement Port Collar @ 1357' cemented with 135sxs-sr	RECEIVED FEB 1 1 2013 KCC WICHITA
8-5/8" @ 227'W/150sxs cement TD @ 4268' 5-1/2" @ 4266'W/175sxs cement Port Collar @ 1357' cemented with 135sxs-sr	RECEIVED FEB 1 1 2013 KCC WICHITA
8-5/8" @ 227'W/150sxs cement TD @ 4268' 5-1/2" @ 4266'W/175sxs cement Port Collar @ 1357' cemented with 135sxs-sr	RECEIVED FEB 1 1 2013 KCC WICHITA
8-5/8" @ 227'W/150sxs cement TD @ 4268' 5-1/2" @ 4266'W/175sxs cement Port Collar @ 1357' cemented with 135sxs-sr Action/Recommendations: Follow Alt.il requirements have been met Verification Sources:	RECEIVED FEB 1 1 2013 KCC WICHITA Up Required Yes No Date: Photos Taken:
8-5/8" @ 227'W/150sxs cement TD @ 4268' 5-1/2" @ 4266'W/175sxs cement Port Collar @ 1357' cemented with 135sxs-sr Action/Recommendations: Follow Alt.il requirements have been met Verification Sources: RBDMS	RECEIVED FEB 1 1 2013 KCC WICHITA Up Required Yes No Date:
8-5/8" @ 227'W/150sxs cement TD @ 4268' 5-1/2" @ 4266'W/175sxs cement Port Collar @ 1357' cemented with 135sxs-sr Action/Recommendations: Follow Alt.II requirements have been met Verification Sources: RBDMS T-I Database KGS T-I Database	RECEIVED FEB 1 1 2013 KCC WICHITA Up Required Yes No Date: Photos Taken:
8-5/8" @ 227'W/150sxs cement TD @ 4268' 5-1/2" @ 4266'W/175sxs cement Port Collar @ 1357' cemented with 135sxs-sr Action/Recommendations: Follow Alt.II requirements have been met Verification Sources: RBDMS T-I Database Other: Retain I Copy District Office RECEIVED	RECEIVED FEB 1 1 2013 KCC WICHITA Up Required Yes No Date: Photos Taken:
8-5/8" @ 227'W/150sxs cement TD @ 4268' 5-1/2" @ 4266'W/175sxs cement Port Collar @ 1357' cemented with 135sxs-sr Action/Recommendations: Follow Alt.II requirements have been met Verification Sources: RBDMS T-I Database KGS T-I Database	RECEIVED FEB 1 1 2013 KCC WICHITA Up Required Yes No Date: Photos Taken:

KCC DODGE CITY

AW

Date: 02/05/13	02/05/13 Distric			: <u>01</u> License #: <u>4058</u>				
Op Name: 4058			Spot: <u>SE-SW-SE-SE</u> Sec <u>31</u> Twp <u>18</u> S Rng <u>21</u> E W					
County: Ness	Lease N				ame: V Strecker Well #: 3-31			
I.D. Sign Yes No		3	Gas V	enting [Yes No			
Tank Battery Condition Condition: Good Questionable Overflowing				Pits Fluid Depth:ft; Approx. Size:ft. xft.				
Pits, Injection Site Fluid Depth:ft; Approx. Size:ft. xft.				Saltwater Pipelines Leaks Visible: Y N Tested for Leaks: Y N				
Oil Spill Evidence				Flowing Holes				
Abandoned Well Potential Poll	ution Problem	Yes No o	Т	A Wells				
			М	onitoring	Records			
Lease Cleanliness Very Good Satisfactory	Poor Ver	y Bad						
SWD/ER Injection Well Yes	No	Ness 🖸	Gaug	e Connect	ions Yes No			
Permit #: psi; Authorized: psi				Tubing:; T/C Annulus:; C/SP Annulus:				
Permit #: Pressure - Actu					; T/C Annulus:; C/SP Annulus:			
Permit #: Pressure - Actu		thorized: psi			; T/C Annulus:; C/SP Annulus:			
Permit #:Pressure - Actu	al: psi; Au	thorized: psi	Tubit	ng:	; T/C Annulus:; C/SP Annulus:			
API Footages	Spot Location	GPS		Well#	Well Status			
38FSL 15-135-25,505-00-00 950FEL		38.43664-99.68162		3-31	New well, Alt.II completed			