Wichita St	ORATION COMMISSION	rt/O NUL NIE		26	r 10	s. a 30	X
	tate Office Bidg. PLUGGING SECTION rket, Room 2078	·W/Z NW NE				section	
Wichit	a, KS 67202	-	•				•
	N'S PLUGGING REPORT			_		section 4.	line
	License 2 5285	_ Lease No					
	The Dane G. Hansen Trust					151,45	
ameš .ddress	P.O. Box 187	Yell Tot	tal Depth		4660) 	_teet
	Logan, KS 67646	Conducto	or Pipe:	Size		_fset	
	•	_ , Surface	Casing:	Size_8	3 5/8 _f .	eet <u>348</u>	
bandonad	Oli Well Gas Well	Input Wei	1	מ מאצ	(el I	A&0	Х
	1 as hereinafter indicated						
	Contractor Blue Goose Drilling			Lican	se Numbe	5104	
legging	P.O. Box 1413, Great Bend, KS 675	30-1413				••	
	to plug at: Hour: Day:		+	8		95	
			98181				<u> </u>
	proposal received from Martin						
	name) Blue Goose Drilling Co.,						
	o fill hole with heavy mud and sp					ite 2216'	•
lst plug	at 2216 with 50 sx cement, 2nd	l plug at 1150'	with 80	sx ce	ment,		
3rd plug	at 650' with 50 sx cement, 4th	plug at 370' v	vith 50 s	x ceme	nt,		
						·	
	at 40' with 10 sx cement, 6th p					cement,	
5th plug	at 40' with 10 sx cement, 6th p	olug to circul				cement,	
5th plug	to circulate mousehole with 10 s	olug to circula	ate ratho	le with	h 15 sx (
5th plug	to circulate mousehole with 10 s	olug to circul	ate ratho	le with	h 15 sx o		
5th plug	to circulate mousehole with 10 s	olug to circula	ved by	le wit	enn Barl	ow	
5th plug 7th plug Pruggin	to circulate mousehole with 10 s Plugging P G Operations attended by Agent?:	elug to circula ex cement. Proposal Recei	ved byPart	le wit	enn Barl	ow HCIAN)	
5th plug 7th plug Piuggin Operati	to circulate mousehole with 10 s Plugging P Governations attended by Agent?: ons Completed: Hour: 10 p.m. Da	elug to circula ex cement. Proposal Recai	ved by Part	le wit	enn Barl	ow HCIAN)	
7th plug 7th plug Piuggin Operati	to circulate mousehole with 10 s Plugging P g Operations attended by Agent?: ons Completed: Hour: 10 p.m. Da PLUGGING REPORT 1st plug at 2216	sx cement. roposal Recai All y: 4 6' with 50 sx o	ved by Part Heath:	Gl 8	enn Barl	ow HCIAN)	
7th plug 7th plug Pruggin Operati ACTUAL 2nd plug	to circulate mousehole with 10 s Plugging P Governations attended by Agent?: ons Completed: Hour: 10 p.m. Da	sx cement. roposal Recai All y: 4 6' with 50 sx o	ved by Part Heath:	Gl 8	enn Barl	ow HCIAN)	Gr.
7th plug Pruggin Operati ACTUAL 2nd plug 4th plug	Plugging P G Operations attended by Agent?: ons Completed: Hour: 10 p.m. Da Plugging REPORT 1st plug at 2216 g at 1150' with 80 sx cement, 3rd	sx cement. roposal Recai All y: 4 6' with 50 sx o	ved by Part Heath:	Gl 8	enn Barl	ow HCIAN)	Ot:
7th plug 7th plug Pruggin Operati ACTUAL 2nd plug 4th plug	Plugging P G Operations attended by Agent?: ons Completed: Hour: 10 p.m. Da Plugging REPORT 1st plug at 2216 g at 1150' with 80 sx cement, 3rd g at 370' with 50 sx cement, g at 40' with 10 sx cement,	elug to circula ex cement. Proposal Recei All 4 6' with 50 sx of plug at 650'	ved by Part Heath:	Gl 8	enn Barl	ow HCIAN)	
7th plug 7th plug Piuggin Operati ACTUAL 2nd plug 4th plug 5th plug	Plugging P g Operations attended by Agent?: ons Completed: Hour: 10 p.m. Da Plugging REPORT 1st plug at 2216 g at 1150' with 80 sx cement, 3rd g at 370' with 50 sx cement, g at 40' with 10 sx cement, g at circulate rathole with 15 sx	cement,	ved by Part Heath:	Gl 8	enn Barl	ow HCIAN)	
7th plug 7th plug Pruggin Operati ACTUAL 2nd plug 4th plug 5th plug 6th plug	Plugging P g Operations attended by Agent?: ons Completed: Hour: 10 p.m. Da Plugging REPORT 1st plug at 2216 g at 1150' with 80 sx cement, 3rd g at 370' with 50 sx cement, g at 40' with 10 sx cement, g to circulate rathole with 15 sx g to circulate mousehole with 10 sx	cement,	ved by Part Heath:	Gl 8	enn Barl	ow HCIAN)	
7th plug 7th plug Pruggin Operati ACTUAL 2nd plug 4th plug 5th plug 6th plug	Plugging P g Operations attended by Agent?: ons Completed: Hour: 10 p.m. Da Plugging REPORT 1st plug at 2216 g at 1150' with 80 sx cement, 3rd g at 370' with 50 sx cement, g at 40' with 10 sx cement, g at circulate rathole with 15 sx	cement, cement, cement, cement, cement, cement, cement, cement,	ved by Part Heath: cement,	G1 8 sx cem	enn Barl (TECHN	ow (ICIAN) ona X fear: 1995 1095 //- 95	
7th plug 7th plug Pruggin Operati ACTUAL 2nd plug 4th plug 5th plug 6th plug	Plugging P g Operations attended by Agent?: ons Completed: Hour: 10 p.m. Da Plugging REPORT 1st plug at 2216 g at 1150' with 80 sx cement, 3rd g at 370' with 50 sx cement, g at 40' with 10 sx cement, g to circulate rathole with 15 sx g to circulate mousehole with 10 sx	cement, cement,	ved by Part Heath: cement,	G1 8 sx cem	enn Barl (TECHN	ow (ICIAN) ona X fear: 1995 1095 //- 95	30:
7th plug 7th plug Pruggin Operati ACTUAL 2nd plug 4th plug 5th plug 6th plug	Plugging P g Operations attended by Agent?: ons Completed: Hour: 10 p.m. Da Plugging REPORT 1st plug at 2216 g at 1150' with 80 sx cement, 3rd g at 370' with 50 sx cement, g at 40' with 10 sx cement, g to circulate rathole with 15 sx g to circulate mousehole with 10 s s: Used 60/40 Pozmix 6% gel by A	cement, cement,	Part Wanth: cement, with 50	G1 8 sx cem	enn Barl (TECHN	ow (ICIAN) ona X fear: 1995 1095 //- 95	

8-4