STATE COR		API NUMBER 15- 101-21,297-6000	
CONSERVAT	PORATION COMMISSION TION DIVISION - PLUGGING SECTION		
200 COLORADO DERBY BUILDING WICHITA, KANSAS 67202 TECHNICIAN'S PLUGGING REPORT		990 feet from S section 3630 feet from E section	
Operator:	Midco Exploration, Inc.	County Lane 15a	
NSWGQ	200 E. 1st Street, Suite 411		
	Wichita, KS 67202		
	•	Surface Casing: Size 8 5/8 feet 330	
Abandoned		Input Well SWD Well D&A >	
		010 HOT 1 OUN_2	
		ling Co., Inc. License Number 5104	
	P. O. Box 1413, Great Bend, KS		
-			
		15 Month: March Year: 19 86	
Piugging	proposal received from	Martin Miller	
(company	name) Blue Goose	(phone)316-792-56	
were: to	o fill hole with beavy mud and sp	Elevation 2814 of cement through drill pipe Anhydrite 2143-	
	at the base of the Anhydrite wit		
2nd plug	at 1/2 the Anhydrite plus 300° w	ith 80 sx cement	
3rd plug	30' below the base of the surfac solid bridge	e pipe with 40 sx cement	
3rd plug 4th plug	30' below the base of the surfactsolid bridge hulls - plug at 40' cement to	e pipe with 40 sx cement surface with 10 sx cement	
3rd plug 4th plug	30' below the base of the surfac solid bridge	e pipe with 40 sx cement  surface with 10 sx cement  cement  posal Received by Jack L. Luthi	
3rd plug 4th plug 6th plug	30' below the base of the surfact solid bridge hulls - plug at 40' cement to to circulate rat hole with 15 sx Plugging Pro	e pipe with 40 sx cement  surface with 10 sx cement cement pose! Received by Jack L. Luthi (TECHNICIAN)	
3rd plug 4th plug 6th plug Plugging	30' below the base of the surfact solid bridge hulls - plug at 40' cement to to circulate rat hole with 15 sx Plugging Pro	e pipe with 40 sx cement  surface with 10 sx cement cement posal Received by Jack L. Luthi (TECHNICIAN)  Ali Part None X	
3rd plug 4th plug 6th plug Plugging Operation	30' below the base of the surfact solid bridge hulls - plug at 40' cement to to circulate rat hole with 15 sx Plugging Pro  Operations attended by Agent?:  s Completed: Hour: 2:50 pm Day:	e pipe with 40 sx cement  surface with 10 sx cement cement posal Received by Jack L. Luthi (TECHNICIAN)  All Part None X  15 Month: March Year: 19 86	
3rd plug 4th plug 6th plug Plugging Operation	30' below the base of the surfact solid bridge hulls - plug at 40' cement to to circulate rat hole with 15 sx Plugging Pro  Operations attended by Agent?:  s Completed: Hour: 2:50 pm Day:	e pipe with 40 sx cement  surface with 10 sx cement cement posal Received by Jack L. Luthi (TECHNICIAN)  Ali Part None X	
3rd plug 4th plug 6th plug Plugging Operation ACTUAL PL	30' below the base of the surfact solid bridge hulls - plug at 40' cement to to circulate rat hole with 15 sx Plugging Pro  Operations attended by Agent?:  s Completed: Hour: 2:50 pm Day: UGGING REPORT 1st plug at 2172'	e pipe with 40 sx cement  surface with 10 sx cement cement posal Received by Jack L. Luthi (TECHNICIAN)  All Part None X  15 Month: March Year: 19 86	
3rd plug 4th plug 6th plug 6th plug Plugging Operation ACTUAL PL sx cement	30' below the base of the surfact solid bridge hulls - plug at 40' cement to to circulate rat hole with 15 sx Plugging Pro  Operations attended by Agent?:  Is Completed: Hour: 2:50 pm Day:  UGGING REPORT 1st plug at 2172'  T, 3rd plug at 360' with 40 sx cement solid by Agent?	e pipe with 40 sx cement  surface with 10 sx cement cement posal Received by Jack L. Luthi (TECHNICIAN)  All Part None X  15 Month: March Year:19 86 with 50 sx cement, 2nd plug at 1386' with 80	
3rd plug 4th plug 6th plug 6th plug Plugging Operation ACTUAL PL sx cement	30' below the base of the surface solid bridge hulls - plug at 40' cement to to circulate rat hole with 15 sx Plugging Pro  Operations attended by Agent?:  USGING REPORT 1st plug at 2172'  1, 3rd plug at 360' with 40 sx cement to surface with 10	e pipe with 40 sx cement  surface with 10 sx cement cement posal Received by Jack L. Luthi  (TECHNICIAN)  All Part None X  15 Month: March Year:19 86 with 50 sx cement, 2nd plug at 1386' with 80  ment, 4th & 5th plugs - solid bridge - hulls	
3rd plug 4th plug 6th plug 6th plug Plugging Operation ACTUAL PL sx cement plug at 4	30' below the base of the surface solid bridge hulls - plug at 40' cement to to circulate rat hole with 15 sx Plugging Pro  Operations attended by Agent?:  USGING REPORT 1st plug at 2172'  1, 3rd plug at 360' with 40 sx cement to surface with 10	e pipe with 40 sx cement  surface with 10 sx cement cement posal Received by Jack L. Luthi  (TECHNICIAN)  All Part None X  15 Month: March Year:19 86 with 50 sx cement, 2nd plug at 1386' with 80  ment, 4th & 5th plugs - solid bridge - hulls	
3rd plug 4th plug 6th plug 6th plug Plugging Operation ACTUAL PL sx cement plug at 4	30' below the base of the surface solid bridge hulls - plug at 40' cement to to circulate rat hole with 15 sx Plugging Pro  Operations attended by Agent?:  USGING REPORT 1st plug at 2172'  1, 3rd plug at 360' with 40 sx cement to surface with 10	e pipe with 40 sx cement  surface with 10 sx cement  cement posal Received by Jack L. Luthi  (TECHNICIAN)  All Part None X  15 Month: March Year:19 86  with 50 sx cement, 2nd plug at 1386' with 80  ment, 4th & 5th plugs - solid bridge - hulls sx cement, 6th plug to circulate rat hole with	
3rd plug 4th plug 6th plug 6th plug Plugging Operation ACTUAL PL sx cement plug at 4	30' below the base of the surface solid bridge hulls - plug at 40' cement to to circulate rat hole with 15 sx Plugging Pro  Operations attended by Agent?:  USGING REPORT 1st plug at 2172'  1, 3rd plug at 360' with 40 sx cement to surface with 10	e pipe with 40 sx cement  surface with 10 sx cement  cement posal Received by Jack L. Luthi  (TECHNICIAN)  AllPartNoneX  15	
3rd plug 4th plug 6th plug Plugging Operation ACTUAL PL sx cement plug at 4	30' below the base of the surface solid bridge hulls - plug at 40' cement to to circulate rat hole with 15 sx Plugging Pro  Operations attended by Agent?:  Is Completed: Hour: 2:50 pm Day:  UGGING REPORT 1st plug at 2172'  1, 3rd plug at 360' with 40 sx cement to surface with 10 ment.  Used 60/40 Pozmix 6% gel by Allie	e pipe with 40 sx cement  surface with 10 sx cement  cement posal Received by Jack L. Luthi  (TECHNICIAN)  All Part None X  15 Month: March Year:19 86  with 50 sx cement, 2nd plug at 1386' with 80  ment, 4th & 5th plugs - solid bridge - hulls sx cement, 6th plug to circulate rat hole with size to the plug at 1386' with solution.  STATE CORPORATION COMMISSION  WAR 20 1985  ed.	
3rd plug 4th plug 6th plug 6th plug Piugging Operation ACTUAL PL sx cement plug at 4 15 sx cem	30' below the base of the surface solid bridge hulls - plug at 40' cement to to circulate rat hole with 15 sx Plugging Pro  Operations attended by Agent?:  Is Completed: Hour: 2:50 pm Day:  UGGING REPORT 1st plug at 2172'  T, 3rd plug at 360' with 40 sx cement to surface with 10 ment.  Used 60/40 Pozmix 6% gel by Alli  (if additional description is	e pipe with 40 sx cement  surface with 10 sx cement  cement posal Received by Jack L. Luthi  (TECHNICIAN)  All Part None X  15 Month: March Year: 19 86  with 50 sx cement, 2nd plug at 1386' with 80  ment, 4th & 5th plugs - solid bridge - hulls sx cement, 6th plug to circulate rat hole with single plug at 1386 with singl	
3rd plug 4th plug 6th plug 6th plug Piugging Operation ACTUAL PL sx cement plug at 4 15 sx cem	30' below the base of the surface solid bridge hulls - plug at 40' cement to to circulate rat hole with 15 sx Plugging Pro  Operations attended by Agent?:  Is Completed: Hour: 2:50 pm Day:  UGGING REPORT 1st plug at 2172'  To and plug at 360' with 40 sx cents  40' cement to surface with 10 ment.  Used 60/40 Pozmix 6% gel by Alli  (If additional description is completed) observe this plugging.	e pipe with 40 sx cement  surface with 10 sx cement  cement posal Received by Jack L. Luthi  (TECHNICIAN)  All Part None X  15 Month: March Year: 19 86  with 50 sx cement, 2nd plug at 1386' with 80  ment, 4th & 5th plugs - solid bridge - hulls sx cement, 6th plug to circulate rat hole with solid states at hole with solid states	
3rd plug 4th plug 6th plug 6th plug Piugging Operation ACTUAL PL sx cement plug at 4 15 sx cem Remarks:	30' below the base of the surface solid bridge hulls - plug at 40' cement to to circulate rat hole with 15 sx Plugging Pro  Operations attended by Agent?:  Is Completed: Hour: 2:50 pm Day:  UGGING REPORT 1st plug at 2172'  To and plug at 360' with 40 sx cents  40' cement to surface with 10 ment.  Used 60/40 Pozmix 6% gel by Alli  (If additional description is completed) observe this plugging.	e pipe with 40 sx cement  surface with 10 sx cement  cement posal Received by Jack L. Luthi  (TECHNICIAN)  All Part None X  15 Month: March Year:19 86  with 50 sx cement, 2nd plug at 1386' with 80  ment, 4th & 5th plugs - solid bridge - hulls sx cement, 6th plug to circulate rat hole with size to the plug at 1386' with solution.  STATE CORPORATION COMMISSION  WAR 20 1985  ed.	