KANSAS STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT'S REPORT

Jewel M. Ogden, Director			
500 Insurance Building 212 North Market			
Windsha O remains	\bigcirc		
File No. Cou	inty: Mess		
File No Could Location:	sec. 2	Two. 20 Day (26 (11)
Name of Field:	Ones for many design and the second s	Total Depth: 47	<u>~~</u> (&)(\\). [] 3
I have this date completed supervisi			
Lease Name: Hinkil		Well No	/
Operator's Full Name: Supp (eie Co		
Complete Address: 522 Uhion	Out The	lite Yous	
Plugging Contractor:	2		
Address:		License No.	
Oil Well X Gas Well	Input Well	SWD Well	D&A ×
Other well as hereafter indicated:			
Was any delay in plugging operations	caused by Conserv	ation Division Agen	t? Yes No C
If yes how long?	Reason:		
Operation Completed: Hour 18 Am	Day 19	Money lest	. 166
The above well was plugged as follows	-	Month gypt	Year //
Total Depth 4733 8 5/8" pipe #			
Gunned pitts circulated hole was			e at SOS A.
end displaced 20 sex cement th	ru drill pipe,	heavy and to	ft. eet
committing plug and displaced		heavy mud to 40?	
tled cementing in place dumped	sac dry hulls	, and mixed 10 s	tnemen xa
comenting to bear of pellar.			
	940		
CONSERVA	~··	Milbert P. Leik	er
Washing and a second se	Signed:	Clust J. L	eiken
		Conservation Divi	sion Agent
Reviewed: Lauri Buck			
Field Supervisor		INVOICEL	
Remarks: '	6,	ATE 10/11/60	J
	in	V. No. 2002-	2
		- 2-u	