15-165 20199-00-00

KANSAS

Rev. 6-26-62

## STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT'S REPORTATE CORPORATION COMMISSION

J. P. Roberts Administrator 500 Insurance Building Wichita, Kansas 67202

NOV 2 0 1968 CONSERVATION DIVISION Wichita, Kansas

11-20-1968

thru drill pipe. Heavy mud to 510' set cementing plug and displaced 20 sc cement thru
Lease Name Basgall Well No. 1  Location CW/2 NW SE Sec. 16 Twp. 16 Rge. 17 (E) (W) X  County Rush Total Depth 3570'  Abandoned Oil Well Gas Well Input Well SWD Well D&A XX  Other well as hereafter indicated:  Plugging Contractor: Co. Tools  Address: Incense No.  Operation Completed: Hour7P Day 18 Month 11 Year 1968  The Above well was plugged as follows:  RTD 3570' 8 5/8 csg set at 11h0' cwc  Gummed pits, circulated heavy mud, set cementing plug at 800' and displaced 20 sc cmt thru drill pipe. Heavy mud to 510' set cementing plug and displaced 20 sc cement thru drill pipe, Heavy mud to 40' set cementing plug, 1/2 sc hulls and 10 sc cement to bas
Location CN/2 NW SE Sec. 16 Twp. 16 Rge. 17 (E) (W) X  County Rush Total Depth 3570*  Abandoned Oil Well Gas Well Input Well SWD Well D & A XX  Other well as hereafter indicated:  Plugging Contractor: Go. Tools  Address: License No.  Operation Completed: Hour TP Day 18 Month 11 Year 1968  The Above well was plugged as follows:  RTD 3570* 8 5/8 csg set at 11h0* cwc  Gummed pits, circulated heavy mud, set cementing plug at 800* and displaced 20 sc cement thru drill pipe. Heavy mud to 510* set cementing plug and displaced 20 sc cement thru drill pipe, Heavy mud to 40* set cementing plug, 1/2 sc hulls and 10 sc cement to bas
Abandoned Oil Well Gas Well Input Well SWD Well D&A XX Other well as hereafter indicated:  Plugging Contractor: Go. Tools  Address: Incense No. Operation Completed: Hour7P Day 18 Month 11 Year 1968  The Above well was plugged as follows:  RTD 3570' 8 5/8 csg set at 1140' cwc  Gunned pits, circulated heavy mud, set cementing plug at 800' and displaced 20 sc cmt thru drill pipe. Heavy mud to 510' set cementing plug and displaced 20 sc cement thru drill pipe, Heavy mud to 40' set cementing plug, 1/2 sc hulls and 10 sc cement to bas
Abandoned Oil Well Gas Well Input Well SWD Well D & A XX  Other well as hereafter indicated:  Plugging Contractor: Go. Tools  Address: License No.  Operation Completed: Hour7P Day 18 Month 11 Year 1968  The Above well was plugged as follows:  RTD 3570' 8 5/8 csg set at 1140' cwc  Gummed pits, circulated heavy mud, set cementing plug at 800' and displaced 20 sc cmt thru drill pipe. Heavy mud to 510' set cementing plug and displaced 20 sc cement thru drill pipe, Heavy mud to 40' set cementing plug, 1/2 sc hulls and 10 sc cement to bas
Other well as hereafter indicated:  Plugging Contractor:  Co. Tools  Address:  Co. Tools  License No.  Operation Completed: Hour7P  Day 18  Month 11  Year 1968  The Above well was plugged as follows:  RTD 3570' 8 5/8 csg set at 11h0' cwc  Gummed pits, circulated heavy mud, set cementing plug at 800' and displaced 20 sc cmt thru drill pipe. Heavy mud to 510' set cementing plug and displaced 20 sc cement thru drill pipe, Heavy mud to h0' set cementing plug, 1/2 sc hulls and 10 sc cement to bas
Address:
Address:
Operation Completed: Hour P Day 18 Month 11 Year 1968  The Above well was plugged as follows:  RTD 3570' 8 5/8 csg set at 1140' cwc  Gummed pits, circulated heavy mud, set cementing plug at 800' and displaced 20 sc cmt thru drill pipe. Heavy mud to 510' set cementing plug and displaced 20 sc cement thru drill pipe, Heavy mud to 40' set cementing plug, 1/2 sc hulls and 10 sc cement to bas
Operation Completed: Hour P Day 18 Month 11 Year 1968  The Above well was plugged as follows:  RTD 3570' 8 5/8 csg set at 1140' cwc  Gummed pits, circulated heavy mud, set cementing plug at 800' and displaced 20 sc cmt thru drill pipe. Heavy mud to 510' set cementing plug and displaced 20 sc cement thru drill pipe, Heavy mud to 40' set cementing plug, 1/2 sc hulls and 10 sc cement to bas
RTD 3570' 8 5/8 csg set at 1140' cwc  Gunned pits, circulated heavy mud, set cementing plug at 800' and displaced 20 sc cmt thru drill pipe. Heavy mud to 510' set cementing plug and displaced 20 sc cement thru drill pipe, Heavy mud to 40' set cementing plug, 1/2 sc hulls and 10 sc cement to bas
Gummed pits, circulated heavy mud, set cementing plug at 800' and displaced 20 sc cmt thru drill pipe. Heavy mud to 510' set cementing plug and displaced 20 sc cement thru drill pipe, Heavy mud to 40' set cementing plug, 1/2 sc hulls and 10 sc cement to bas
thru drill pipe. Heavy mud to 510' set cementing plug and displaced 20 sc cement thru drill pipe, Heavy mud to 40' set cementing plug, 1/2 sc hulls and 10 sc cement to bas
drill pipe, Heavy mud to 40' set cementing plug, 1/2 sc hulls and 10 sc cement to bas
of cellar. Plugged rat hole with 2 sc cement.
I hereby certify that the above well was plugged as herein stated.
INVOICED Signed: fro 7. Massey
Wall Diverse Comments
INV. NO