

15101-19022-6000

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
500 INSURANCE BUILDING
212 NORTH MARKET
WICHITA 2, KANSAS

FORM CP-1

STATE CORPORATION COMMISSION

JAN 21 1963

1-21-63
CONSERVATION DIVISION
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM
File One Copy

Lease Owner Davis Brothers

Address Tulsa, Okla.

Lease (Farm Name) Reifschneider 'A' Well No. 1

Well Location SW NE Sec. 17 Twp. 18S Rge. 29W (E) (W)

County Lane Field Name (If any) None

Total Depth 4681 Oil Well Gas Well Input Well SWD Well D & A X

Was well log filed with application? Yes If not, explain:

Date and hour plugging is desired to begin 10:00 AM 1-16-63

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission.

Name of company representative in charge of plugging operations Jack Farret

Address Great Bend, Kansas

Plugging Contractor Terrel Drilling & Producing License No.

Address Russell, Kansas

Invoice covering assessment for plugging this well should be sent to Terrel Drilling &

Producing Address Russell, Kansas

and payment will be guaranteed by applicant.

Signed: Joe K. Brannon
Applicant or Acting Agent

Date: 1-16-63



15101-19022-0000

JOHN ANDERSON, Jr. Governor
RICHARD C. BYRD Chairman
ALVIN F. GRAUERHOLZ Commissioner
HARRY G. WILES Commissioner
RAYMOND B. HARVEY Secretary
CHARLES C. McCARTER Gen. Counsel

State Corporation Commission

CONSERVATION DIVISION

(Oil, Gas and Water)
500 Insurance Bldg. 212 N. Market
WICHITA, KANSAS

January 15, 1963

WELL PLUGGING AUTHORITY

Well No. 1
Lease Reifschneider
Description SW NE 17-18-20W
County Lane

Davis Bros. Oil Co.
510 McFarlin Bldg.
Tulsa, Oklahoma

Gentlemen:

This is your authority to plug the above subject well in accordance with the Rules and Regulations of the State Corporation Commission.

This authority is void after 90 days from the above date.

Very truly yours,

J. P. ROBERTS
Assistant Petroleum Conservation
Director

Mr. W. L. Nichols Moreland, Kansas
is hereby assigned to supervise the plugging of the above
named well.

