

CP1

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
800 BITTING BUILDING
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM
File One Copy

Lease Owner Aurora Gasoline Company Address 308 Wright Bldg. Tulsa, Okla.
(Applicant)

Lease (Farm Name) Anderson Well No. 1

Well Location SE SE NE Sec. 26 Twp. 19S Rge. 20 (E)-(W)

County Rush Field Name (if any)

Total Depth 4542 Oil Gas Dry Hole Dry Hole

Was well log filed with application? Yes. If not, explain:

Date and hour plugging is desired to begin 5-23 1:00 A. M. 1954

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission, or with the approval of the following exceptions: Explain fully any exceptions desired.

(Use an additional sheet if necessary)

Name of the person on the lease in charge of well for owner T. C. Strain

Strain Drilling Company Address Box 188 Hays, Kansas

Name of Plugging Contractor Strain Drilling Company

Address Box 188 Hays, Kansas.

Invoice covering assessment for plugging this well should be sent to

Strain Drilling Company Address Box 188 Hays, Kansas

and payment will be guaranteed by applicant.

RECEIVED
STATE CORPORATION COMMISSION

5-27-54
CONSERVATION DIVISION
Wichita, Kansas

T. C. Strain
Applicant or Acting Agent

Date May 26, 1954

PLUGGING

FILE SEC 26 T 19 R 20W
BOOK 36 PAGE 27

15-165-00110-0000



STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
800 BITTING BUILDING
WICHITA, KANSAS

May 25, 1954

Well No.	
Lease	
Description	Anderson
County	SE SE NE 26-19-20W
File No.	Rush
	36-27

Aurora Oil & Gas Co.
c/o Strain Drig..Co.
Box 188
Hays, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. Warren H. Horner, Box 207, Great Bend, Kansas.

STATE CORPORATION COMMISSION
CONSERVATION DIVISION

BY: J. P. Roberts
J. P. ROBERTS

cc: District Plugging Supervisor