15.135.21089-0000

STATE OF KANSAS STATE CORPORATION COMMISSION CONSERVATION DIVISION P. O. BOX 17027 Wichita, Kansas 67217

Rev. 3-15-72
FORM CP-1
COMMISSION

WELL PLUGGING APPLICATION FORM
File One Copy

FEB 3 1970 NESCOVATION DIVISION We chita, Kansas

Lease Owner
Address 200 O. W. Garvey Bldg.
Lease (Farm Name) Cure Well No. #1
Well Location Sec. 34 Twp. 20 Rge. 22 (E) (W) X
County Ness Total Depth 4390 Field Name
O11 Well Gas Well Imput Well SWD Well Rotary D & A X
Well Log filed with application as required Yes
Date and hour plugging is desired to begin
PLUGGING OF THIS WELL WILL BE DONE IN ACCORDANCE WITH K.S.A. 55-128 OF THE RULES AND REGULATIONS OF THE STATE CORPORATION COMMISSION.
Name of company representative authorized to be in charge of plugging operations:
Wilmer Dreiling Address 408 Jefferson Ellis, IKs.
Plugging Contractor Gabbert-Jones, Inc. License No.
Address 830 Sutton Place
·
Invoice covering assessment for plugging this well should be sent to:
Invoice covering assessment for plugging this well should be sent to: Name
Name I. Mark Richardson
NameI. Mark RichardsonAddress200 0. W. Garvey Bldg.

15-135-4089-0000

STATE OF KANSAS STATE CORPORATION COMMISSION CONSERVATION DIVISION P. O. BOX 17027 Wichita, Kansas 67217

Rev. 3-15-72 FORM CP-1

WELL PLUGGING APPLICATION FORM File One Copy

ddress 200 0. W. Garvey Bldg.	
	Well No. #程 /
	Sec. 34 Twp. 20 a Rge. 22 (E) (W) X/
	Total Depth 43900 Field Name
il Well Gas Well Input Wel	1SWD WellRotary D & AXX
ell Log filed with application as rec	quired Yess
ate and hour plugging is desired to !	begin
ame of company representative author:	ized to be in charge of plugging operations:
	ized to be in charge of plugging operations: Address 408&Jefferson Ellis, IKs.
Wilmer Dreiling	Address 408&Jefferson Ellis, IKs.
Wilmer Dreiling lugging Contractor Gabbert-Jones	Address 4088Jefferson Ellis IKs. License No.
Wilmer Dreiling lugging Contractor	Address 4088Jefferson Ellis, IKs. License No.
Wilmer Dreiling lugging Contractor	Address 4088Jefferson Ellis, IKs. License No. Lace Ing this well should be sent to:
Wilmer Dreiling lugging Contractor	Address 4088Jefferson Ellis TKs. License No. ace ing this well should be sent to:
Wilmer Dreiling lugging Contractor	Address 4088Jefferson Ellis, IKs. License No. ace ing this well should be sent to:
Wilmer Dreiling lugging Contractor	Address 4088Jefferson Ellis IKs. License No. ace ing this well should be sent to: licant or acting agent.
Wilmer Dreiling lugging Contractor	Address 4088Jefferson Ellis, IKs. License No. ace ing this well should be sent to:



15.135-21089000

State Corporation Commission

CONSERVATION DIVISION

(Oil, Gas and Water)
P. O. Box 17027 3830 S. Meridian
WICHITA, KANSAS 67217

September 30, 1975

WELL PLUGGING AUTHORITY

Well No.

2

Lease

Cure

Description

C W/2 NW NE Sec. 34-208-22W

County

Ness 43 90

Total Depth

Plugging Contractor Gabbert & Jones Drilling

J. Mark Richardson 220 O. W. Garvey Building Wichita, Kansas 67202

Gentlemen:

This is your authority to plug the above subject well in accordance with the Rules and Regulations of the State Corporation Commission.

This authority is void after 90 days from the above date.

Yours very truly,

J/Lewis Brock, Administrator

Mr. Leo Massey, 109 W. 15th St., Hays, Kansas is hereby assigned to supervise the plugging of the above named well.



State Corporation Commission

CONSERVATION DIVISION

(Oil, Gas and Water)
P. O. Box 17027 3830 S. Meridian
WICHITA, KANSAS 67217

September 30, 1975

WELL PLUGGING AUTHORITY

Well No.

2

Lease

Cure

Description

C W/2 NW NE Sec. 34-20S-22W

County

Ness 4390

Total Depth 439

Plugging Contractor Gabbert & Jones Drilling

J. Mark Richardson 220 O. W. Garvey Building Wichita, Kansas 67202

Gentlemen:

This is your authority to plug the above subject well in accordance with the Rules and Regulations of the State Corporation Commission.

This authority is void after 90 days from the above date.

Yours very truly,

J. Lewis Brock, Administrato

Mr. Leo Massey, 109 W. 15th St., Hays, Kansas is hereby assigned to supervise the plugging of the above named well.