CONFIDENTIAL

KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

Form ACO-1 June 2009 Form Must Be Typed Form must be Signed All blanks must be Filled

WELL COMPLETION FORM WELL HISTORY - DESCRIPTION OF WELL & LEASE

OPERATOR: License #34392	API No. 15 - 065-23752 -00-CO
Name: TexKan Exploration, LLC	Spot Description:
Address 1: _ P.O. Box 191643	csesesec28twp9s R25 ☐ East ♥ West
Address 2:	1,980 Feet from North / 🗹 South Line of Section
City: Dallas State: TX Zip: 75219 +	1,650 Feet from ✓ East / ☐ West Line of Section
Contact Person: Bill Robinson	Footages Calculated from Nearest Outside Section Corner:
Phone: (785) 688-4040	□NE □NW ☑SE □SW
CONTRACTOR: License #_ 33350	County: Graham
Name: Southwind Drilling	Lease Name: Sauer Well #: 3 A
Wellsite Geologist: Bill Robinson	Field Name: Bollig
ourchaser: Coffeyville	Producing Formation: Lansing/Kansas City
Designate Type of Completion:	Elevation: Ground: 2579 Kelly Bushing: 2588
✓ New Well	Total Depth: 4170 Plug Back Total Depth: 4150
☑ oil ☐ wsw ☐ swd ☐ slow	Amount of Surface Pipe Set and Cemented at: 233 Feet
Gas D&A ENHR SIGW	Multiple Stage Cementing Collar Used? ✓ Yes No
☐ OG ☐ GSW ☐ Temp. Abd.	If yes, show depth set: 2212 Feet
CM (Coal Bed Methane)	If Alternate II completion, cement circulated from: 2212
Cathodic Other (Core, Expl., etc.):	feet depth to: surface w/ 425 sx cmt
f Workover/Re-entry: Old Well Info as follows:	sx cm.
Operator:	
Well Name:	Drilling Fluid Management Plan (Data must be collected from the Reserve Pit)
Original Comp. Date: Original Total Depth:	
☐ Deepening ☐ Re-perf. ☐ Conv. to ENHR ☐ Conv. to SWD	Chloride content: ppm Fluid volume: bbls
Conv. to GSW	Dewatering method used:
Plug Back: Plug Back Total Depth	Location of fluid disposal if hauled offsite:
Commingled Permit #:	Operator Name:
Dual Completion Permit #:	Lease Name: License #:
SWD Permit #:	QuarterSecTIGONFIDENTIALEast West
ENHR Permit #:	
GSW Permit #:	County: Pern#(#G_1_3_2013
7-8-11 7-15-11 7-29-11	KCC
Spud Date or Date Reached TD Completion Date or Recompletion Date	
	1

INSTRUCTIONS: An original and two copies of this form shall be filed with the Kansas Corporation Commission, 130 S. Market - Room 2078, Wichita, Kansas 67202, within 120 days of the spud date, recompletion, workover or conversion of a well. Rule 82-3-130, 82-3-106 and 82-3-107 apply. Information of side two of this form will be held confidential for a period of 12 months if requested in writing and submitted with the form (see rule 82-3-107 for confidentiality in excess of 12 months). One copy of all wireline logs and geologist well report shall be attached with this form. ALL CEMENTING TICKETS MUST BE ATTACHED. Submit CP-4 form with all plugged wells. Submit CP-111 form with all temporarily abandoned wells.

AFFIDAVIT

I am the affiant and I hereby certify that all requirements of the statutes, rules and regulations promulgated to regulate the oil and gas industry have been fully complied with and the statements herein are complete and correct to the best of my knowledge.

Signature:	Bin	0		
Title: agent			_ Date:	8-2-11

KCC Office Use	ONLY
Letter of Confidentiality Received	RECEIVED
_ Date 8/15/11 to 8	1/5/13 1 6 2011
Confidential Release Date:	AUG 10 ZUI
✓ Wireline Log Received☐ Geologist Report Received	KCC WICHITA
UIC Distribution	M Date: \$-23-

Operator Name: Te	xKan Exploration	on, LLC		Lease	Name: _	Sauer		_ Well #: _3	Α	
Sec. 28 Twp.9	s. r. <u>25</u>	☐ East	: ✓ West	Count	_{y:} <u>Gra</u>	ham		101 t - 5 and also		· · · · · · · · · · · · · · · · · · ·
INSTRUCTIONS: Sitime tool open and clarecovery, and flow rateline Logs surveyed.	osed, flowing and sho tes if gas to surface to	ut-in press est, along	ures, whether s with final chart(shut-in pres	ssure rea	ched static leve	l, hydrostatic pres	ssures, bottom	hole temp	erature, fluid
Drill Stem Tests Take (Attach Additional	•	Y	∕es ☑ No		 ✓L		on (Top), Depth a		_	Sample
Samples Sent to Geo	ological Survey	 ✓ Y	es No		Nam Anhy			Тор 2216		Datum 72
Cores Taken Electric Log Run Electric Log Submitte (If no, Submit Cop.	•	□ y ☑ y ☑ y	es 🗌 No		B/KC			4087		1499
List All E. Logs Run: RAG/CNL/DIL	-									
			CASING	RECORD	✓ N	ew Used		·		
		T		conductor, s		ermediate, produc	tion, etc.			
Purpose of String	Size Hole Drilled		ze Casing it (In O.D.)		ight . / Ft.	Setting Depth	Type of Cement	# Sacks Used		and Percent Additives
surface	12 1/4	8 5/8		23		233	common	150	3% C	C + 2% gel
production	7 7/8	5 1/2		15.5		4150	common	100	500 g	al WFR-2
		<u> </u>	ADDITIONAL	L CEMENT	ING / SQI	JEEZE RECORD	<u>. </u>		<u> </u>	
Purpose: Perforate Protect Casing Plug Back TD Plug Off Zone	Depth Top Bottom	Туре	e of Cement	# Sack	s Used		Type and	Percent Additives	3	
Shots Per Foot			RD - Bridge Plug Each Interval Per				acture, Shot, Cemer Amount and Kind of N		rd	Depth
4	4014-20					A/500 15%	6 HCL			3987
								RECE	IVED	
									6 201	1
								KCC W		-Λ
TUBING RECORD:	Size: 2 7/8	Set At:	· · · · · · · · · · · · · · · · · · ·	Packer A	At:	Liner Run:	Yes 🗸	SOVIEIDI 100 M		
Date of First, Resumed	I Production, SWD or EN	NHR.	Producing Met	hod:	ng 🗌	Gas Lift	Other (Explain)	AUG 1		
Estimated Production Per 24 Hours	0ii 10	Bbls.	Gas 0	Mcf	Wat	er E 25	3bls.	Gas-Oil R	_	Gravity 34
DISPOSITI	ION OF GAS:			METHOD O	F COMPLI	ETION:		PRODUCTI	ON INTER	VAL:
✓ Vented Solo	_		_	✓ Perf.		y Comp. Co	mmingled	014-20		
(If vented, Su	ıbmit ACO-18.)		Other (Specify)				· _			

ALLIED CEMENTING CO., LLC. 039661

REMIT TO P.O. BOX 31	SERY	VI CE P QINT:
RUSSELL, KANSAS 67665		Lussell Ks.
		IDENST-200 HAN
	ALLED OUT ON LOCATION	JOB START JOB FINISH
DATE 7-15-2011 29 9 5 25W		COUNTY STATE
LEASE AVER WELL## A-3 LOCATION ST Per	TER BN 1/2W 2NTE	GRAHAMY KONSOS
OLD OR NEW (Circle one)		Carrier
OLD OR TEN CHOIC OIL)		
CONTRACTOR SOUTHWIND DRLG. Rig # 2	OWNER	
TYPE OF JOB PRODUCTION STRING, (2- STAGE, DY)		4
HOLE SIZE 7 7/8 T.D. 4/70	CEMENT	OM STAGE TOP STONE
CASING SIZE 5 1/2 New DEPTH 4158'	AMOUNT ORDERED 1005X	
TUBING SIZE 15.50 tcsG DEPTH	40 4 % Gel 4	FRO-Stal POR SX.
DRIED PIPELATCH DOWN HIM DEPTH 4120	500GAL WER-2 MUDFIUS	
TOOL Weatherford D.V. DEPTHTOLO	2212	<u> </u>
PRES. MAX MINIMUM 2212	COMMON	@
MEAS. LINE SHOE JOINT 30.	POZMIX	@
CEMENT LEFT IN CSG. 30. 05	GEL	
PERFS.		
00	CHLORIDE	@
2 TO - 0020	LASC	@
EQUIPMENT /		
Shane - Heath		@
PUMPTRUCK CEMENTER GRAN		
# 417 HELPER WOODY		
BULK TRUCK	<u> </u>	
# 328 DRIVER NICK		@
BULK TRUCK		
# 481 DRIVER TONY - WALTER	HANDLING 767ALS	x @ 2,25
	MILEAGE TO TON Mile	e 114
REMARKS:	WILEAGE	RECEIVED
Ran 126 JTS OF 52 csg. 15.50#	The state of the state of the second of the second of	TOTAL
HANDA TIS OF SOCCA IS	the state of the s	AUG 1 6 2011
		700 10 20H
SET @ 7/30 Recieved L'iRoulation of		ICE
ROTATE CSG, FOR 1/2 HR, PUMP WFR. 2 Flush		
ROTATE CSG, FOR 1/2 HR, PUMP WFR. 2 FlySH of Cement W/ 1005x Com. Clear-Line and	DEPTH OF JOB	KCC WICHITA
ROTATE CSG, FOR 1/2 HR, Pump WFR. 2 FINSH + Cerment W/ 1005x Com. Clear-Line and DISPACE LATCH DN, Pluy -LAND @ 1700 # (Her	DEPTH OF JOB	KCC WICHITA
ROTATE CSG, FOR 1/2 HR, PUMP WFR. 2 FLYSH + CEMENT W/ 1005x COM, Clear-Line and DISPLACE LATCH DN, Pluy -LAND @ 1700 #. (HELD DROP DART & OPEN DV TOOL @1,000 #, CIRCULA	DEPTH OF JOB D)PUMP TRUCK CHARGE EXTRA FOOTAGE	KCC WICHITA @
RECIEVED L'IRCULATION, ST ROTATE CSG, FOR 1/2 HR, PUMP WFR. 2 FLYSH of Cennent W/ 1008x Com, Clear-Line and DISPLACE LATCH DN, Pluy — LAND @ 1700 #. (HEL DROP DART & OPEN DV TOOL @4,000 #, CIRCULA 2 HRS of MIX 425 3x, ON TOP STAGE ROLE	DEPTH OF JOB DE	KCC WICHITA @
RETATE CSG, FOR 1/2 HR, Pump WFR. 2 FINSH of Cerment W/ 1005x Com. Clear-Line and Displace LATCH DN, Pluy -LAND @ 1700 # (HELD DROP DART & OPEN DV TOOL @4,000 #, CIRCULA 2 HRS, of Mix 425 SX. ON TOP STAGE Released A Displace 53/BBL #12° Close DV, Tookallow	DEPTH OF JOB	KCC WICHITA
RETATE CSG, FOR 1/2 HR, Pump WFR. 2 FINSH of Cerment W/ 1005x Com. Clear-Line and Displace LATCH DN, Pluy -LAND @ 1700 # (HELD DROP DART & OPEN DV TOOL @4,000 #, CIRCULA 2 HRS, of Mix 425 SX. ON TOP STAGE Released A Displace 53/BBL #12° Close DV, Tookallow	DEPTH OF JOB	KCC WICHITA
RECIEVED CIRCULATION STATE COMP WFR. 2 FIVEH of CEMPAT W/ 1005x Com, Clear-Line and Displace LATCH DN, Pluy — LAND @ 1700 # (HELD DROP DART & OPEN DV TOOL @1,000 #, CIRCULA DISPLACE STAGE RELEASED AND TOP STAGE RELEASED AND ADJUST CHOSE DV, TOOL QUIDON TOOL ON TOP STAGE RELEASED AND TOP STAGE RELE	DEPTH OF JOB POPUMP TRUCK CHARGE POEXTRA FOOTAGE MILEAGE 70 MTHY x 2	KCC WICHITA
ROTATE CSG, FOR 1/2 HR, Pump WFR. 2 FINSH of Cerment W/ 1005x Com. Clear-Line and Displace LATCH DN, Pluy — LAND @ 1700 # (HELD DROP DART of OPEN DV TOOL @1,000 #, CIRCUIA 2 HRS, of Mix 425 Sx. ON TOP STAGE, Released BY Acthora 305x@ Hathora (Held Sex & Mouse hole)	DEPTH OF JOB_ DEPTH OF JOB_ DPUMP TRUCK CHARGE DEXTRA FOOTAGE MILEAGE 70 MIHV X 2 MANIFOLD 70 MILY X 2 X OTATING // COD	KCC WICHITA
Retate CSG, FOR 1/2 HR, Pump WFR. 2 FIUSH of Cennent W/ 1005x Com. Clear-Line and Displace LATCH DN, Play — LAND @ 1700 # (HELD DROP DART of OPEN DV TOOL @4,000 #, CIRCUIA 2 HRS, of Mix 425 Sx. ON TOP STAGE Released to the plag. I Displace 53/BBL HIZ Close DV, Tookal, on 305x@ Hathole (Held Sx. e moise hole) CHARGE TO: Tex Kan Exploration 1	DEPTH OF JOB_ DEPTH OF JOB_ DPUMP TRUCK CHARGE DEXTRA FOOTAGE MILEAGE 70 MIHV X 2 MANIFOLD 70 MILY X 2 X OTATING // COD	KCC WICHITA
ROTATE CSG, FOR 1/2 HR, Pump WFR. 2 FINSH of Cerment W/ 1005x Com. Clear-Line and Displace LATCH DN, Pluy — LAND @ 1700 # (HELD DROP DART of OPEN DV TOOL @1,000 #, CIRCUIA 2 HRS, of Mix 425 Sx. ON TOP STAGE, Released BY Acthora 305x@ Hathora (Held Sex & Mouse hole)	DEPTH OF JOB_ DEPTH OF JOB_ DPUMP TRUCK CHARGE DEXTRA FOOTAGE MILEAGE 70 MIHV X 2 MANIFOLD 70 MILY X 2 X OTATING // COD	© 4. 00 -NC-
RECIEVED CIRCULATION, STATE RECIEVED CIRCULATION, STATE RECIEVED CIRCULATION, STATE RECIEVED CIRCULATION, STATE RECIEVED CIRCULATION, STAGE PLUSH RECIEVED CIRCULATION, STAGE PLUSH RECIEVED CIRCULATION, PLOY COMP. CIRCULATION L RECIEVED CIRCULATION COMPAND TO STAGE RELEASE RECIEVED CIRCULATION COMPAND TO STAGE RELEASE RECIEVED CIRCULATION COMPAND C	DEPTH OF JOB_ DPUMP TRUCK CHARGE PEXTRA FOOTAGE MILEAGE 70 MIHV x 2 MANIFOLD	CE KCC WICHITA @ 1/2 00 @ 4. 00 @ 4. 00 TOTAL
Recieved Circulation, of Rotate CSG, FOR 1/2 HR, Pump WFR. 2 FINSH of Comment W/ 1005x Com, Clear-Line and Displace Laten Dn, Pluy — LAND @ 1700 # (Her DROP Dart of OPEN DV Tool @ 1,000 #, CIRCULA 2 HRS, of Mix 425 Sx. ON Top STAGE Release 12 Close Dv, Tool & Jask e moise hole (Here STREET	DEPTH OF JOB_ DPUMP TRUCK CHARGE PEXTRA FOOTAGE MILEAGE 70 MIHV x 2 MANIFOLD	© 4. 00 -NC-
RECIEVED CIRCULATION, STATE RECIEVED CIRCULATION, STATE RECIEVED CIRCULATION, STATE RECIEVED CIRCULATION, STATE RECIEVED CIRCULATION, STAGE PLUSH RECIEVED CIRCULATION, STAGE PLUSH RECIEVED CIRCULATION, PLOY COMP. CIRCULATION L RECIEVED CIRCULATION COMPAND TO STAGE RELEASE RECIEVED CIRCULATION COMPAND TO STAGE RELEASE RECIEVED CIRCULATION COMPAND C	DEPTH OF JOB O)PUMP TRUCK CHARGE EEXTRA FOOTAGE MILEAGE 70 MIHV X 2 MANIFOLD 70 MILY X 2 X OTATING // CAD LC. PLUG & FLOA	CE KCC WICHITA @ 4. 22 @ 4. 22 TOTAL TOTAL
Recieved Circulation, of Rotate CSG, FOR 1/2 HR, Pump WFR. 2 FINSH of Comment W/ 1005x Com, Clear-Line and Displace Laten Dn, Pluy — LAND @ 1700 # (Her DROP Dart of OPEN DV Tool @ 1,000 #, CIRCULA 2 HRS, of Mix 425 Sx. ON Top STAGE Release 12 Close Dv, Tool & Jask e moise hole (Here STREET	DEPTH OF JOB_ DEPTH OF JOB_ DPUMP TRUCK CHARGE PEXTRA FOOTAGE MILEAGE 70 MIHY X2 MANIFOLD 70 MILYX2 XOTATING // PAD LC. PLUG & FLOA	TOTAL TOTAL TOTAL
ROTATE CSG, FOR 1/2 HR, Pump WFR. 2 FINSH of Cennent W/ 1005x Com. Clear-Line and Displace LATCH DN, Play — LAND @ 1700 # (HELD DROP DART of OPEN DV TOOL @4,000 #, CIRCUIA 2 HRS, of Mix 425 Sx. ON TOP STAGE Released to the plag. A Displace 53/BBL HIZ Close DV, Tookal, on 305x@ Hathole (Held Street Charge to: Zex Kan Exploration) CHARGE TO: Zex Kan Exploration I	DEPTH OF JOB O) PUMP TRUCK CHARGE PEXTRA FOOTAGE MILEAGE 70 MIHY X2 MANIFOLD 70 MILY X2 X OTATING HEAD LC. PLUG & FLOA Weathorford(DY) 2 STAGE 1-BASKET 8 - TORBO (PATRALIZ	TEQUIPMENT TOTAL TOTAL TOTAL TOTAL
ROTATE CSG, FOR 1/2 HR, Pump WFR.2 FIVEH of Comment W/ 1005x Com. Clear-Line and Displace Latel Dn, Play - LAND @ 1700 # (HELD DROP DART of OPEN DV TOOL @ 1,000 #, CIRCULA LINE STAGE RELEASE ON TOP STAGE RELEASE ON TOP STAGE RELEASE ON TOP STAGE RELEASE MOSSING HOLD (HELD STREET STATE ZIP STATE ZIP STATE ZIP STATE ZIP STATE ZIP STATE STATE ZIP	DEPTH OF JOB O) PUMP TRUCK CHARGE PEXTRA FOOTAGE MILEAGE 70 MIHY X2 MANIFOLD 70 MILY X2 X OTATING HEAD LC. PLUG & FLOA Weathorford(DY) 2 STAGE 1-BASKET 8 - TORBO (PATRALIZ	TEQUIPMENT TOTAL TOTAL TOTAL TOTAL
ROTATE CSG, FOR 1/2 HR, Pump WFR.2 Flush A CAMENT W/ 1005x Com, Clear-Line AND DISPLACE LATCH DN, Pluy — LAND @ 1700 # (HELD DROP DART & OPEN DV TOOL @ 1,000 #, CIRCUIN 2 HRS, & MIX425 SX. ON TOP STAGE, Rele Plug, & DISPLACE 53 BBL HIZ Close DV, Tool@2,00 30.5x@ Rathole TO STREET CITY STATE ZIP A Cement DID CIRCULATE TO Allied Cementing Co., LLC.	DEPTH OF JOB O) PUMP TRUCK CHARGE CEXTRA FOOTAGE WILLEAGE 70 MIHY X 2 MANIFOLD 70 MILY X 2 X OTATING // PAD LC. PLUG & FLOA Weathorford(DY) 25TAGE 1-BASKET	TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL
Recipie Circulation, State Cisco Circulation, State Cisco, For 12 HR, Pump wfr. Flush of Cement w/ 1005x Com. Clear-Line and Displace Later Dn. floy — Land @ 1700 # (her Drop Dart of Ofen DN Tool @1,000 #, Circulated Displace 53 / BBL H12 Close DN, Tool @1,000 # (her DISPlace 53 / BBL H12 Close DN, Tool @1,000 # (her Displace 53 / BBL H12 Close DN, Tool @1,000 # (her Displace 53 / BBL H12 Close DN, Tool @1,000 # (her Displace 53 / BBL H12 Close DN, Tool @1,000 # (her Displace 53 / BBL H12 Close DN, Tool @1,000 # (her Displace 53 / BBL H12 Close DN, Tool @1,000 # (her Displace 53 / BBL H12 Close DN, Tool @1,000 # (her Displace 53 / BBL H12 Close DN, Tool @1,000 # (her Displace 53 / BBL H12 Close DN, Tool @1,000 # (her Displace 53 / BBL H12 Close DN, Tool @1,000 # (her Displace 53 / BBL H12 Close DN, Tool @1,000 # (her Displace 53 / BBL H12 Close DN, Tool @1,000 # (her Displace 53 / BBL H12 Close DN, Tool @1,000 # (her Displace 53 / BBL H12 Close DN, Tool @1,000 # (her Displace 53 / BBL H12 Close DN, Tool @1,000 # (her Displace 53 / BBL H12 Close DN, Tool @1,000 # (her Displace 54 / BBL H12 Close DN, Tool @1,000 # (her Displace 54 / BBL H12 Close DN, Tool @1,000 # (her Displace 54 / BBL H12 Close DN, Tool @1,000 # (her Displace 54 / BBL H12 Close DN, Tool @1,000 # (her Displace 54 / BBL H12 Close DN, Tool @1,000 # (her Displace 54 / BBL H12 Close DN, Tool @1,000 # (her Displace 54 / BBL H12 Close DN, Tool @1,000 # (her Displace 54 / BBL H12 Close DN, Tool @1,000 # (her Displace 54 / BBL H12 Close DN, Tool @1,000 # (her Displace 54 / BBL H12 Close DN, Tool @1,000 # (her Displace 54 / BBL H12 Close DN, Tool @1,000 # (her Displace 54 / BBL H12 Close DN, Tool @1,000 # (her Displace 54 / BBL H12 Close DN, Tool @1,000 # (her Displace 54 / BBL H12 Close DN, Tool @1,000 # (her Displace 54 / BBL H12 Close DN, Tool @1,000 # (her Displace 54 / BBL H12 Close DN, Tool @1,000 # (her Displace 54 / BBL H12 Close DN, Tool @1,000 # (her Displace 54 / BBL H12 Close DN, Tool @1,000 # (her Displace 54 / BBL H12 Close DN, Tool @1,000	DEPTH OF JOB O) PUMP TRUCK CHARGE CEXTRA FOOTAGE WHILEAGE 70 MTHY X2 MANIFOLD 70 MILY X2 X OTATING HEAD LC. PLUG & FLOA Weathorford(DY) 2 STAGE 1-BASKET 8 - TORBO (PANTRA) 1-FIOATSHOE	TEQUIPMENT TOTAL TOTAL TOTAL TOTAL
Recieved Circulation, State CSG, FOR 12 HR, Pump wfr. 2 Flush of Coment w/ 1008x Com. Clear-Line and Displace Latch Dn. Pluy — Land @ 1700 # (Her DROP Dart of OPEN DV Tool @ 1000 #, Circulated Lines of Mix 425 8x. On Top Stage, Here Plug, a Displace 53 BBL H12° Close Dv. Tool 2005x @ Hathole (Here Street City State ZIP CITY STATE ZIP CITY STATE ZIP To Allied Cementing Co., LLC. You are hereby requested to rent cementing equipment and furnish cementer and helper(s) to assist owner or	DEPTH OF JOB_ DEPTH OF JOB_ DPUMP TRUCK CHARGE PEXTRA FOOTAGE MILEAGE 70 MIHY X2 MANIFOLD 70 MILYXA XOTATING // PAD LC. PLUG & FLOA Ventraroro (DY) 2 STAGE 1-BASKET 8 - TORBO CENTRAIZ 1-LATCH DOWN Flug AS	TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL
Recipied Circulation of Comment w/ 100 st Comm. Clear-Line and Displace Later Dn. Pluy — Land @ 1700 # (Head Drop Dart of Open DV Tool @ 1700 # (Head Drop DV Tool @ 1700 # (Head Drop DV Tool @ 1700 # (Head	DEPTH OF JOB O) PUMP TRUCK CHARGE CEXTRA FOOTAGE WHILEAGE 70 MTHY X2 MANIFOLD 70 MILY X2 X OTATING HEAD LC. PLUG & FLOA Weathorford(DY) 2 STAGE 1-BASKET 8 - TORBO (PANTRA) 1-FIOATSHOE	TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL
Recieved Circulation, State Cisc. For 1/2 HR, Pump wfr. 2 Flush of Comment w/ 100 Sx Com. Clear-Line and Displace Lately Dn, Pluy — Land @ 1700 # (her Drop Dart of Ofen Drop Tool Groot F. Circulated Lately Drop Dart of Ofen Drop Stage Released Drop Stage Released Drop Stage Drop Tool Circulated Test of Did Circulated Drop Street State Drop Circulated Drop Street Drop Circulated Drop Street Drop Circulated Drop Drop Circulated Drop Street Drop Circulated Drop Drop Street Drop Drop Circulated Drop Drop Drop Drop Drop Drop Drop Drop	DEPTH OF JOB O) PUMP TRUCK CHARGE CEXTRA FOOTAGE WHILEAGE 70 MTHY X2 MANIFOLD 70 MILY X2 X OTATING HEAD LC. PLUG & FLOA Weathorford(DY) 2 STAGE 1-BASKET 8 - TORBO (PANTRA) 1-FIOATSHOE	TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL
Recieved C. Reulation, Stock of Composite CSG, For 12 HR, Pump wfr. 2 Flush of Comment w/ 100 Sx Com. Clear-Line and Displace Latel Dn, Pluy — Land @ 1700 # (her Drop Dart of Olen Drop Groot from Circulation) A HRS, of Mix 425 Sx. On Top Stage, Reference for mose hole. CHARGE TO: Tex Kan Exploration I STREET CITY STATE ZIP To Allied Cementing Co., LLC. You are hereby requested to rent cementing equipment and furnish cementer and helper(s) to assist owner or contractor to do work as is listed. The above work was done to satisfaction and supervision of owner agent or contractor. I have read and understand the "GENERAL"	DEPTH OF JOB O) PUMP TRUCK CHARGE PEXTRA FOOTAGE MILEAGE 70 MIHY X2 MANIFOLD 70 MILY X2 ROTATING HEAD LC. PLUG & FLOA Weather FORD (DY) 2 STAGE 1-BASKET 8-TORBO CENTRALIZ 1-FIOAT Shoe 8-LIMIT Clamp'S	TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL
Recieved Circulation, Store to CSG, FOR 1/2 HR, Pump WFR. 2 Flush of Comment w/ 100 Sx Com. Clear-Line and Displace Latel Dn, Pluy — Land @ 1700 # (her Drop Dart of Olen Drop Composite Circulation) 2 HRS, of Mix 425 Sx. On Top Stage, Release Plug, of Pathole 32 RBL H12° Close Dr. Topage, Release Sx emose hole. CHARGE TO: Zex Kon Exploration STREET CITY STATE ZIP To Allied Cementing Co., LLC. You are hereby requested to rent cementing equipment and furnish cementer and helper(s) to assist owner or contractor to do work as is listed. The above work was done to satisfaction and supervision of owner agent or	DEPTH OF JOB O) PUMP TRUCK CHARGE CEXTRA FOOTAGE SMILEAGE 70 MTHY x2 MANIFOLD 70 MILY X2 ROTATING HEAD LC. PLUG & FLOA Veathorford(DY) 2 STAGE 1-BASKET 8 - TORBO Centraliz 1-LATCH Down Plug AS 1-FJOATSHOE 8-Limit Clamp'S SALES TAX (If Any)	TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL
Recieved C. Real Atom, Starte CSG, FOR 1/2 HR, Pump WFR. 2 Flush of Comment w/ 100 Sx Comm, Clear-Line and Displace Latel Dn, Pluy — Land @ 1700 # (her DROP Dart of Olem DV Tool @ 1000 #, Circular 2 HRS, of Mix 425 Sx. on Top Stage, Release 100 Not the Stage Dv, Tool 200 Not the Stage Dv, T	DEPTH OF JOB O) PUMP TRUCK CHARGE PEXTRA FOOTAGE MILEAGE 70 MIHY X2 MANIFOLD 70 MILY X2 ROTATING HEAD LC. PLUG & FLOA Weather FORD (DY) 2 STAGE 1-BASKET 8-TORBO CENTRALIZ 1-FIOAT Shoe 8-LIMIT Clamp'S	TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL
Recieved Circulation, State CSG, For 12 HR, Pump wfr. Flush of Cerment w/ 1008x Com. Clear-Line and Displace Lateld Dn. Pluy — Land @ 1700 # (her DROP Dart of OPEN DV Tool @ 1000 #, Circulated Dn. Plus of Tool @ 1700 #, Circulated Dn. Plus of Mix 425 3x. ON Top Stage Released Tools of the Mix 425 3x. ON Top Stage Released Charge Dv. Toologo Machole (Held See Mose hole) CHARGE TO: Tex Kon Exploration I STREET CITY STATE ZIP To Allied Cementing Co., LLC. You are hereby requested to rent cementing equipment and furnish cementer and helper(s) to assist owner or contractor to do work as is listed. The above work was done to satisfaction and supervision of owner agent or contractor. I have read and understand the "GENERAL TERMS AND CONDITIONS" listed on the reverse side.	DEPTH OF JOB DEPTH OF JOB DPUMP TRUCK CHARGE PEXTRA FOOTAGE MILEAGE 70 MTHY x2 MANIFOLD 70 MILY X2 ROTATING HEAD LC. PLUG & FLOA Ventraforo(DY) 2 STAGE 1-BASKET 8 - TORBO (PANTRAIZ 1-HATCH DOWN Plug AS 1-FIOATShoe B-LIMIT Clamp'S SALES TAX (If Any) TOTAL CHARGES	TOTAL TOTAL TOTAL TOTAL TOTAL
Recieved Circulation, State CSG, FOR 1/2 HR, Pump WFR. 2 Flush of Comment w/ 100 Sx Comm. Clear-Line and Displace Latel Dn, Pluy — Land @ 1700 # (her Drop Dart of Open DV Tool @ 1000 #, Circulated Dn, Plug - Land @ 1700 #, Circulated Dn, Plug - Land @ 1700 #, Circulated Dn, Plug - Land @ 1700 #, Circulated Dn, Plug - Displace 53 RBL H12 Close Dv, Toologo Released Sx & mosse hole. CHARGE TO:	DEPTH OF JOB DEPTH OF JOB DPUMP TRUCK CHARGE DEXTRA FOOTAGE SMILEAGE 70 MIHY X 2 MANIFOLD TO MILY X 2 ROTATING HEAD LC. PLUG & FLOA Weather FOR (DY) 2 STAGE 1-BASKET 8-TORBO Centraliz 1-LATCH Down Plug AS 1-LATCH Down Plug AS 1-LATCH Down Plug AS 1-LATCH CHARGES BALES TAX (If Any) TOTAL CHARGES DISCOUNT	TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL
Recieved Circulation, Starte CSG, For 12 HR, Pump wfr. Flush of Cerment w/ 1008x Com. Clear-Line and Displace Later Dn. Pluy — Land @ 1700 # (her DROP Dart of OPEN DV Tool @ 1000 #, Circulated Displace Sales Inc. ON Top Stage Released To Sales Hold Close Dv. Toologo (Here) CHARGE TO: Tex Kon Exploration I STREET CITY STATE ZIP To Allied Cementing Co., LLC. You are hereby requested to rent cementing equipment and furnish cementer and helper(s) to assist owner or contractor to do work as is listed. The above work was done to satisfaction and supervision of owner agent or contractor. I have read and understand the "GENERAL TERMS AND CONDITIONS" listed on the reverse side.	DEPTH OF JOB DEPTH OF JOB DPUMP TRUCK CHARGE PEXTRA FOOTAGE MILEAGE 70 MTHY x2 MANIFOLD 70 MILY X2 ROTATING HEAD LC. PLUG & FLOA Ventraforo(DY) 2 STAGE 1-BASKET 8 - TORBO (PANTRAIZ 1-HATCH DOWN Plug AS 1-FIOATShoe B-LIMIT Clamp'S SALES TAX (If Any) TOTAL CHARGES	TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL

ALLIED CEMENTING CO., LLC. 035909

DATE 7/5/1/	SEC.	wp.	RANGE 2	y . , , , ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ;	CALLED OUT	ON	LOCATION	JOB START	JOB FINISH
	3	1	LOCATION	177	1			COUNTY	STATE
LD OR NEW (Ci	rcle one)	17	LOCATION	1211		2 to Re		UZENOA	
CO OR GEO (CI		ant displica Assumed si		- 	doi: M	1 a fr	<u>Paring Comating</u> The Language at 1	_ka arabi	eri og progressi De Salando og erde
ONTRACTOR	South	<u> </u>	Acilles	K. t.	OWNER			<u> </u>	
YPE OF JOB	Surture	201	روحه ا) <u>C</u>	CEMEN		ky refulgaci	the Madelpha	d demograph
OLE SIZE / ASING SIZE A	2/x 1		TH 223		-	IT ORDER	ED /5		75.66
UBING SIZE		DEP			AMOUN	S God	CD / ~ .	- 1 SA	
RILL PIPE	us karren aust		TH ment	en Fonds					od se <mark>sala se i della la</mark> Odda, sala se i della la
OOL	Tadage to had blinde	DEP	TH	n (liphelli)		1844.00			ar Davis i
RES. MAX			TALLED AVA	<u>U karani si</u>	COMM		<u>ehouseligt</u>		
IEAS. LINE		SHC	DE JOINT		POZMIZ			<u> </u>	
<u>EMENT LEFT IN</u> ERFS.				engeliensk Koolenskool	GEL	· · · 	กูกราบกระหนึ่งเลือน เพราะเกราะ	<u> </u>	
ISPLACEMENT				<u>" </u>	ASC				
ICLIVILLI II	EQUIP			4 37.84 Y	2.7			@	
1788、 建筑 1888年1920年20日本	EQUIF.	TURN HE			A Property	i when h			spiros riegidos
UMPTRUCK	CEMENTER		144 c		ខែស្ន ី ខេត ្ត	1 (3.07/49) (36.09)	eldi basırdır.	<u> </u>	
	HELPER	10,0	4		en om en	ा । अनुवेशीय है कि व्यवस्था है । - विकास के कि	ant ne propinitions The contract of the	-@RECEN	ÆD
ULK TRUCK			San Market	ali di Kisa.		r in english din	Lucilia, Sa	@ <u></u>	วกท
	DRIVER	Mari	<u> </u>		JANA JAN			— @ AUb 1 u	Margaria Gradiania
ULK TRUCK				et y Wit	144.14			&CC MI	CHITA
	DRIVER	<u>. 1 2313.</u>		F.W. A.(H.)	HANDL	ING	州班特特力		Marie de la companion de la co La companion de la companion de
i e e e e e e e e e e e e e e e e e e e	or is the figure in the state The residual to the state of the	trodika tekt Kalingan	STAN SALA AND Berthall Sala		MILEA	GE	* 179 de		
. ak od 1800 – progradne nakolena in kaj k	REMA	ARKS:	CONTRACTOR STATE	ensi 25 sectione		an a	. Carlos de la cida de la región de Maria.	TOTA	Locara say a sa
Ran 6	<u>n 40-4-1, 1414.</u> Vision 190-4 0- <u>50</u>	Com	-/n~j	5.7	*************************************		SERV	ICE	જારાઓ મુખ્ય છે. જે ત્રીના ફુટ કાંગણ જો છે. ભી ભાગમાં મુખ્ય લાગો છે.
Ran 6 y	Surger last	60m		p/a.	DEPTH	OF JOB			
Ran 6 3 Fil C Mx-1 13 8 6	150 51	Con		لتور خطيفية	DEPTH PUMPT	OF JOB_	ARGE	and the second second	
Ran 6 3	South	Comments of the second		p/a.	DEPTH PUMPT EXTRA	OF JOB TRUCK CH FOOTAGE	ARGE	rapudaking	ang akang akan ang akang ay arang ar
Ran 6) [13.5]	Sunday	Silver Silver		pla-	DEPTH PUMPT EXTRA MILEA	OF JOB_ RUCK CH FOOTAGE GE	ARGE		arenane ag
Ran 6 } [150 Sh	STORESTORE		pla-	DEPTH PUMPT EXTRA MILEA MANIF	OF JOB TRUCK CH FOOTAGE GE	ARGE	@ 3aa	energia (de la de la dela de
Ran 6) [150 sh	ST. Comments		pla-	DEPTH PUMPT EXTRA MILEA MANIF	OF JOB FRUCK CH FOOTAGE GE	ARGE	_ @ _ @ _ @	A CONTRACTOR OF THE STATE OF TH
Par 6	150 Sl	STORES		s/e	DEPTH PUMPT EXTRA MILEA MANIF	OF JOB FRUCK CH FOOTAGE GE	ARGE	@ @ @	energende er gebende e
CHARGE TO:	Tox 1		Cuda hay		DEPTH PUMP T EXTRA MILEA MANIF	OF JOB FRUCK CH FOOTAGE GE	ARGE	_ @ _ @ _ @	
CHARGE TO:	Tex 1		e de servicio de la companya della companya della companya de la companya della c		DEPTH PUMP T EXTRA MILEA MANIF	OF JOB FRUCK CH FOOTAGE GE	ARGE		
CHARGE TO:	Tex 1		Cuda hay		DEPTH PUMP T EXTRA MILEA MANIF	OF JOB FRUCK CH FOOTAGE GE	ARGE		
CHARGE TO:	Tex 1		e de servicio de la companya della companya della companya de la companya della c		DEPTH PUMP T EXTRA MILEA MANIF	OF JOB FRUCK CH FOOTAGE GE	ARGE	@ @ @ 	
CHARGE TO:	Tex 1		e de servicio de la companya della companya della companya de la companya della c		DEPTH PUMP T EXTRA MILEA MANIF	OF JOB FRUCK CH FOOTAGE GE	ARGE	@ @ @ 	
CHARGE TO:	STAT		e de servicio de la companya della companya della companya de la companya della c		DEPTH PUMP T EXTRA MILEA MANIF	OF JOB FRUCK CH FOOTAGE GE	ARGE	@ @ @ TOTA	
CHARGE TO:	STAT	Carrier of the second of the s	ZIP		DEPTH PUMP T EXTRA MILEA MANIF	OF JOB FRUCK CH FOOTAGE OLD PLU	ARGE	@ @ TOTA TEQUIPME	
CHARGE TO: CITY To Allied Cemer You are hereby r	STAT	TE Centre	ZIP	ipment	DEPTH PUMP T EXTRA MILEA MANIF	OF JOB FRUCK CH FOOTAGE OLD PLU	ARGE	@ @ @ @ TOTA T EQUIPMI @ @ @	
CHARGE TO: CITY To Allied Cemer You are hereby r and furnish ceme	STAT sting Co., LI equested to renter and hel	C: refit cent per(s) t	ZIP	lipment ner or	DEPTH PUMP TEXTRA MILEA MANIF	OF JOB FRUCK CH FOOTAGE OLD PLU	ARGE	@ @ TOTA TEQUIPME	
CHARGE TO:	STAT strating Co., LI equested to renter and hel work as is li	C. rent cent lper(s) to sted. T	ZIP menting equipo assist ow he above w	ipment ner or ork was	DEPTH PUMP TEXTRA MILEA MANIF	OF JOB FRUCK CH FOOTAGE OLD PLU	ARGE	@ @ @ TOTA T EQUIPMI @ @ @ @ @ @	
CHARGE TO:	STAT strate strate strate conting Co., LI equested to reduce and hel work as is lift ion and supe	C: refit cent lper(s) t sted. Ti	ZIP. menting equivo assist ow he above w of owner a	ipment ner or ork was gent or	DEPTH PUMPT EXTRA MILEA MANIF	OF JOB FRUCK CH FOOTAGE OLD PLU	ARGE	@ @ @ @ TOTA T EQUIPMI @ @ @	
CHARGE TO:	STAT stranger Co., LI requested to renter and hel work as is li ion and super read and u	Crefit cent lper(s) to sted. The revision understa	ZIP menting equipo assist ow he above wo fowner a and the "GE"	ipment ner or ork was gent or NERAL	DEPTH PUMPT EXTRA MILEA MANIF	OF JOB FRUCK CH FOOTAGE OLD PLU	ARGE	@ @ @ TOTA T EQUIPMI @ @ @ @ @ @	
CHARGE TO:	STAT stranger Co., LI requested to renter and hel work as is li ion and super read and u	Crefit cent lper(s) to sted. The revision understa	ZIP menting equipo assist ow he above wo fowner a and the "GE"	ipment ner or ork was gent or NERAL	DEPTH PUMPT EXTRA MILEA MANIF	OF JOB_FRUCK CH FOOTAGE OLD PLU	ARGE	@ @ @ TOTA T EQUIPMI @ @ @ @ @ @	
CHARGE TO: CTREET To Allied Cemer You are hereby re and furnish ceme contractor to do done to satisfactic contractor. I have TERMS AND C	STAT STAT Atting Co., LI requested to requested to requested to requested to requested and the read and th	C. refit cent lper(s) to sted. The rvision understands S" listed.	ZIP menting equio assist ow he above w of owner a and the "GE d on the rev	ipment ner or ork was gent or NERAL	DEPTH PUMP T EXTRA MILEA MANIF SALES TOTAL	OF JOB_FRUCK CH FOOTAGE OLD	ARGE	@ @ @ TOTA T EQUIPMI @ @ @ @ @ @	
CHARGE TO:	STAT STAT Atting Co., LI requested to requested to requested to requested to requested and the read and th	Crefit cent lper(s) to sted. The revision understa	ZIP menting equio assist ow he above w of owner a and the "GE d on the rev	ipment ner or ork was gent or NERAL erse side	DEPTH PUMPT EXTRA MILEA MANIF SALES TOTAL	OF JOB_FRUCK CH FOOTAGE OLD	ARGE	@ @ @ TOTA T EQUIPME @ @ @ @ TOTA	
CHARGE TO: CTREET CITY To Allied Cemer You are hereby reand furnish cemer contractor to do done to satisfaction to contractor. I have the contractor of the contractor of the contractor. I have the contractor of the contract	STAT STAT Atting Co., LI requested to requested to requested to requested to requested and the read and th	C. refit cent lper(s) to sted. The rvision understands S" listed.	ZIP menting equio assist ow he above w of owner a and the "GE d on the rev	ipment ner or ork was gent or NERAL erse side	DEPTH PUMP T EXTRA MILEA MANIF SALES TOTAL	OF JOB_TRUCK CH_FOOTAGE GE OLD TAX (If Ar. CHARGE	ARGE	@ @ @ TOTA T EQUIPME @ @ @ @ TOTA	INT