TO: STATE CORPORATION COMMISSION CONSERVATION DIVISION - PLUGGING SECTION 200 COLORADO DERBY BUILDING WICHITA, KANSAS 67202	API NUMBER 15- 135-22,066-000
	C NE NE, SEC. 25, 7 16 s, R 26 W/E
	feet from \$ section line
TECHNICIAN'S PLUGGING REPORT	660 feet from E section line
Operator License / 5131	Lease Name Stutz Weil # 1
Operator: Thunderbird Drilling, Inc.	County Ness 147.19
Name& P.O. Box 97	Well Total Depth 4529 feet
Ellinwood, KS 67526	Conductor Pipe: Sizefeet
	Surface Casing: Size 8 5/8 feet 356
therdened Oll Well X Gas Well	Input Well D&A
Other well as hereinafter indicated	
	Drilling Inc. Hanne Number 5131
	Drilling, Inc. License Number 5131
Address P.O. Box 97. Ellinwood, KS 67526	
Company to plug at: Hour: 10:15 a.m. Day:	11 Month: 8 Year:19 89
Plugging proposal received from Maynard	Weber
(company name) Thunderbird Drilling, In	316-564-2577
(company name) Indidezoria Diliano, in	(phone) 310-304 2377
were: 4½" at 4522' Open hole 4522-29'	
were: 4½" at 4522' Open hole 4522-29' 1st plug sand back to 4470' and dump 4 sx	cement on top of sand through bailer,
were: 4½" at 4522' Open hole 4522-29' 1st plug sand back to 4470' and dump 4 sx 2nd plug pump 4 sx hulls, 70 sx cement, 1	cement on top of sand through bailer,
were: 4½" at 4522' Open hole 4522-29' 1st plug sand back to 4470' and dump 4 sx	cement on top of sand through bailer,
lst plug sand back to 4470' and dump 4 sx 2nd plug pump 4 sx hulls, 70 sx cement, 1 and pump 150 sx cement.	c cement on top of sand through bailer,  O sx gel, 1 sx hulls, release 8 5/8" wiper plug
lst plug sand back to 4470' and dump 4 sx 2nd plug pump 4 sx hulls, 70 sx cement, 1 and pump 150 sx cement.	cement on top of sand through bailer,
lst plug sand back to 4470' and dump 4 sx 2nd plug pump 4 sx hulls, 70 sx cement, 1 and pump 150 sx cement.	c cement on top of sand through bailer,  O sx gel, 1 sx hulls, release 8 5/8" wiper plug  posal Received by Richard Lacey  (TECHNICIAN)
were: 4½" at 4522' Open hole 4522-29'  1st plug sand back to 4470' and dump 4 sx  2nd plug pump 4 sx hulls, 70 sx cement, 1  and pump 150 sx cement.  Plugging Pro  Plugging Operations attended by Agent?:	cement on top of sand through bailer,  O sx gel, 1 sx hulls, release 8 5/8" wiper plug  posal Received by Richard Lacey  (TECHNICIAN)  All X Part None
lst plug sand back to 4470' and dump 4 sx  2nd plug pump 4 sx hulls, 70 sx cement, 1  and pump 150 sx cement.  Plugging Pro  Plugging Operations attended by Agent?:  Operations Completed: Hour: 11 a.m. Day:	cement on top of sand through bailer,  O sx gel, 1 sx hulls, release 8 5/8" wiper plug  posal Received by Richard Lacey (TECHNICIAN)  Allx Part None
lst plug sand back to 4470' and dump 4 sx  2nd plug pump 4 sx hulls, 70 sx cement, 1  and pump 150 sx cement.  Plugging Pro  Plugging Operations attended by Agent?:  Operations Completed: Hour: 11 a.m. Day: ACTUAL PLUGGING REPORT 1st plug bailed 4	cement on top of sand through bailer,  O sx gel, 1 sx hulls, release 8 5/8" wiper plug  posal Received by Richard Lacey (TECHNICIAN)  All X Part None  11 Month: 8 Year:19 89  ex cement at top of fish at 3755',
lst plug sand back to 4470' and dump 4 sx  2nd plug pump 4 sx hulls, 70 sx cement, 1  and pump 150 sx cement.  Plugging Pro  Plugging Operations attended by Agent?:  Operations Completed: Hour: 11 a.m. Day:  ACTUAL PLUGGING REPORT 1st plug bailed 42  2nd plug pumped 400 lbs. hulls, 70 sx cement.	coment on top of sand through bailer,  O sx gel, 1 sx hulls, release 8 5/8" wiper plug  posal Received by Richard Lacey (TECHNICIAN)  AllxPartNone
lst plug sand back to 4470' and dump 4 sx  2nd plug pump 4 sx hulls, 70 sx cement, 1  and pump 150 sx cement.  Plugging Pro  Plugging Operations attended by Agent?:  Operations Completed: Hour: 11 a.m. Day: ACTUAL PLUGGING REPORT 1st plug bailed 4	coment on top of sand through bailer,  O sx gel, 1 sx hulls, release 8 5/8" wiper plug  posal Received by Richard Lacey (TECHNICIAN)  All x Part None
lst plug sand back to 4470' and dump 4 sx  2nd plug pump 4 sx hulls, 70 sx cement, 1  and pump 150 sx cement.  Plugging Pro  Plugging Operations attended by Agent?:  Operations Completed: Hour: 11 a.m. Day:  ACTUAL PLUGGING REPORT 1st plug bailed 42  2nd plug pumped 400 lbs. hulls, 70 sx cement.	coment on top of sand through bailer,  O sx gel, 1 sx hulls, release 8 5/8" wiper plug  posal Received by Richard Lacey (TECHNICIAN)  All x Part None  11 Month: 8 Year:19 89  Esx cement at top of fish at 3755', ment, 10 sx gel, 100 lbs. hulls, and 150 sx  O psi and shut in 100 psi.  RECEIVED
lst plug sand back to 4470' and dump 4 sx  2nd plug pump 4 sx hulls, 70 sx cement, 1  and pump 150 sx cement.  Plugging Pro  Plugging Operations attended by Agent?:  Operations Completed: Hour: 11 a.m. Day:  ACTUAL PLUGGING REPORT 1st plug bailed 42  2nd plug pumped 400 lbs. hulls, 70 sx cement.	coment on top of sand through bailer,  O sx gel, 1 sx hulls, release 8 5/8" wiper plug  posal Received by Richard Lacey (TECHNICIAN)  All x Part None
lst plug sand back to 4470' and dump 4 sx  2nd plug pump 4 sx hulls, 70 sx cement, 1  and pump 150 sx cement.  Plugging Pro  Plugging Operations attended by Agent?:  Operations Completed: Hour: 11 a.m. Day:  ACTUAL PLUGGING REPORT 1st plug bailed 42  2nd plug pumped 400 lbs. hulls, 70 sx cement.	coment on top of sand through bailer,  O sx gel, 1 sx hulls, release 8 5/8" wiper plug  posal Received by Richard Lacey (TECHNICIAN)  All x Part None  11 Month: 8 Year:19 89  Esx cement at top of fish at 3755', ment, 10 sx gel, 100 lbs. hulls, and 150 sx  O psi and shut in 100 psi.  RECEIVED

1 N. A.O 1 GED, WV. NO. 25680