STATE CORPORATION COMMISSION CONSERVATION DIVISION - Plugging Section 130 S. Market, Room 2078 Wichita, Kansas 67202 NOV 2 9 1994

11-29-1994

CONSERVATION DIVISION
WICHITA, KS

			- Wichin			
		C 14/2 C14		MBER: <u>15-077</u> N <u>2</u> Tolanshi		
	_	C W/2 SW	NW , SECTION	M <u>Z</u> IOMISHI	IP RANGE	: <u>_5₩</u> _
OPERATOR LICEN	ise # 45	11		3300 FFF	T FROM S SECTION L	INF
or Entrion Electric	<u> 10</u>				ET FROM E SECTION	
OPERATORV	WILLIAM	H DAVIS				
NAME &						
ADDRESS						
						159.58
					ORREST #1	15 17
				COUNTY: HAR	PER	
				WELL TOTAL DEPTH:	4910'	PR 580/
			COMPLIC	TOR PIPE:4-1/	2" 8 40251	
			00,000		2 (1020	
			SURFAC	E CASING: 8-5	/8" @ 290'	
ABANDONED OIL	WELL	GAS WELL	X IMPUT	WELL SMD	DEA _	
OTHER LEEL AS	HEDE I NAFTED	INDICATED.				
OTHER BELL AD	ILLEI ILLE					· · · · · · · · · · · · · · · · · · ·
			BECHTEL			
ADDRESS:B	BLACKWEL]	L OK		LIC	ENSE:	· · · · · · · · · · · · · · · · · · ·
					_	
COMPANY TO PLU	JG AT: HOUR:		DAY:	MONTH:	YR:	<u> 1994 </u>
Dillective Drope	MAI DECEMEN	rnow- DA	RREL RENEA	TT		
	EXAT KECF I AFD			NO .		
COMPANY NAME -	WUD	AUTC			DHOUT.	
COMPANY NAME:	<u>W H D2</u>	AVIS			PHOKE:	
				- CIBP 3801		
WERE: PB'	TD 3801'	- PERFS	3874 - 78'		<u>' - 33</u>	98'-
WERE: <u>PB'</u>	TD 3801'	- PERFS	3874 - 78'	- CIBP 3801	<u>' - 33</u>	98'-
WERE: <u>PB'</u>	TD 3801' 4' - SAN	- PERFS	3874 - 78'	- CIBP 3801	<u>' - 33</u>	98'-
MERE: PB' 340-C'	TD 3801' 4' - SAN IRC 340'	- PERFS	3874-78' 0' & 4 SX	- CIBP 3801	<u>' - 33</u>	98'-
MERE: PB' 340-C'	TD 3801' 4' - SAN IRC 340'	- PERFS	3874 - 78'	- CIBP 3801	<u>' - 33</u>	98'-
MERE: PB' 340 - C'	TD 3801' 4' - SAN IRC 340'	- PERFS ID TO 335	3874-78' 0' & 4 SX	- CIBP 3801 - 35 SX 900	' - 35 SX 6	98'-
PLUGGING OPERA	TD 3801' 4' - SAN IRC 340' SSAL RECEIVED ATTOMS ATTEND	- PERFS ID TO 335 BY:	3874-78' 0' & 4 SX	- CIBP 3801 - 35 SX 900	- 33 - 35 SX 6	98'-
PLUGGING OPERA	TD 3801' 4' - SAN IRC 340'	- PERFS ID TO 335 BY:	3874-78' 0' & 4 SX	- CIBP 3801 - 35 SX 900	' - 35 SX 6	98'-
PLUGGING PROPORTION OF THE PROPERTY COMPLETED:	TD 3801' 4' - SAN IRC 340' DSAL RECEIVED ATIONS ATTENDO HOUR: 14	- PERFS ID TO 335 BY:	3874-78' 0' & 4 SX	- CIBP 3801 - 35 SX 900	- 33 - 35 SX 6	98'-
PLUGGING PROPO PLUGGING OPERA COMPLETED: ACTUAL PLUGGIN	TD 3801' 4' - SAN IRC 340' SSAL RECEIVED ATIONS ATTENDI HOUR: 14	PERFS D TO 335 BY: ED BY AGENT?	3874-78' 0' & 4 SX ALL (- CIBP 3801 - 35 SX 900 PART (_X	- 33 - 35 SX 6	98'- 500'
PLUGGING PROPO PLUGGING OPERA COMPLETED: ACTUAL PLUGGIN	TD 3801' 4' - SAN IRC 340' SAL RECEIVED ATIONS ATTENDO HOUR: 14 IG REPORT: ERFS CLC	PERFS D TO 335 BY: D BY AGENT? OSED BY P	3874-78' 0' & 4 SX ALL (DAY:17	- CIBP 3801 - 35 SX 900	- 33 - 35 SX 6 - 35 SX 6 - 36 SX 6 - 37 SX 6	98'- 500'
PLUGGING PROPO PLUGGING OPERA COMPLETED: ACTUAL PLUGGIN	TD 3801' 4' - SAN IRC 340' DSAL RECEIVED ATIONS ATTENDO HOUR: 14 IG REPORT: ERFS CLC DISP TO	- PERFS D TO 335 BY: ED BY AGENT? OSED BY P 0 2708! -	3874-78' 0' & 4 SX ALL (DAY:17 UMPING 100 RECOVEREI	- CIBP 3801 - 35 SX 900 PART (X	' - 33 SX 6 ' - 35 SX 6 NOME { YEAR 0# SAND & 5 -1/2" CSG -	98'- 500'
PLUGGING PROPO PLUGGING OPERA COMPLETED: ACTUAL PLUGGIN PLUGGING	TD 3801' 4' - SAN IRC 340' DSAL RECEIVED ATIONS ATTENDO HOUR: 14 IG REPORT: ERFS CLC DISP TO	PERFS D TO 335 BY: ED BY AGENT? OO OSED BY P 0 2708' - AND SPOT	3874-78' 0' & 4 SX ALL (DAY:17 UMPING 100 RECOVEREI	- CIBP 3801 - 35 SX 900 PART (X	' - 33 SX 6 ' - 35 SX 6 NOME { YEAR 0# SAND & 5 -1/2" CSG -	98'- 500'
PLUGGING PROPORTION OF THE PULCE PUL	TD 3801' 4' - SAN IRC 340' SAL RECEIVED ATIONS ATTENDE HOUR: 14 IG REPORT: ERFS CLO DISP TO LED CSG M 343' -	PERFS D TO 335 BY: D BY AGENT? OO DSED BY PO 2708' - AND SPOT	3874-78' O' & 4 SX ALL (DAY:17 UMPING 100 RECOVERED PLUGS (- CIBP 3801 - 35 SX 900 PART (X	' - 33 SX 6 ' - 35 SX 6 NOME { YEAR 0# SAND & 5 -1/2" CSG -	98'- 500'
PLUGGING PROPO PLUGGING OPERA COMPLETED: ACTUAL PLUGGIN PLUGGING	TD 3801' 4' - SAN IRC 340' SAL RECEIVED ATIONS ATTENDE HOUR: 14 IG REPORT: ERFS CLO DISP TO LED CSG M 343' -	PERFS D TO 335 BY: D BY AGENT? OO DSED BY PO 2708' - AND SPOT	3874-78' 0' & 4 SX ALL (DAY:17 UMPING 100 RECOVEREI	- CIBP 3801 - 35 SX 900 PART (X	' - 33 SX 6 ' - 35 SX 6 NOME { YEAR 0# SAND & 5 -1/2" CSG -	98'- 500'
PLUGGING PROPO PLUGGING OPERA COMPLETED: ACTUAL PLUGGIN PUL FRO REMARKS:A	TD 3801' 4' - SAN IRC 340' CSAL RECEIVED ATIONS ATTENDO HOUR: 14 IG REPORT: ERFS CLC DISP TO LED CSG M 343' -	PERFS D TO 335 BY: D BY AGENT? OO DSED BY PO 2708' - AND SPOT	3874-78' O' & 4 SX ALL (DAY:17 UMPING 100 RECOVERED PLUGS (- CIBP 3801 - 35 SX 900 PART (X	' - 33 SX 6 ' - 35 SX 6 NOME { YEAR 0# SAND & 5 -1/2" CSG -	98'- 500'
PLUGGING PROPORTION OF THE PULCE PUL	TD 3801' 4' - SAN IRC 340' CSAL RECEIVED ATIONS ATTENDO HOUR: 14 IG REPORT: ERFS CLC DISP TO LED CSG M 343' -	PERFS D TO 335 BY: D BY AGENT? OO DSED BY PO 2708' - AND SPOT	3874-78' O' & 4 SX ALL (DAY:17 UMPING 100 RECOVERED PLUGS (- CIBP 3801 - 35 SX 900 PART (X	' - 33 SX 6 ' - 35 SX 6 NOME { YEAR 0# SAND & 5 -1/2" CSG -	98'- 500'
PLUGGING PROPO PLUGGING OPERA COMPLETED: ACTUAL PLUGGIN PUL FRO REMARKS:A	TD 3801' 4' - SAN IRC 340' CSAL RECEIVED ATIONS ATTENDO HOUR: 14 IG REPORT: ERFS CLC DISP TO LED CSG M 343' -	PERFS D TO 335 BY: D BY AGENT? OO DSED BY PO 2708' - AND SPOT	3874-78' O' & 4 SX ALL (DAY:17 UMPING 100 RECOVERED PLUGS (- CIBP 3801 - 35 SX 900 PART (X	' - 33 SX 6 ' - 35 SX 6 NOME { YEAR 0# SAND & 5 -1/2" CSG -	98'- 500'
PLUGGING PROPO PLUGGING OPERA COMPLETED: ACTUAL PLUGGIN PUL FRO REMARKS:A	TD 3801' 4' - SAN IRC 340' CSAL RECEIVED ATIONS ATTENDO HOUR: 14 IG REPORT: ERFS CLC DISP TO LED CSG M 343' -	PERFS D TO 335 BY: D BY AGENT? OO DSED BY PO 2708' - AND SPOT	3874-78' 0' & 4 SX ALL (DAY:17 UMPING 100 RECOVERED PLUGS (- CIBP 3801 - 35 SX 900 PART (X MONTH: 1 # HULLS, 50 2700' OF 4 9 908' & 590	- 33 - 35 SX 6 -	98'- 500'
PLUGGING PROPO PLUGGING OPERA COMPLETED: ACTUAL PLUGGIN PUL FRO REMARKS:A	TD 3801' 4' - SAN IRC 340' CSAL RECEIVED ATIONS ATTENDO HOUR: 14 IG REPORT: ERFS CLC DISP TO LED CSG M 343' -	PERFS D TO 335 BY: D BY AGENT? OO DSED BY PO 2708' - AND SPOT	3874-78' 0' & 4 SX ALL (DAY:17 UMPING 100 RECOVERED PLUGS (- CIBP 3801 - 35 SX 900 PART (X	' - 33 SX 6 ' - 35 SX 6 NOME { YEAR 0# SAND & 5 -1/2" CSG -	98'- 00' = 1994
PLUGGING PROPO PLUGGING OPERA COMPLETED: ACTUAL PLUGGIN PUL FRO REMARKS:A	TD 3801' 4' - SAN IRC 340' CSAL RECEIVED ATIONS ATTENDO HOUR: 14 IG REPORT: ERFS CLC DISP TO LED CSG M 343' -	PERFS D TO 335 BY: D BY AGENT? OO DSED BY PO 2708' - AND SPOT	3874-78' 0' & 4 SX ALL (DAY:17 UMPING 100 RECOVERED PLUGS (- CIBP 3801 - 35 SX 900 PART (X MONTH: 1 # HULLS, 50 2700' OF 4 9 908' & 590	- 33 - 35 SX 6 -	98'- 500'

DW

Re: Landowner Corp

11-17