ı 040023	12-9-87
TO: STATE CORPORATION COMMISSION	API NUMBER 15-007-21,399-0000
CONSERVATION DIVISION - PLUGGING SECTION 200 COLORADO DERBY BUILDING	NE SW SE, SEC. 12, T 32 S, R 14 W/E
ICHITA, KANSAS 67202	990 feet from S section line
TECHNICIAN'S PLUGGING REPORT	1650 feet from E section line
Operator License / 5050	Lease Name Brook Well # 1
Operator: Hummon Corporation	County Barber 149.08
Address 400 One Main Place	Well Total Depth 4587 feet
Wichita, KS 67202	Conductor Pipe: Sizefeet
	Surface Casing: \$ize <u>8 5/8</u> feet 308
Abandoned Oll Well X Gas Well	_ Input Weil D&A
Other well as hereinafter indicated	
Plugging Contractor Elmo Morgenstern - Cl	arke Corporation License Number 5105
Address 107 West Fowler, Medicine Lodge,	KS 67104
	9 Month: 12 Year:19 87
Piwaalna proposal received from Elmo Mor	genstern
Flugging proposal received from Elmo Mor	
(company name) Clarke Corporation	(phone)316-886-5665
(company name) Clarke Corporation	(phone)316-886-5665 4525-27, 4533-35, 4496-99, 4285-86' Elevation 18
(company name) Clarke Corporation  were: 4½" at 4587' PRTD 4547' Perfs at  lst plug sand back to 4230' and dump 4 sx	(phone)316-886-5665 4525-27, 4533-35, 4496-99, 4285-86 Elevation 18 cement on top of sand through bailer,
(company name) Clarke Corporation	(phone)316-886-5665 4525-27, 4533-35, 4496-99, 4285-86 Elevation 18 cement on top of sand through bailer,
(company name) Clarke Corporation  were: 4½" at 4587' PRTD 4547' Perfs at  lst plug sand back to 4230' and dump 4 sx	(phone)316-886-5665 4525-27, 4533-35, 4496-99, 4285-86 Elevation 18 cement on top of sand through bailer,
(company name) Clarke Corporation  were: 4½" at 4587' PRTD 4547' Perfs at  lst plug sand back to 4230' and dump 4 sx	(phone)316-886-5665 4525-27, 4533-35, 4496-99, 4285-86' Elevation 18 cement on top of sand through bailer, ite cement.
(company name) Clarke Corporation  were: 4½" at 4587' PRTD 4547' Perfs at  1st plug sand back to 4230' and dump 4 sx  2nd plug pump 5 sx hulls and 125 sx Econol	(phone)316-886-5665  4525-27, 4533-35, 4496-99, 4285-86' Elevation 18 cement on top of sand through bailer, ite cement.  OSBI Received by Richard Lacey
Clarke Corporation  Were: 4½" at 4587' PRTD 4547' Perfs at  1st plug sand back to 4230' and dump 4 sx  2nd plug pump 5 sx hulls and 125 sx Econol  Plugging Prop	(phone)316-886-5665  4525-27, 4533-35, 4496-99, 4285-86' Elevation 18 cement on top of sand through bailer, ite cement.  OSAI Received by Richard Lacey (TECHNICIAN)
Clarke Corporation  Were: 4½" at 4587' PRTD 4547' Perfs at  1st plug sand back to 4230' and dump 4 sx  2nd plug pump 5 sx hulls and 125 sx Econol  Plugging Properties attended by Agent?: A	(phone)316-886-5665  4525-27, 4533-35, 4496-99, 4285-86 Elevation 18 cement on top of sand through bailer, ite cement.  osal Received by Richard Lacey (TECHNICIAN)  I! X Part None
Clarke Corporation  Were: 4%" at 4587' PBTD 4547' Perfs at  Ist plug sand back to 4230' and dump 4 sx  2nd plug pump 5 sx hulls and 125 sx Econol  Plugging Propertions attended by Agent?: A  Operations Completed: Hour: 11:30 a.mQay:	(phone)316-886-5665  4525-27, 4533-35, 4496-99, 4285-86' Elevation 18 cement on top of sand through bailer, ite cement.  osal Received by Richard Lacey (TECHNICIAN)  It
Clarke Corporation  Were: 4%" at 4587' PBTD 4547' Perfs at  Ist plug sand back to 4230' and dump 4 sx  2nd plug pump 5 sx hulls and 125 sx Econol  Plugging Propertions attended by Agent?: A  Operations Completed: Hour: 11:30 a.mQay:	(phone)316-886-5665  4525-27, 4533-35, 4496-99, 4285-86 Elevation 18 cement on top of sand through bailer, ite cement.  osal Received by Richard Lacey (TECHNICIAN)  I! X Part None
Clarke Corporation  Gere: 45" at 4587' PBTD 4547' Perfs at 1st plug sand back to 4230' and dump 4 sx 2nd plug pump 5 sx hulls and 125 sx Econol Plugging Operations attended by Agent?: A Operations Completed: Hour: 11:30 a.mDay: ACTUAL PLUGGING REPORT 1st plug sanded back sand with dump bailer,	(phone)316-886-5665  4525-27, 4533-35, 4496-99, 4285-86' Elevation 18 cement on top of sand through bailer,  ite cement.  osa! Received by Richard Lacey (TECHNICIAN)  I!
Clarke Corporation  Were: 4½" at 4587' PRTD 4547' Perfs at  Ist plug sand back to 4230' and dump 4 sx  2nd plug pump 5 sx hulls and 125 sx Econol  Plugging Operations attended by Agent?: A  Operations Completed: Hour: 11:30 a.mDay:  ACTUAL PLUGGING REPORT 1st plug sanded ba	(phone)316-886-5665  4525-27, 4533-35, 4496-99, 4285-86' Elevation 18 cement on top of sand through bailer,  ite cement.  Osal Received by Richard Lacey (TECHNICIAN)  I!
Clarke Corporation  Gere: 45" at 4587' PBTD 4547' Perfs at 1st plug sand back to 4230' and dump 4 sx 2nd plug pump 5 sx hulls and 125 sx Econol Plugging Operations attended by Agent?: A Operations Completed: Hour: 11:30 a.mDay: ACTUAL PLUGGING REPORT 1st plug sanded back sand with dump bailer,	(phone)316-886-5665  4525-27, 4533-35, 4496-99, 4285-86' Elevation 18 cement on top of sand through bailer,  ite cement.  Osal Received by Richard Lacey (TECHNICIAN)  I!
Clarke Corporation  Were: 4½" at 4587' PRTD 4547' Perfs at  Ist plug sand back to 4230' and dump 4 sx  2nd plug pump 5 sx hulls and 125 sx Econol  Plugging Operations attended by Agent?: A  Operations Completed: Hour: 11:30 a.mDay:  ACTUAL PLUGGING REPORT 1st plug sanded ba  of sand with dump bailer,  2nd plug pumped down 8 5/8" surface casing	(phone)316-886-5665  4525-27, 4533-35, 4496-99, 4285-86' Elevation 18 cement on top of sand through bailer,  ite cement.  Osal Received by Richard Lacey (TECHNICIAN)  I! X Part None  9 Month: 12 Year:19 87  ck from 4547-4230' and put 4 sx cement on top  with 500 lbs. hulls and 100 sx cement.
Clarke Corporation  Were: 4½" at 4587' PRTD 4547' Perfs at  Ist plug sand back to 4230' and dump 4 sx  2nd plug pump 5 sx hulls and 125 sx Econol  Plugging Operations attended by Agent?: A  Operations Completed: Hour: 11:30 a.mDay:  ACTUAL PLUGGING REPORT 1st plug sanded ba  of sand with dump bailer,  2nd plug pumped down 8 5/8" surface casing	(phone)316-886-5665  4525-27, 4533-35, 4496-99, 4285-86' Elevation 18 cement on top of sand through bailer,  ite cement.  Osal Received by Richard Lacey (TECHNICIAN)  I!
Clarke Corporation  Were: 4½" at 4587' PRTD 4547' Perfs at  Ist plug sand back to 4230' and dump 4 sx  2nd plug pump 5 sx hulls and 125 sx Econol  Plugging Operations attended by Agent?: A  Operations Completed: Hour: 11:30 a.mDay:  ACTUAL PLUGGING REPORT 1st plug sanded ba  of sand with dump bailer,  2nd plug pumped down 8 5/8" surface casing	(phone)316-886-5665  4525-27, 4533-35, 4496-99, 4285-86' Elevation 18 cement on top of sand through bailer,  ite cement.  Richard Lacey (TECHNICIAN)  I!

DATE 12-15-87

Signed A tophician feefer

FORM CP-2/3 Rev.01-84