

CP1

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
800 BETTING BUILDING
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM
File One Copy

Lease Owner Rocket Drilling Company, Inc. Address 352 North Broadway
(Applicant) Wichita, Kansas

Lease (Farm Name) Larned Townsite Unit 10 Well No. 1

Well Location Approx. C N/2 S/2 SW Sec. 33 Twp. 21S Rge. 16W (E)-(W)

County Pawnee Field Name (if any) Larned

Total Depth 3889 Oil Gas Dry Hole X

Was well log filed with application? Yes . If not, explain:

(See attached)

Date and hour plugging is desired to begin as soon as approved

Plugging of the well will be done in accordance with the Rules and Regulations
of the State Corporation Commission, or with the approval of the following
exceptions: Explain fully and exceptions desired.

(Use an additional sheet if necessary)

Name of the person on the lease in charge of well for owner Mr. Buck Wilson
3819 W. 10th RR #1
Address Great Bend, Kansas

Name of Plugging Contractor unknown at this time

Address "

Invoice covering assessment for plugging this well should be sent to
352 North Broadway
Rocket Drilling Company, Inc. Address Wichita, Kansas

and payment will be guaranteed by applicant.

RECEIVED
08-04-56

L.H. Myrick
Applicant or Acting Agent

Date 8-3-56

PLUGGING
FILE SEC 33 T 21 R 16W
BOOK PAGE 86 LINE 39



STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
211 NORTH BROADWAY
WICHITA, KANSAS

August 6, 1956

Well No. 1
Lease Larned TWST Unit # 10
Description CN/2 S/2 SW 33-21-16W
County Pawnee
File No. 86-39

Rocket Drilling Company, Inc.
352 North Broadway
Wichita, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. R. H. Brundage, Box 283, Holsington, Kansas.

STATE CORPORATION COMMISSION
CONSERVATION DIVISION

By

S. S. Greider

S. S. Greider
WELL PLUGGING SUPERVISOR

cc:
District Plugging Supervisor