
CARD MUST BE TYPED

TO DRILL NOTICE (see rules on reverse side)




| Storting Date: Jan | nuary 9 | 1985 | API Number 15- 165-21282 - |
|--|--------------|-----------------|--|
| Statting Date. | month da | у уеаг | 100' S of C ☐ East |
| OPERATOR: License #5293 Name Helmerich & Payne, Inc. | | | . E/2, .SW. SW. Sec .24 . Twp .19 . S, Rge 16 X West |
| Address P.O. Box 558 | | | *560 Ft North from Southeast Corner of Section |
| City/State/Zip Garden City, KS 67846 Contact Person Millard L. Lindsay | | | |
| Phone 316-276-3693 | | | Nearest lease or unit boundary line560 feet. |
| CONTRACTOR: License # | | | |
| | | | County Rush |
| Name Mustang Drlg | | | Lease Name |
| City/State Great Bend, Kansas | | | Domestic well within 330 feet : yes 🔯 no |
| Well Drilled For: | Well Class: | Type Equipment: | Municipal well within one mile : 🔲 yes 🐰 no |
| 🔀 Oil 🔲 Swd | ■ Infield | X] Mud Rotary | |
| | [X Pool Ext. | ☐ Air Rotary | Depth to Bottom of fresh waterDakota225 feet |
| OWWO Expl | | Cable | Lowest usable water formation |
| If OWWO: old weil info as follows: | | | Depth to Bottom of usable water |
| Operator | | | Surface pipe by Alternate: 1 [X 2] |
| Weli Name | | | Surface pipe to be setAnhydrite 1100 feet |
| | | | Conductor pipe if any required |
| Comp Date | | | Ground surface elevation |
| Projected Total Depth Feet Projected Formation at TD Arbuckle | | | This Authorization Expires |
| Projected Formation at TD | | | This Authorization Expires |
| Expected Producing Formations Arbuckle | | | Approved By/-3-3-5 |
| I certify that we will comply with K.S.A. 55-101, et seq., plus eventually plugging hole to K.C.C. specifications. 1445. 660 FSL | | | |
| Date .1-8-85 Signature of Operator or Agent Willam 22mm, Title Dist. Prod. Manager | | | |

CORRECTED _ MOYED 100' SOUTH

Must be filed with the K.C.C. five (5) days prior to commencing well This card void if drilling not started within six (6) months of date received by K.C.C.

A Regular Section of Land 1 Mile = 5.280 Ft.



Important procedures to follow:

- 1. Notify District office before setting surface casing.
- 2. Set surface casing by circulating cement to the top.
- 3. File completion forms ACO-1 with K.C.C. within 90 days of well completion, following instructions on ACO-1, side 1, and including copies of wireline logs.
- 4. Notify District office 48 hours prior to old well workover or re-entry.
- 5. Prior to plugging, prepare a plugging plan, then obtain agreement from the appropriate district office for an approved plugging plan.
- 6. Submit plugging report (CP-4) to K.C.C. after plugging is completed.
- 7. Obtain an approved injection docket number before disposing of salt water.
- 8. Notify K.C.C. within 10 days when injection commences or terminates.
- 9. If an alternate 2 completion, cement in the production pipe from below any usable water to surface within 120 days of spud date.

1-9-85 JAN 09 1985

Conservation Division 200 Colorado Derby Building Wichita, Kansas 67202 (316) 263-3238