

CP

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
211 NORTH BROADWAY
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM
File One Copy

Lease Owner Aylward Drilling Company Address 813 1st. Natl. Bank Bldg., Wichita
(Applicant)

Lease (Farm Name) Lake "B" Well No. 1

Well Location SE SE SE Sec. 11 Twp. 31 Rge. 14 (~~EX~~) - (W)

County Barber Field Name (if any) _____

Total Depth 4611 Oil Gas Dry Hole Dry Hole

Was well log filed with application? No If not, explain: _____

To accompany plugging record.

Date and hour plugging is desired to begin April 3, 1956

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission.

Name of the person on the lease in charge of well for owner _____

John Parsons Address Medicine Lodge, Kansas

Plugging Contractor Aylward Drilling Company

Plugging Contractor's License No. _____

Invoice covering assessment for plugging this well should be sent to _____

Aylward Drilling Company Address 813 1st. Natl. Bank Bldg., Wichita

and payment will be guaranteed by applicant.

RECEIVED
STATE CORPORATION COMMISSION

Paul W. Hesse
Applicant or Acting Agent

APR 5 - 1956
4-5-56
CONSERVATION DIVISION
Wichita, Kansas

Date Apr. 4, 1956

PLUGGING
FILE SEC 11
BOOK PAGE 51 LINE 18

PLUGGING
FILE SEC 11 T 31 R 14W
BOOK PAGE 51 LINE 18

15-007-00756-0000



STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
211 NORTH BROADWAY
WICHITA, KANSAS

April 5, 1956

Well No.	1
Lease	Lake #30
Description	SE SE SE 11-31-11W
County	Barber
File No.	51-18

Aylward Drilling Company
813 First National Bank Bldg.
Wichita, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. H. A. Rives, Box 8, Pratt, Kansas.

STATE CORPORATION COMMISSION
CONSERVATION DIVISION

By S. S. Greider
S. S. Greider
WELL PLUGGING SUPERVISOR

cc:
District Plugging Supervisor