

DATE 9-8-99

New Situation  
 Response to Request  
 Follow-up

OPERATOR American Warrior #4058

NAME 3118 Cummings. P.O. Box 799 LOCATION 1701 FUL 1533 FEL SEC 26, T 18 S. R. 21 <sup>1701 FUL</sup> <sub>W</sub>

& ADDRESS Garden City, KS 67846 LEASE Wells Well # 1-26

PHONE NO. \_\_\_\_\_ COUNTY Ness  
OPER. 316-275-9231 OTHER \_\_\_\_\_

REASON FOR INVESTIGATION: To witness Alternate II cementing bond log

LEASE INSPECTION

PROBLEM: Cement did not circulate on original cementing job

PERSON(S) CONTACTED: \_\_\_\_\_

FINDINGS: Well has 227' of 8 9/8" surface pipe  
~~set~~ Set cement retainer @ 768' perforated  
@ 800' perforated @ 380' Both sets of perfs  
cemented. Bond Log shows good cement from  
850' to 362 and 227' to 0'

COMPLAINT

photos taken: \_\_\_\_\_  
ACTION/RECOMMENDATIONS: Cement should be sufficient to protect fresh & usable water

FIELD REPORT

Retain 1 copy Joint District Office  
Send 1 copy Conservation Division

RECEIVED Richard W. Tracy  
STATE BOARD OF CONSERVATION

SEP 21 1999

CONSERVATION DIVISION  
Wichita, Kansas