KCC OIL/GAS REGULATORY OFFICE

DATE 12/19/96	[X] New Situation	
OPERATOR American Warrior, Inc. #4058	[] Response to Requ - 100' NW of	uest
NAME P.O. Box 399	LOCATION SE SW NE , SEC 25, T 19 S P 22	XEX ₩
& Garden City, KS 67846	LEASE Borger Well # 3	
PHONE NO. OPER. 913-398-2270 OTHER	COUNTY Ness [API#15-135-23,969-0600]	-
REASON FOR INVESTIGATION: Alternate II cement	-	
		INSPECTION
		PBC
PROBLEM:		
		LEASE
		<u> </u>
PERSON(S) CONTACTED: Scott Corsair		
FINDINGS: 5½" casing set at 4374	• .	···
7 7/8" hole - 4386'		
2 3/8" tubing		INT
Port collar at 1487		COMPLAINT
Cemented with 155 sx Midcon II ¼# f	floseal.	11
Cementing done by Halliburton.		
15 bbl. cement circulated.		
Began at 1 p.m., finished 2:30 p.m.		** ** ********************************
	(i) :	
•	photos taken:	
ACTION/RECOMMENDATIONS: Alternate II cement		REPORT
		1 !
		x
Retain 1 conv. Joint District Occ.		Da
Retain 1 copy Joint District Office Send 1 copy Conservation Division	ByMichael Maier	AST.
	. 12/19/90	