

Conservation Division Finney State Office Building 130 S. Market, Rm. 2078 Wichita, KS 67202-3802



Phone: 316-337-6200 Fax: 316-337-6211 http://kcc.ks.gov/

Sam Brownback, Governor

Mark Sievers, Chairman Thomas E. Wright, Commissioner Shari Feist Albrecht, Commissioner

October 29, 2013

Hutchinson Oil Co. PO Box 521 Derby, KS 67037

Re: Hunley 1-20

NE/4 Sec. 20-22S-11W Stafford County, Kansas 15-185-23761-00-00

Dear Sir or Madam:

This letter is to inform you that you have been granted a 90 day extension of time in which to close the drilling pits associated with the Hunley 1-20 well.

The original 365 days for closure expired on 09/13/2013. This extension will expire on 01/29/2014. Conditions should have existed within this time frame to allow closure of this drill pit. **No additional extensions will be granted**.

In the event there is water standing in these pits, please dewater and dispose of fluids in an authorized disposal facility to expedite closure. Extension of this time frame automatically extends the time period for filing the closure of surface pit form.

Failure to close the pit prior to the expiration date shall result in a monetary penalty in accordance with K.A.R. 82-3-602(a).

Please complete the pit closure form (CDP-4) through Kolar (Kansas On-Line Automated Reporting) at https://kolar.kgs.ku.edu.

If you have any questions in this regard, please do not hesitate to contact Kathy Haynes at (316) 337-6243.

Sincerely,

Ryan A. Hoffman

Director

Cc:

File District

Rojan a Hoffman

Hutchinson Oil Co.

Wm. S. Hutchinson P.O. Box 521 Derby, Kansas 67037 Telephone 316-788-5440 Fax 316-788-3384

October 4th 2013

Kansas Corporation Commission Conservation Division 130 So. Market-Rm#2078 Wichita, KS 67202-3802 RE: Hunley #1-20 NE/4 Sec.20-22S-11W, Stafford Co., KS API#15-185-23761-00-00

Corporation Commission:

Due to a very wet summer the completion of backfilling the **Hunley #1-20** reserve pit has been delayed.

Our reserve pit is only 40% backfilled. Langfeld Dirt Service out of Ellinwood, Kansas backfilled the working pits and our fresh water pit in January, 2013 and on the 30th of April, 2013 crowded the reserve pit.

Hutchinson Oil Co. has been in contact with the fee owner and the tenant on the delay. Cattle are currently in the pasture and Hutchinson Oil Co. has put an electric fence charger with a solar panel completely around the portion that has not been backfilled.

Hutchinson Oil Co. would like to request an extension so that the pit can thoroughly dry out before backfilling. Hutchinson Oil Co. will continue to crowd the pit to expedite the process.

William S. Hutchinson

OCT 25 2013
RECEIVED