## NOTICE OF INTENTION TO DRILL

(see rules on reverse side)

-00-01

DWWO

Expected Spud DateDecember 29, 1987				API Number 15— 007-21868
month day year  OPERATOR: License # .03378				NE NE SW Sec. 34. Twp. 32. s, Rg. 12. X West
Name Sage Oil Company Address P.O. Box 19588				2,180 Ft. from South Line of Section 2,930 Ft. from East Line of Section
City/State/Zip Oklahoma City, OK 73159				
				(Note: Locate well on Section Plat on reverse side)
Contact Person Wayne M. Smith				Nearest lease or unit boundary line460 feet
Phone (405) 709-0498 949-0490				CountyBarber
CONTRACTOR: License # . Pending 36.75				Lease Name Randels Well # .l
Name Woodward Well Service				Ground surface elevation
City/State_Woodward/Oklahoma				Domestic well within 330 feet:yes _X no
Well Drilled For: Well Class: Type Equipment:				Municipal well within one mile:yesX no
Oil	Storage	X Infield	X Mud Rotary	Depth to bottom of fresh water
Gas	Inj '	Pool Ext.	Air Rotary	Depth to bottom of usable water
<u>X</u> owwo	Expl	Wildcat	Cable	Surface pipe by Alternate: 1 2 Surface pipe \$\frac{1}{2} \frac{2}{2} \frac{1}{2} \frac{2}{2} \frac{1}{2} \fr
If OWWO: old well info as follows:				Surface pipe Alan New York set . at . 29.5
Operator Donald. J., Malone. (op. #8890.)				Conductor pipe required
Well Name Randels. #1				Projected Total Depth3700feet
Comp Date . 7. / . 19. / 84 Old Total Depth 4 880				FormationElgin
I certify that well Date12/16/	l will comply v /87 Sign:	with K.S.A. 55-10 ature of Operato	01, et seq., plus eventus er or Agent	ally plugging hole to KCC specifications.  M. Sure Title President
For KCC Use: Conductor Pipe I This Authorization	Required	7-218	Minimum Surface Pi	pe Required

Must be filed with the K.C.C. five (5) days prior to commencing well This card void if drilling not started within six (6) months of date received by K.C.C.

Important procedures to follow:

- I. Notify District office before setting surface casing.
- 2. Set surface casing by circulating cement to the top.
- 3. File completion forms ACO-1 with K.C.C. within 120 days of well spud date, following instructions on ACO-1, side 1, and including copies of wireline logs.
- 4. Notify District office 48 hours prior to old well workover or re-entry.
- 5. Prior to filing Intent, prepare a proposed plugging plan in case well is D & A, then obtain approval of plan when calling district office prior to setting surface pipe.
- 6. Submit plugging report (CP-4) to K.C.C. after plugging is completed.
- 7. Obtain an approved injection docket number before disposing of salt water.
- 8. Notify K.C.C. within 10 days when injection commences or termi-

RIATE - PARTE

9. If an alternate 2 completion, cement in the production pipe from below any usable water to surface within 120 days of spud date.

DEC 4 - 1987 CONSCIEVATION DIVISION Wichita, Kansas

State Corporation Commission of Kansas Conservation Division 200 Colorado Derby Building Wichita, Kansas 67202-1212 (316) 263-3238

A Regular Section of Land 1 Mile = 5.280 Ft.

