## NOTICE OF INTENTION TO DRILL

(see rules on reverse side) API Number 15- 007-22, 143-00-00 11/05/86 Starting Date ..... S<sup>1</sup><sub>2</sub> NW<sup>1</sup><sub>4</sub> SE<sup>1</sup><sub>4</sub> Sec. 6 Twp. 32 S. Rg 12 X West OPERATOR: License # 5020 1650 Ft. Ft. from South Line of Section Name Rine Exploration Company 1980 Ft. Ft. from East Line of Section Address Suite #545, 300 W. Douglas City/State/Zip ... Wichita, KS 67202 (Note: Locate well on Section Plat on reverse side) Contact Person. M. Bradford Rine Barber County...Barber

Clarke Well # 2-6 Phone 316/262-5418 CONTRACTOR: License # 6033 Ground surface elevation 1505 est. . . . . . . . . feet MSL Name ..... Murfin Drilling Company .... City/State.....Wichita, KS 67202..... Domestic well within 330 feet: Municipal well within one mile: \_\_\_yes  $\underline{x}$  no Depth to bottom of fresh water. 50 Ft. \_\_\_\_ Well Drilled For: Well Class: Type Equipment: \_\_ Oil \_\_ SWD \_\_ Infield X Mud Rotary Depth to bottom of usable water 200 Ft. X Gas Ini X Pool Ext. \_\_\_ Air Rotary Surface pipe by Alternate: \_\_\_ Cable \_\_\_ owwo \_\_\_ Expl \_\_\_ Wildcat Surface pipe planned to be set ....310 Ft. If OWWO: old well info as follows: Conductor pipe required ..... Operator ..... Well Name Formation Mississippian Comp Date ..... Old Total Depth..... I certify that well will comply with K.S.A. 55-101, et seq., plus eventually, plugging hole to KCC specifications. Date ... 10/02/86 ... Signature of Operator or Agent M. Bradford Rine ... Title President / Geologist 

Must be filed with the K.C.C. five (5) days prior to commencing well This card void if drilling not started within six (6) months of date received by K.C.C.


## Important procedures to follow:

- 1. Notify District office before setting surface casing.
- 2. Set surface casing by circulating cement to the top.
- 3. File completion forms ACO-1 with K.C.C. within 90 days of well completion, following instructions on ACO-1, side 1, and including copies of wireline logs.
- 4. Notify District office 48 hours prior to old well workover or re-entry.
- 5. Prior to filing Intent, prepare a proposed plugging plan in case well is D & A, then obtain approval of plan when calling district office prior to setting surface pipe.
- 6. Submit plugging report (CP-4) to K.C.C. after plugging is completed.
- 7. Obtain an approved injection docket number before disposing of salt

VED vater. FRE CORPORATION COMMESION tify K.C.C. within 10 days when injection commences or termi-330CONS. DIV. WICHITA, KS nates.

> 9. If an alternate 2 completion, cement in the production pipe from below any usable water to surface within 120 days of spud date.

A Regular Section of Land 1 Mile = 5.280 Ft.



6 1986 OCT

State Corporation Commission of Kansas Conservation Division 200 Colorado Derby Building Wichita, Kansas 67202 (316) 263-3238