	ADO DERBY BUILDING		s, R11 (W)
	KANSAS 67202	App. 4695 feet from	
	N'S PLUGGING REPORT	App. 3225 feet from	
	30128	Lease Name Hrencher Ne	
Operator: Name& Address	Kenneth S. White 200 E. 1st, Suite 210	CountyBarber	119.66
		Well Total Depth	3682 fee
	Wichita, KS 67202	Conductor Pipe: Size	fest
	4	Surface Casing: Size8 5/8	
benobned/	OII Well X Gas Well_	Input WellSWD Well	D&A
	t as hereinafter indicated		
lugging	Contractor Kelso Casing Pulling,	Inc. License Numb	er 6050
ddress	P.O. Box 347, Chase, KS 67524		
ompany t	o plug at: Hour: 10 a.m. Day:	30 Month: 3	92
	proposal received from Vernon Du		
	Name) Kelso Casing Pulling, Inc.		•316-938-2943
			,
ere: 5%	" at 3682' w/100 sy cement PRTD	3627 5! Porfo ht 2611 10!	•
	u at 3682 w/100 sx cement, PBTD pump 25 sx cement at 3550.	3627.5', Perfs at 3611-18'	·
st plug	pump 25 sx cement at 3550',		1 0.5/01
st plug	pump 25 sx cement at 3550', pump 3 sx hulls, 10 sx gel, 50 sx		lease 8 5/8"
lst plug	pump 25 sx cement at 3550',		lease 8 5/8"
st plug	pump 25 sx cement at 3550', pump 3 sx hulls, 10 sx gel, 50 sx g and pump 100 sx cement.	cement, 10 sx gel, 1 sx hulls, re	
st plug	pump 25 sx cement at 3550', pump 3 sx hulls, 10 sx gel, 50 sx g and pump 100 sx cement.	cement, 10 sx gel, 1 sx hulls, re	Lacey
st plug	pump 25 sx cement at 3550', pump 3 sx hulls, 10 sx gel, 50 sx g and pump 100 sx cement.	cement, 10 sx gel, 1 sx hulls, re osal Received by Richard (TECHN	Lacey ICIAN)
st plug : And plug priper plug	pump 25 sx cement at 3550', pump 3 sx hulls, 10 sx gel, 50 sx g and pump 100 sx cement. Plugging Prop	cement, 10 sx gel, 1 sx hulls, re osal Received by Richard (TECHN	Lacey ICIAN)
end plug priper plug	pump 25 sx cement at 3550', pump 3 sx hulls, 10 sx gel, 50 sx g and pump 100 sx cement. Plugging Prop Operations attended by Agent?: A s Completed: Hour: 11:50 a.mDay:	cement, 10 sx gel, 1 sx hulls, recoment, 10 sx gel, 1 sx hulls, recomend of the state of the sta	Lacey ICIAN) ne
end plug priper plug	pump 25 sx cement at 3550', pump 3 sx hulls, 10 sx gel, 50 sx g and pump 100 sx cement. Plugging Prop Operations attended by Agent?: A s Completed: Hour: 11:50 a.mDay: UGGING REPORT 1st plug pumped dow	cement, 10 sx gel, 1 sx hulls, recoment, 10 sx gel, 1 sx hulls, recomend of the state of the sta	Lacey ICIAN) ne
end plug priper plug lugging (perations CTUAL PLU	pump 25 sx cement at 3550', pump 3 sx hulls, 10 sx gel, 50 sx g and pump 100 sx cement. Plugging Prop Operations attended by Agent?: A s Completed: Hour: 11:50 a.mDay: UGGING REPORT lst plug pumped dow 550',	cement, 10 sx gel, 1 sx hulls, received by Richard (TECHN II Y Part Not 30	Lacey ICIAN) Ber:19 92 ment, stopped
end plug priper plug iugging (perations CTUAL PLU lug at 35 nd plug p	pump 25 sx cement at 3550', pump 3 sx hulls, 10 sx gel, 50 sx g and pump 100 sx cement. Plugging Prop Operations attended by Agent?: A s Completed: Hour: 11:50 a.mDay: UGGING REPORT 1st plug pumped dow 550', pumped down 8 5/8" with 300 lbs. h	cement, 10 sx gel, 1 sx hulls, received by Richard (TECHN I!	Lacey ICIAN) Ber:19 92 ment, stopped
Ind plug priper plug Iugging (perations CTUAL PLU lug at 35 nd plug pulls, rel	pump 25 sx cement at 3550', pump 3 sx hulls, 10 sx gel, 50 sx g and pump 100 sx cement. Plugging Prop Operations attended by Agent?: A s Completed: Hour: 11:50 a.mDay: UGGING REPORT 1st plug pumped dow 550', pumped down 8 5/8" with 300 1bs. h Leased 8 5/8" wiper plug and pumped	cement, 10 sx gel, 1 sx hulls, re cement, 10 sx gel, 1 sx hulls, re Richard (TECHN I!	Lacey ICIAN) Ber:19 92 ment, stopped
lugging (perations CTUAL PLI lug at 35 nd plug p	pump 25 sx cement at 3550', pump 3 sx hulls, 10 sx gel, 50 sx g and pump 100 sx cement. Plugging Prop Operations attended by Agent?: A s Completed: Hour: 11:50 a.mDay: UGGING REPORT 1st plug pumped dow 550', pumped down 8 5/8" with 300 lbs. h	cement, 10 sx gel, 1 sx hulls, re cement, 10 sx gel, 1 sx hulls, re Richard (TECHN I!	Lacey ICIAN) Ber:19 92 ment, stopped
Ind plug priper plug Iugging (perations CTUAL PLU lug at 35 nd plug pulls, rel aximim pr	pump 25 sx cement at 3550', pump 3 sx hulls, 10 sx gel, 50 sx g and pump 100 sx cement. Plugging Prop Departions attended by Agent?: A s Completed: Hour: 11:50 a.mDay: UGGING REPORT 1st plug pumped down 550', Dumped down 8 5/8" with 300 lbs. h Leased 8 5/8" wiper plug and pumped Tessure 550 psi and shut in 500 psi	cement, 10 sx gel, 1 sx hulls, re osal Received by Richard (TECHN I! x Part Not 30 Month: 3 y n 5½" casing with 50 sx common cer ulls, 10 sx gel, 50 sx cement, 10 d 100 sx cement. i 3	Lacey ICIAN) Ber:19 92 ment, stopped
Ind plug priper plug Iugging (perations CTUAL PLU lug at 35 nd plug pulls, rel aximim pr	pump 25 sx cement at 3550', pump 3 sx hulls, 10 sx gel, 50 sx g and pump 100 sx cement. Plugging Prop Operations attended by Agent?: A s Completed: Hour: 11:50 a.mDay: JGGING REPORT 1st plug pumped dow 550', Dumped down 8 5/8" with 300 lbs. h Leased 8 5/8" wiper plug and pumper Cessure 550 psi and shut in 500 psi Jsed 60/40 Pozmix 6% gel by B.J. So	cement, 10 sx gel, 1 sx hulls, received by Richard (TECHN I! y Part No. 30	Lacey ICIAN) Ber: 19 92 ment, stopped Sx gel, 100 1bs
Ind plug priper plug Iugging (perations CTUAL PLU lug at 35 nd plug pulls, rel aximim pr	pump 25 sx cement at 3550', pump 3 sx hulls, 10 sx gel, 50 sx g and pump 100 sx cement. Plugging Prop Operations attended by Agent?: A s Completed: Hour: 11:50 a.mDay: JGGING REPORT 1st plug pumped dow 550', Dumped down 8 5/8" with 300 lbs. h Leased 8 5/8" wiper plug and pumper Cessure 550 psi and shut in 500 psi Jsed 60/40 Pozmix 6% gel by B.J. So	cement, 10 sx gel, 1 sx hulls, re osal Received by Richard (TECHN I! x Part Not 30 Month: 3 y n 5½" casing with 50 sx common cer ulls, 10 sx gel, 50 sx cement, 10 d 100 sx cement. i 3	Lacey ICIAN) Ber: 19 92 ment, stopped Sx gel, 100 lbs