CONSERVATION COLORAGE		ALI HOMBEN 13-	077-21,009 <b>-00 00</b>
	ORATION COMMISSION ON DIVISION - PLUGGING SECTION		, 7 <u>34</u> s, R <u>6</u>
200 COLORADO DERBY BUILDING WICHITA, KANSAS 67202		1650 to	et from N/Osection line
TECHNICIAN	'S PLUGGING REPORT		et from WE section line
Operator L	icense #5630		Well # 1
Operator: _	Brandt Production Co.	County	Harper
Name& Address _	1200 . Douglas Bldg	Well Total Depth	5285 /7/. 74 teet
	104 S. Broadway		efeet
_	Wichita, Ks. 67202		
Abandoned (	Oll WellGas Well	input WeliSW	D Well D&A XX
Other well	as hereinafter indicated		
	ontractor Brandt Drilling Co.	'	
	1200 Douglas Building, W	•	<del> </del>
	plug at: Hour: 7:00a.m. Day:		
	roposal received from		
	Me) K.C.C., Salina, K		·· —· —·
were:	35 sacks at 3700'; 35 sacks a	at 950'; 35 sacks at 320';	10 in rat
10 in 1	mouse		
	RECEIVED		
STATE	CORPORATION COMMISSION		
	JUI 27 1984		
			· · · · · · · · · · · · · · · · · · ·
	The state of the s	oposal Received by Tom	
	Wichita, Kansas	<u></u>	(TECHNICIAN)
CO	Wichita, Kansas perations attended by Agent?:	AllPart	(TECHNICIAN) None_XX
Cor Plugging Op Operations	Wichita, Kansas  perations attended by Agent?:  Completed: Hour: 6:00a.m.Day	AllPart	(TECHNICIAN)  NолеXX  Year:1984
COPPLUTE OF COPPLU	Wichita, Kansas  perations attended by Agent?:  Completed: Hour: 6:00a.m.Day  GGING REPORT Filled hole	AllPart	Year:19 84
COPPLUTE OF COPPLU	Wichita, Kansas  perations attended by Agent?:  Completed: Hour: 6:00a.m.Day  GGING REPORT Filled hole  as cement through drill pipe;	AllPart	(TECHNICIAN)  None XX  Year: 19 84  Pips to 3700'; spotted  spotted 35 sacks
Plugging Operations ACTUAL PLUG 35 sack cement	Wichita, Kansas  perations attended by Agent?:  Completed: Hour: 6:00a.m.Day  GGING REPORT Filled hole  as cement through drill pipe;  through drill pipe; pulled dr	AllPart	Year:19 84  Pips to 3700'; spotted  spotted 35 sacks  35 sacks cement through
Plugging Operations ACTUAL PLUG 35 sack cement drill p	Wichita, Kansas  perations attended by Agent?:  Completed: Hour: 6:00a.m.Day  GGING REPORT Filled hole  as cement through drill pipe;  through drill pipe; pulled dr  ipe; pulled drill pipe to 60!	AllPart	Year:19 84  Pipe to 3700'; spotted spotted 35 sacks 35 sacks cement through
Plugging Operations ACTUAL PLUG 35 sack cement drill p	Wichita, Kansas  perations attended by Agent?:  Completed: Hour: 6:00a.m.Day  GGING REPORT Filled hole  as cement through drill pipe;  through drill pipe; pulled dr  ipe; pulled drill pipe to 60!	AllPart	Year:19 84  Pipe to 3700'; spotted spotted 35 sacks 35 sacks cement through
Plugging Operations ACTUAL PLUG 35 sack cement drill p of a wo	Wichita, Kansas  perations attended by Agent?:  Completed: Hour: 6:00a.m.Day  GGING REPORT Filled hole  as cement through drill pipe;  through drill pipe; pulled dr  ipe; pulled drill pipe to 60'  od and rubber plug. Run one	Part  : XMAXXX 17 Month: 7  with heavy mud; run drill  pulled drill pipe to 950';  ill pipe to 320'; spotted;  ; spotted 25 sacks cement  joint of drill pipe in rat	None XX  Year: 19 84  Pipe to 3700'; spotted spotted 35 sacks 35 sacks cement through through drill pipe on top circulated 10 sacks
Plugging Operations ACTUAL PLUG 35 sack cement drill p of a wo cement cement	Wichita, Kansas  perations attended by Agent?:  Completed: Hour: 6:00a.m.Day  GGING REPORT Filled hole  as cement through drill pipe;  through drill pipe; pulled dr  ipe; pulled drill pipe to 60'  od and rubber plug. Run one  to surface, Run one joint of  to surface.  Sun Cement Tick	AllPart	None XX  Year: 19 84  Pipe to 3700'; spotted  spotted 35 sacks  35 sacks cement through  through drill pipe on top  circulated 10 sacks  circulated 10 sacks
Plugging Operations ACTUAL PLUG 35 sack cement drill p of a wo	Wichita, Kansas  perations attended by Agent?:  Completed: Hour: 6:00a.m.Day  GGING REPORT Filled hole  as cement through drill pipe;  through drill pipe; pulled dr  ipe; pulled drill pipe to 60'  od and rubber plug. Run one  to surface, Run one joint of  to surface.	AllPart	None XX  Year: 19 84  Pipe to 3700'; spotted  spotted 35 sacks  35 sacks cement through  through drill pipe on top  circulated 10 sacks  circulated 10 sacks
Plugging Operations ACTUAL PLUG 35 sack cement drill p of a wo cement Cement Remarks:	Wichita, Kansas  perations attended by Agent?:  Completed: Hour: 6:00a.m.Day  GGING REPORT Filled hole  as cement through drill pipe;  through drill pipe; pulled dr  ipe; pulled drill pipe to 60'  od and rubber plug. Run one  to surface, Run one joint of  to surface.  Sun Cement Tick	AllPart	None XX  Year: 19 84  Pipe to 3700'; spotted  spotted 35 sacks  35 sacks cement through  through drill pipe on top  circulated 10 sacks  circulated 10 sacks  this form.)
Plugging Operations ACTUAL PLUG 35 sack cement drill p of a wo cement cement Remarks:	Wichita, Kansas  perations attended by Agent?:  Completed: Hour: 6:00a.m.Day  GGING REPORT Filled hole  as cement through drill pipe;  through drill pipe; pulled dr  ipe; pulled drill pipe to 60'  od and rubber plug. Run one  to surface, Run one joint of  to surface.  Sun Cement Tick  (If additional description	AllPart	None XX  Year: 19 84  Pipe to 3700'; spotted  spotted 35 sacks  35 sacks cement through  through drill pipe on top  circulated 10 sacks  circulated 10 sacks  this form.)
Plugging Operations ACTUAL PLUG 35 sack cement drill p of a wo cement Cement Remarks:	Wichita, Kansas  perations attended by Agent?:  Completed: Hour: 6:00a.m.Day  GGING REPORT Filled hole  as cement through drill pipe;  through drill pipe; pulled dr  ipe; pulled drill pipe to 60'  od and rubber plug. Run one  to surface, Run one joint of  to surface.  Sun Cement Tick  (If additional description	AllPart	None XX  Year: 19 84  Pipe to 3700'; spotted  spotted 35 sacks  35 sacks cement through  through drill pipe on top  circulated 10 sacks  circulated 10 sacks  this form.)