STATE OF KANSAS STATE CORPORATION COMMISSION 130 South Market Room 2078 Wichita, Kansas 67202 WELL PLUGGING RECORD K.A.R. 82-3-117

TYPE OR PRINT NOTICE: Fill out completely and return to Cons. Div. office within 60 days.

API NUMBER 15-007-22164- 60-6/
LEASE NAME McIntire
WELL NUMBER 1
4620 Ft. from N / S Section Line

2310 ____ Ft. from E / W Section Line

						RGE. <u>12</u> (E) (
LEASE OPERATOR <u>Kestrel Energy Inc.</u> ADDRESS 999 18 th St., #2490, Denver, CO 80202				cour	NTY <u>Barber</u>		
PHONE # _303-295-0344 OPERATOR'S LICENSE NO				Date '	Date Well Completed		
Character of Well Good 25				Plugg	Plugging Commenced 6-29-2001		
(Oil, Gas, D&A, SWD, Input, Water Supply Well)				Plugg	Plugging Completed7-10-2001		
The plugging pr	oposal was app	roved on <u>6-</u> 2	29-2001			(
by Richard L	.acey				(KCC	District Agent's Na	
is ACO-1 filed?							
Producing Form	nation <u>Admire</u>	e	Depth to Top _	2784 E	ottom <u>2786</u>	T. D. <u>3860</u> 472	
Show depth and	d thickness of all	l water, oil and	gas formations.				
	WATER RECO		То		G RECORD	Pulled out	
Formation	Content	From	10	Size	Put in		
			-	8 5/8 5 1/2	262 3917	None 2000	
					3717	2000	
Lay down rods ar Lay down 5 ½, r	ig down move off	f. 7/10/01: run nt, pull tubing to	2 3/8 tubing to 700 o 60 and circulate to	o, Allied load hole vosurface, 60/40, 6 9	vith jel and spot 50s //6 jel, lay down tubi		
Lay down rods at Lay down 5 ½, r Tubing to 290 an	ig down move off d spot 50sx cemen	f. 7/10/01: run nt, pull tubing to (If additiona	2 3/8 tubing to 700 o 60 and circulate to all description is necess	o, Allied load hole vos surface, 60/40, 6 osary, use BACK of this	vith jel and spot 50s 6 jel, lay down tubi form.)	sx cement, pull ng	
Lay down rods at Lay down 5 ½, r Tubing to 290 an Name of Pluggi	ig down move off d spot 50sx cemen ng Contractor	f. 7/10/01: run nt, pull tubing to (If additiona Clarke Corp	2 3/8 tubing to 700 o 60 and circulate to all description is necess	o, Allied load hole vos surface, 60/40, 6 9 sary, use <u>BACK</u> of this	vith jel and spot 50s 6 jel, lay down tubi form.) License No.	sx cement, pull ng 5105	
Lay down rods at Lay down 5 ½, r Tubing to 290 an Name of Pluggi Address P.O. NAME OF PAR	ig down move off d spot 50sx cemer ng Contractor _ Box 187, 107 W TY RESPONSIE	f. 7/10/01: run nt, pull tubing to (If additiona Clarke Corp // Fowler, Med	2 3/8 tubing to 700 to 60 and circulate to description is necessoration	o, Allied load hole vos surface, 60/40, 6 9 sary, use BACK of this sary.	vith jel and spot 50s 6 jel, lay down tubi form.) License No.	sx cement, pull ng 5105	
Lay down rods at Lay down 5 ½, r Tubing to 290 an Name of Pluggi Address P.O. NAME OF PAR STATE OF Ka	ig down move off d spot 50sx cemer ng Contractor _ Box 187, 107 W TY RESPONSIE	f. 7/10/01: run nt, pull tubing to (If additiona Clarke Corp // Fowler, Med BLE FOR PLU COU	2 3/8 tubing to 700 to 60 and circulate to 1 description is necessionation icine Lodge, KS 6 GGING FEES:	o, Allied load hole von surface, 60/40, 6 % sary, use BACK of this 37104 Kestrel Energy, In	vith jel and spot 50s 6 jel, lay down tubi form.) License No	sx cement, pull ng 5105 ss.	
Lay down rods at Lay down 5 ½, r Tubing to 290 an Name of Pluggi Address P.O. NAME OF PAR STATE OF Kar	ig down move off d spot 50sx cemen ng Contractor _ Box 187, 107 W TY RESPONSIE nsas	f. 7/10/01: run nt, pull tubing to (If additiona Clarke Corp // Fowler, Med BLE FOR PLU	2 3/8 tubing to 700 2 60 and circulate to 3 description is necess oration licine Lodge, KS 6 GGING FEES: JNTY of Barber (Employee	o, Allied load hole was surface, 60/40, 6 % sary, use BACK of this B7104 Kestrel Energy, In of Operator) or (Operator) or (Operator)	vith jel and spot 50s /s jel, lay down tubi form.) License No. C. perator) of above de	sx cement, pull ng 5105 ss. scribed well, being fi	
Lay down rods at Lay down 5 ½, r Tubing to 290 an Name of Pluggi Address P.O. NAME OF PAR STATE OF Kar Alan duly sworn on oa	ng Contractor Box 187, 107 W TY RESPONSIE nsas Vratil th, says: That I ha	f. 7/10/01: run nt, pull tubing to (If additiona Clarke Corp // Fowler, Med BLE FOR PLU COU	2 3/8 tubing to 700 to 60 and circulate to 60 and 60	o, Allied load hole von surface, 60/40, 6 % sary, use BACK of this sary, use EACK of this sary are sary and the sary are sary and sary are sary are sary and sary are	vith jel and spot 50s /s jel, lay down tubi form.) License No. C. perator) of above de	sx cement, pull ng 5105	
Lay down rods at Lay down 5 ½, r Tubing to 290 an Name of Pluggi Address P.O. NAME OF PAR STATE OF Kar Alan duly sworn on oa	ng Contractor Box 187, 107 W TY RESPONSIE nsas Vratil th, says: That I ha	f. 7/10/01: run nt, pull tubing to (If additiona Clarke Corp // Fowler, Med BLE FOR PLU COU	2 3/8 tubing to 700 2 60 and circulate to 3 description is necess oration licine Lodge, KS 6 GGING FEES: JNTY of Barber (Employee	o, Allied load hole von surface, 60/40, 6 % sary, use BACK of this sary, use EACK of this sary are sary and the sary are sary and sary are sary are sary and sary are	vith jel and spot 50s /s jel, lay down tubi form.) License No. C. perator) of above de	sx cement, pull ng 5105 ss. scribed well, being fi	
Lay down rods at Lay down 5 ½, r Tubing to 290 an Name of Pluggi Address P.O. NAME OF PAR STATE OF Kar Alan duly sworn on oa	ig down move off d spot 50sx cemer ng Contractor	Clarke Corp Clarke Corp Fowler, Med BLE FOR PLU COU ave knowledge ne are true and o	2 3/8 tubing to 700 to 60 and circulate to 60 and 60	o, Allied load hole was surface, 60/40, 6 of surface, 60/40, 6 of sary, use BACK of this sary, use BACK of this sary and surface of Operator) or (Operator, and matters he God.	vith jel and spot 50s 6 jel, lay down tubi form.) License No. c. perator) of above de rein contained and the containe	sx cement, pull ng 5105 ss. scribed well, being fithe log of the above-	
Lay down rods at Lay down 5 ½, r Tubing to 290 an Name of Pluggi Address P.O. NAME OF PAR STATE OF Kar Alan duly sworn on oa	ng Contractor Box 187, 107 W TY RESPONSIE nsas Vratil th, says: That I ha filled that the san	Clarke Corp Clarke Corp Fowler, Med BLE FOR PLU COU ave knowledge ne are true and o	2 3/8 tubing to 700 to 60 and circulate to 60 and 60	o, Allied load hole was surface, 60/40, 6 of surface, 60/40, 6 of sary, use BACK of this sary, use BACK of this sary and surface of Operator) or (Operator, and matters he God.	vith jel and spot 50s /s jel, lay down tubi form.) License No. C. perator) of above de	sx cement, pull ng 5105 ss. scribed well, being fithe log of the above-	
Lay down rods at Lay down 5 ½, r Tubing to 290 an Name of Pluggi Address P.O. NAME OF PAR STATE OF Kar Alan duly sworn on oa described well as	ng Contractor Box 187, 107 W TY RESPONSIE nsas Vratil th, says: That I ha filled that the san GLENDA MORRIS NOTARY PUBLIC STATE OF KANSA My Appl. Exp. ///	Clarke Corp Clarke Corp Fowler, Med BLE FOR PLU COU ave knowledge ne are true and of the corp Son	2 3/8 tubing to 700 to 60 and circulate to 60 and 60	o, Allied load hole vosurface, 60/40, 6 % surface, 60/40, 6 % sary, use BACK of this BACK of this BACK of this GATIO4 Kestrel Energy, In the conference of Operator) or (Operator, and matters he God. O. Box 187, Media	vith jel and spot 50s 6 jel, lay down tubi form.) License No. c. perator) of above de rein contained and spot 50s	sx cement, pull ng 5105 ss. scribed well, being fithe log of the above-	
Name of Pluggi Address P.O. NAME OF PAR STATE OF Kar Alan duly sworn on oar described well as	ig down move off d spot 50sx cemer of the spo	Clarke Corp Clarke Corp Fowler, Med BLE FOR PLU COU ave knowledge ne are true and of the corp Son	2 3/8 tubing to 700 to 60 and circulate to 60 and 60	o, Allied load hole vosurface, 60/40, 6 % surface, 60/40, 6 % sary, use BACK of this BACK of this BACK of this GATIO4 Kestrel Energy, In the conference of Operator) or (Operator, and matters he God. O. Box 187, Media	vith jel and spot 50s 6 jel, lay down tubi form.) License No. c. perator) of above de rein contained and spot 50s	sx cement, pull ng 5105 ss. scribed well, being fi the log of the above-	
Name of Pluggi Address P.O. NAME OF PAR STATE OF Ka Alan duly sworn on oa described well as	ig down move off d spot 50sx cemer of the spo	Clarke Corp Clarke Corp Fowler, Med BLE FOR PLU COU ave knowledge ne are true and constant SON SSCRIBED AND	2 3/8 tubing to 700 to 60 and circulate to 60 and 60	of Operator) or (Opents, and matters he God. D. Box 187, Medic ore me this	vith jel and spot 50s 6 jel, lay down tubi form.) License No. c. perator) of above de rein contained and to cine Lodge, KS 67 day of	sx cement, pull ng 5105 ss. scribed well, being fi the log of the above-	
Name of Pluggi Address P.O. NAME OF PAR STATE OF Ka Alan duly sworn on oa described well as	ig down move off d spot 50sx cemer of the spo	Clarke Corp Clarke Corp Fowler, Med BLE FOR PLU COU ave knowledge ne are true and constant SON SSCRIBED AND	2 3/8 tubing to 700 to 60 and circulate to 60 and 6	of Operator) or (Opents, and matters he God. D. Box 187, Medic ore me this	vith jel and spot 50s 6 jel, lay down tubi form.) License No. c. perator) of above de rein contained and to cine Lodge, KS 67 day of	sx cement, pull ng 5105 ss. scribed well, being fi the log of the above-	

OK