

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
P. O. BOX 17027
Wichita, Kansas 67217

Rev. 3-15-72
RECEIVED
STATE CORPORATION COMMISSION

AUG 25 1972

WELL PLUGGING APPLICATION FORM
File One Copy

CONSERVATION DIVISION
Wichita, Kansas

Lease Owner SeRoBee Drilling Company

Address 256 North Topeka, Wichita, Kansas 67202

Lease (Farm Name) Carthrae Well No. 1

Well Location C SE SE Sec. 7 Twp. 34S Rge. 15 (E) (W) W

County Barber Total Depth 810 Field Name _____

Oil Well _____ Gas Well _____ Input Well _____ SWD Well _____ Rotary D & A _____ Lost Hole _____

Well Log filed with application as required Yes

Date and hour plugging is desired to begin 5:00 PM 8-12-72

PLUGGING OF THIS WELL WILL BE DONE IN ACCORDANCE WITH K.S.A. 55-128 OF THE RULES AND REGULATIONS OF THE STATE CORPORATION COMMISSION.

Name of company representative authorized to be in charge of plugging operations:

Paul Sipter Address _____

Plugging Contractor Garvey Drilling Company License No. *


Address Box 1164, Great Bend, Kansas 67530

Invoice covering assessment for plugging this well should be sent to:

Name SeRoBee Drilling Company

Address 256 North Topeka, Wichita, Kansas 67202

and payment will be guaranteed by applicant or acting agent.

Signed: 
~~Applicant~~ Acting Agent

Date: _____

State of Kansas



State Corporation Commission

CONSERVATION DIVISION

(Oil, Gas and Water)

P. O. Box 17027 3830 S. Meridian
WICHITA, KANSAS 67217

August 15, 1972

WELL PLUGGING AUTHORITY

Well No.	1
Lease	Carthrae
Description	C SE SE 7-34-15W
County	Barber
Total Depth	810
Plugging Contractor	Garvey Drilling Co.


SeRoBee Drilling Company
256 N. Topeka
Wichita, Kansas 67202

Gentlemen:

This is your authority to plug the above subject well in accordance with the Rules and Regulations of the State Corporation Commission.

This authority is void after 90 days from the above date.

Yours very truly,


J. Lewis Brock, Administrator

Mr. G. Russell Biberstein Attica, Kansas 67009
is hereby assigned to supervise the plugging of the above named well.