

CP1

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
211 NORTH BROADWAY
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM
File One Copy

Lease Owner Pickrell Drilling Company Address 705 Fourth Nat'l Bank Bldg.
(Applicant)

Lease (Farm Name) Hutchison Well No. 1

Well Location SW SW SW Sec. 3 Twp. 34 Rge. (E) 12 (W)

County Barber Field Name (if any) - -

Total Depth 1767 Oil Gas Dry Hole D & A

Was well log filed with application? No If not, explain: _____

Will be mailed later.

Date and hour plugging is desired to begin 10:00 A.M. 10/18/56

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission.

Name of the person on the lease in charge of well for owner _____

Gerald W. Pike Address 705 Fourth Nat'l Bank Bldg. Wichita, Kansas

Plugging Contractor Pickrell Drilling Company

Plugging Contractor's License No. _____

Address 705 Fourth Nat'l Bank Bldg.

Invoice covering assessment for plugging this well should be sent to _____

Pickrell Drilling Company Address 705 Fourth Nat'l Bank Bldg. Wichita, Kansas

and payment will be guaranteed by applicant.

RECEIVED
PLUGGING STATE CORPORATION COMMISSION
FILE SEC 3 T. 34 R. 12W
BOOK PAGE 109 LINE 24
OCT 24 1956
CONSERVATION DIVISION
Wichita, Kansas

[Signature]
Applicant or Acting Agent

Date 10/22/56



STATE OF KANSAS
 STATE CORPORATION COMMISSION
 CONSERVATION DIVISION
 211 NORTH BROADWAY
 WICHITA, KANSAS

October 22, 1956

Well No. 1
 Lease Hutchinson
 Description SW SW SW 3-34-12W
 County Barber
 File No. 109-24

Pickrell Drilling Company
 705 Fourth National Bank Bldg.
 Wichita, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. M. A. Rivas, Box 8, Pratt, Kansas.

STATE CORPORATION COMMISSION
 CONSERVATION DIVISION

By S. S. Greider
 S. S. Greider
 WELL PLUGGING SUPERVISOR

cc:
 District Plugging Supervisor