

CPI

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
211 NORTH BROADWAY
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM
File One Copy

Lease Owner TIME PETROLEUM COMPANY Address 512 ORPHEUM BUILDING, WICHITA, KS.
(Applicant)

Lease (Farm Name) ROTH Well No. 1

Well Location CENTER NW/4 Sec. 36 Twp. 33S Rge. (E) - (W) 14

County BARBER Field Name (if any) MEDICINE LODGE POOL

Total Depth 4817 Oil Gas Dry Hole DRY HOLE

Was well log filed with application? Yes If not, explain: _____

Date and hour plugging is desired to begin 11:00 P.M., 2/17/57

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission.

Name of the person on the lease in charge of well for owner CLYDE ADAMS

Address 1305 EAST 5TH STREET, WINFIELD, KANSAS

Plugging Contractor KIRKPATRICK DRILLING COMPANY

Plugging Contractor's License No. _____

Address 512 ORPHEUM BUILDING, WICHITA, KANSAS

Invoice covering assessment for plugging this well should be sent to _____

TIME PETROLEUM COMPANY Address 512 ORPHEUM BUILDING, WICHITA, KANSAS

and payment will be guaranteed by applicant.

TIME PETROLEUM COMPANY

BY: R. Schreiner
Applicant or Acting Agent

RECEIVED
STATE CORPORATION COMMISSION

MAR 21 1957
3-21-57
CONSERVATION DIVISION
Wichita, Kansas

Date 2/17/57

PLUGGING
FILE SEC. 36 T. 33 R. 14W
BOOK PAGE 141 LINE 38



STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
211 NORTH BROADWAY
WICHITA, KANSAS

February 19, 1957

Well No. 1
Lease Both
Description 788/4 36-33-14W
County Barber
File No. 141-38

The Petroleum Company
512 Orpheus Building
Wichita, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. M. A. Rives, Box 8, Pratt, Kansas.

STATE CORPORATION COMMISSION
CONSERVATION DIVISION

BY S. S. Greider
S. S. Greider
WELL PLUGGING SUPERVISOR

cc:
District Plugging Supervisor