Ichita State	1 041148 -	API NUMBER 15- 007-01,042-00-01	
		D. NW SE NW, SEC. 16, T 33 S, R 14 WXX	
30 S. Market, Room 2078 Wichita, KS 67202 ECHNICIAN'S PLUGGING REPORT 2-/3		3355 feet from S section line	
		3355 feet from E section line	
erator 1	License J 5447	Lease Name McGrath A Well # 1	
	OXY USA INC.	County Barber	
ame& ddress	110 S. Main, Ste. 800	Well Total Depth 5010 162.83 feet	
	Wichita, KS 67202	Gonductor Pipe: Size feet_	
		Surface Casing: Size 8 5/8 feet 812	
án dan ed	Oli Well Gas Well X	Input Well SWD Well D&A	
	t as hereinafter indicated		
	Clarke Corporation	5105	
	2.0. Box 187, Medicine Lodge, KS 67	License Number 5105	
		13 Honth: 2 Year: 1996	
	proposal received from Lance Fel		
-	_ •	(phone) 316-672-5630	
ore: <u> </u>	$5\frac{1}{2}$ " at 5002' w/300 sx cement, PBTD	9 4957', Perfs at 4650-60,3460-75'	
st plug	put 2 sx cement on CIBP at 4580',		
un 2 3/3	sand back to 3400° and dump 5 sx c spot 50 sx cement at 827°, 4th pl	ement on top of sand through bailer, ug spot 50 sx cement at 410',	
th plug	spot 15 sx dement at 60'.		
	Plugging Pro	posal Received by Steve Pfeifer	
		(TECHNIGHAN)	
	Operations attended by Agent?:	All X Part Non601 Of	
	11		
peratio	ns Completed: Hour: 11 a.m. Day:		
peration	LUGGING REPORT 1st nlug put 2 sx	cement on CIBP at 4580',	
peration	LUGGING REPORT 1st nlug put 2 sx		
peration CTUAL Pond plug	LUGGING REPORT 1st nlug put 2 sx	cement on CIBP at 4580',	
CTUAL Prod plug	sanded back to 3400 and dumped 5	cement on CIBP at 4580',	
CTUAL Plad plug an 2'3/3	sanded back to 3400° and dumped 5 but tubing in to spot plugs:	cement on CIBP at 4580',	
CTUAL Pland plug an 2'3/3 rd plug th plug	sanded back to 3400' and dumped 5 "tubing in to spot plugs: at 327' with 50 sx cement,	cement on CIBP at 4580',	
operation ACTUAL Pland plug an 2'3/3 rd plug th plug th plug	sanded back to 3400' and dumped 5 "tubing in to spot plugs: at 827' with 50 sx cement, at 410' with 50 sx cement, at 60' with 15 sx cement.	sx cement on top of sand bridge through Bailer,	
CTUAL Point plug and 2 3/3 and plug th plug th plug Remarks:	sanded back to 3400' and dumped 5 "tubing in to spot plugs: at 827' with 50 sx cement, at 410' with 50 sx cement, at 60' with 15 sx cement. Used 60/40 Pozmix 6% gel by Hal (If additional description	cement on CIBP at 4580',	
crual Pond plug an 2'3/3 rd plug th plug th plug Remarks:	sanded back to 3400' and dumped 5 "tubing in to spot plugs: at 827' with 50 sx cement, at 410' with 50 sx cement, at 60' with 15 sx cement. Used 60/40 Pozmix 6% gel by Hal (if additional description daxwoods because this plugging.	sx cement on top of sand bridge through Bailer, liburton. Recovered 2900' of 5½" casing.	
crual Plug an 2'3/3 rd plug th plug Remarks:	sanded back to 3400' and dumped 5 "tubing in to spot plugs: at 827' with 50 sx cement, at 410' with 50 sx cement, at 60' with 15 sx cement. Used 60/40 Pozmix 6% gel by Hal (If additional description	sx cement on top of sand bridge through Bailer, liburton. Recovered 2900' of 5½" casing.	