

15-167-04021-0000

STATE OF KANSAS  
STATE CORPORATION COMMISSION  
CONSERVATION DIVISION  
211 NORTH BROADWAY  
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM  
File One Copy

Lease Owner The Texas Company Address 614 Bitting Building  
(Applicant)

Lease (Farm Name) Henry Boxberger Well No. 7

Well Location NW NW NW Sec. 14 Twp. 14S Rge. 14W(E) - (W)

County Russell Field Name (if any) Hall-Gurney

Total Depth 3320' Oil      Gas      Dry Hole X

Was well log filed with application? No If not, explain:     

Will be filed with plugging record

Date and hour plugging is desired to begin March 19, 1956

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission.

Name of the person on the lease in charge of well for owner     

Mr. E. E. Ball Address Route 1, Russell, Kansas

Plugging Contractor Stickle Drilling Company

Plugging Contractor's License No.     

Address Box 117, Great Bend, Kansas

Invoice covering assessment for plugging this well should be sent to     

M. C. Harrell Address Box 1801, Wichita, Kansas

and payment will be guaranteed by applicant.

Herbert L. Mussall  
Applicant or Acting Agent

Date March 19, 1956

RECEIVED  
MAR 20 1956  
03-20-56  
CONSERVATION DIVISION  
WICHITA, KANSAS

**PLUGGING**

FILE SEC 14 T 14 R 14W  
BOOK PAGE 47 LINE 5

CPI



STATE OF KANSAS  
STATE CORPORATION COMMISSION  
CONSERVATION DIVISION  
211 NORTH BROADWAY  
WICHITA, KANSAS

March 20, 1956

Well No.	7
Lease	Boxberger
Description	NW 1/4 NW 14-14-14W
County	Russell
File No.	47-5

The Texas Company  
c/o H. A. Harwell  
Box 1801  
Wichita, Kansas

Dear Sir:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. Milton Galyardt, Box 145, Russell, Kansas.

STATE CORPORATION COMMISSION  
CONSERVATION DIVISION

By S. S. Greider  
S. S. Greider  
WELL PLUGGING SUPERVISOR

cc:  
District Plugging Supervisor