

15-119-10082-00-00

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
211 NORTH BROADWAY
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM

File One Copy

Lease Owner Graham-Michaelis Drlg. Co Address 211 North Broadway, Wichita, Kansas
(Applicant)

Lease (Farm Name) SANDERS "B" Well No. 1

Well Location C SW/4 Sec. 7 Twp. 32S Rge. 28W (R) (W)

County Meade Field Name (if any) _____

Total Depth 5660' Oil _____ Gas _____ Dry Hole x

Was well log filed with application? yes If not, explain: _____

Date and hour plugging is desired to begin as soon as possible

Plugging of the well will be done in accordance with the Rules and Regulations of
the State Corporation Commission.

Name of the person on the lease in charge of well for owner _____

Carl W. Jacobs Address 1621 Williams St., Great Bend, Ks.

Plugging Contractor Graham-Michaelis Drilling Company

Plugging Contractor's License No. _____

Address 211 North Broadway, Wichita, Kansas

Invoice covering assessment for plugging this well should be sent to _____

Graham-Michaelis Drilling Co. Address 211 North Broadway, Wichita, Ks.

and payment will be guaranteed by applicant.

RECEIVED
STATE CORPORATION COMMISSION

DEC 19 1957
12-19-57
CONSERVATION DIVISION
Wichita, Kansas

Graham Michaelis
Applicant or Acting Agent

Date December 13, 1957

PLUGGING
FILE SEC 7 T 32 R 28W
BOOK PAGE 66 LINE 21

STATE OF KANSAS
State Corporation Commission
Conservation Division
211 North Broadway
Wichita, Kansas

December 12, 1957


Well No.	1
Lease	Sanders "B"
Description	OSW 7-32-28W
County	Meade
File No.	68-21

Graham-Michaelis Drilling Company
211 North Broadway
Wichita, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. Don Peterson, Box 52, Lakin, Kansas Phone EL-56471

Very truly yours,


Jewel M. Ogden
Director of Conservation Division

cc:
District Plugging Supervisor