STATE OF KANSAS STATE CORPORATION COMMISSION

Give All Information Completely
Make Required Affidavit
Mail or Deliver Report to:
Conservation Division
State Corporation Commission
212 North Market, Insurance Bldg.

WELL PLUGGING RECORD

Wichita, Kansas							7,1773 7,177.77	$\underline{SOW}(E)$ (W
NORTH				CNW#SW#"			NE NW	
! : 1	;]		*	<u>W. J.</u>	Coppinger	r et al		
	ļ.		Vame	<u>Meyer</u>	77 - 1 7 7 7 1	Tri - loi d	- O Va	_ Well No
	<u></u>				,	g., Wichit	dry hole	
					as Oil, Gas or R	T Dry Hole)	12-	<u> </u>
·i			ell compl	lugging filed	<u> </u>	<u> </u>	Janua	ry 8 19 63
				lugging approv	red	*	Janua	
		,	g comme		/eu	. 9		ry 28, 19 63
İ	. 1	,	g complet				Marc	eh 1 19 63
	·			lonment of wel	l or producing	z formation	dry	
	3 1 1	· · · · · ·			<u> </u>		·	*2
		If a pro	ducing w	ell is abandon	ed, date of la	st production	<u> </u>	19
		Was p	ermission	obtained from	the Conserv	ation Division o	r its agents bef	ore plugging was con
Locate well corre Section	Plat	mencec	IP		yes			
me of Conservation	a Agent who sup	ervised pluggi	ng of this	well Hugh	Scott, L			<u> </u>
ducing formation		, • '		pth to top	Botton	— ———————————————————————————————————	Total Depth of	Well 6225 Fe
ow depth and thicl	kness of all water	r, oil and gas f	ormations	•		v .	•	
OIL, GAS OR W	ATER RECOR	D S .			•			CASING RECORD
FORMATI		CONTEN	17	FROM	то	CITE	DUT IN	0,011.50.007
FORMATI		GUNTER	••	- ROM	10	8-5/811	1451	PULLED DUT
· · · · · · · · · · · · · · · · · · ·				N.		U-0/0"	<u> </u>	none
		 				4-1/2tt	5800	4961
		,					7000	4/04
					· .	-		
				·				,
	· · · · · · · · · · · · · · · · · · ·			<u> </u>		1.		
				*	100	3.1		
Mov Sar		started of	cleanin	ng cellar sax ceme	and blow	ed pipe an	rell. nd loaded l	nole with wat
Mor Sar Wor Pu	ved on and nded to 565 rked pipe a lled pipe a	started of and diand finishand droppe	cleaning the clean clear	ng cellar sax ceme eaning ou e; started	and blowent, work t cellar;	ing down wed pipe an	rell. nd loaded h head; wor	nole with waterked on equip
Mor Sar Wor Pul Fi:	ved on and nded to 565 rked pipe a lled pipe a shed pipe,	started of and drand finish and droppe worked p	cleanin imped cle ned cle ed pipe ipe and	ng cellar sax ceme eaning ou ; started holed by	and blowent, work t cellar; d fishing	ing down wed pipe an	rell. nd loaded h head; wor	nole with waterked on equip
Mov San Woo Pu. Fi. Woo	ved on and nded to 565 rked pipe a lled pipe a shed pipe, rked and sh	started of and diand finishand droppe worked proof proof of the contract of th	cleaning mped shed clead pipe and 3967	ng cellar sax ceme eaning ou e; started holed bu	and blowent, work to cellar; dishing a lidge a lidge a lidge	ing down wad pipe and broke off	rell. Id loaded l head; worlded on br	nole with waterked on equip
Mov Sar Woo Pul Fi: Woo Pul	ved on and nded to 565 rked pipe a shed pipe, rked and shilled rest of the state of	started of and diand finishand droppe worked pine of pipe;	cleaning the clean	ng cellar sax ceme eaning ou e; started holed br Pulled well wi	and blowent, work to cellar; defishing tidge @ 4 pipe th mud an	ing down wad pipe an broke off	rell. Id loaded l head; worlded on br	nole with waterked on equip
Moy Sar Wor Pul Fi: Wor Pul Dur	ved on and nded to 565 rked pipe a shed pipe, rked and shiled rest of mped 35 sax	started of and diand finish worked protection pipe of pipe; and cement;	cleaning amped shed cleaning and pipe and 3967 plugged filled	ng cellar sax ceme eaning ou e; started holed br Pulled well wi hole and	and blowent, work tellar; dishing tidge @ La pipe th mud and rock br	ing down wed pipe and broke off	rell. Id loaded l head; worlded on br	nole with waterked on equip
Moy Sar Wor Pul Fi: Wor Pul Dur	ved on and nded to 565 rked pipe a shed pipe, rked and shilled rest of the state of	started of and diand finish worked protection pipe of pipe; and cement;	cleaning amped shed cleaning and pipe and 3967 plugged filled	ng cellar sax ceme eaning ou e; started holed br Pulled well wi hole and	and blowent, work tellar; dishing tidge @ La pipe th mud and rock br	ing down wed pipe and broke off	rell. Id loaded l head; worlded on br	nole with waterked on equip
Moy Sar Wor Pul Fi: Wor Pul Dur	ved on and nded to 565 rked pipe a shed pipe, rked and shiled rest of mped 35 sax	started of and diand finish worked protection pipe of pipe; and cement;	cleaning amped shed cleaning and pipe and 3967 plugged filled	ng cellar sax ceme eaning ou e; started holed br Pulled well wi hole and	and blowent, work tellar; dishing tidge @ La pipe th mud and rock br	ing down wed pipe and broke off	rell. Id loaded l head; worlded on br	nole with waterked on equip
Moy Sar Wor Pul Fi: Wor Pul Dur	ved on and nded to 565 rked pipe a shed pipe, rked and shalled rest of mped 35 sax	started of and diand finish worked protection pipe of pipe; and cement;	cleaning amped shed cleaning and pipe and 3967 plugged filled	ng cellar sax ceme eaning ou e; started holed br Pulled well wi hole and	and blowent, work tellar; dishing tidge @ La pipe th mud and rock br	ing down wed pipe and broke off	rell. Id loaded let head; worlded on broader. Idge @ 750	nole with waterked on equipolidge.
Moy Sar Wor Pul Fi: Wor Pul Dur	ved on and nded to 565 rked pipe a shed pipe, rked and shalled rest of mped 35 sax	started of and diand finish worked protection pipe of pipe; and cement;	cleaning amped shed cleaning and pipe and 3967 plugged filled	ng cellar sax ceme eaning ou e; started holed br Pulled well wi hole and	and blowent, work tellar; dishing tidge @ La pipe th mud and rock br	ing down wed pipe and broke off	rell. Id loaded head; worlded on bridge @ 750	nole with waterked on equipolidge.
Moy Sar Wor Pul Fi: Wor Pul Dur	ved on and nded to 565 rked pipe a shed pipe, rked and shalled rest of mped 35 sax	started of and diand finish worked protection pipe of pipe; and cement;	cleaning amped shed cleaning and pipe and 3967 plugged filled	ng cellar sax ceme eaning ou e; started holed br Pulled well wi hole and	and blowent, work tellar; dishing tidge @ La pipe th mud and rock br	ing down wed pipe and broke off	rell. Id loaded head; worlded on bridge @ 750	nole with waterked on equipoledge.
Moy Sar Wor Pul Fi: Wor Pul Dur	ved on and nded to 565 rked pipe a shed pipe, rked and shalled rest of mped 35 sax	started of and diand finish worked protection pipe of pipe; and cement;	cleaning amped shed cleaning and pipe and 3967 plugged filled	ng cellar sax ceme eaning ou e; started holed br Pulled well wi hole and	and blowent, work tellar; dishing tidge @ La pipe th mud and rock br	ing down wed pipe and broke off	rell. Id loaded let head; work Ided on broken Ided @ 750	nole with waterked on equipolidge.
Moy Sar Wor Pul Fi: Wor Pul Dur	ved on and nded to 565 rked pipe a shed pipe, rked and shalled rest of mped 35 sax	started of and diand finish worked protection pipe of pipe; and cement;	cleaning amped shed cleaning and pipe and 3967 plugged filled	ng cellar sax ceme eaning ou e; started holed br Pulled well wi hole and	and blowent, work tellar; dishing tidge @ La pipe th mud and rock br	ing down wed pipe and broke off	rell. Id loaded let head; work Ided on broken Ided @ 750	nole with waterked on equipolidge.
Moy Sar Wor Pul Fi: Wor Pul Dur	ved on and nded to 565 rked pipe a shed pipe, rked and shalled rest of mped 35 sax	started of and diand finish worked protection pipe of pipe; and cement;	cleaning amped shed cleaning and pipe and 3967 plugged filled	ng cellar sax ceme eaning ou e; started holed br Pulled well wi hole and	and blowent, work tellar; dishing tidge @ La pipe th mud and rock br	ing down wed pipe and broke off	relland loaded head; worlded on bringer @ 750	nole with waterked on equipoledge. I
Moy Sar Wor Pul Fi: Wor Pul Dur	ved on and nded to 565 rked pipe a shed pipe, rked and shalled rest of mped 35 sax	started of and diand finish worked protection pipe of pipe; and cement;	cleaning amped shed cleaning and pipe and 3967 plugged filled	ng cellar sax ceme eaning ou e; started holed br Pulled well wi hole and	and blowent, work tellar; dishing tidge @ La pipe th mud and rock br	ing down wed pipe and broke off	rell. Id loaded let head; work Ided on broken Ided @ 750	nole with waterked on equipoledge. I
Moy Sar Wor Pul Fi: Wor Pul Dur	ved on and nded to 565 rked pipe a shed pipe, rked and shalled rest of mped 35 sax	started of and diand finish and droppe worked protect pipe of pipe; at 50' ar	cleaning imped the clear of the	ng cellar sax ceme eaning ou e; started holed bu Pulled well wi hole and bed with	and blowent, work to cellar; dishing a ling a ling and pipe th mud and rock broken to sax ce	ing down wad pipe and broke off OO'. Spud drock bridge. ment.	relland loaded head; worlded on bringer @ 750	nole with waterked on equipoledge. I
Mov Sar Woo Pul Fi: Woo Pul Dur Plo	ved on and nded to 565 rked pipe a lled pipe a shed pipe, rked and sh lled rest o mped 35 sax ugged well	started of and diand finish and droppe worked protection of pipe; at 50' ar	cleaning imped in the clean in	ng cellar sax ceme eaning ou e; started holed bu Pulled well wi hole and bed with	and blowent, work to cellar; dishing a ling a ling and pipe th mud and rock broken broke broken brok	ing down wad pipe and broke off OO'. Spud drock bridge. ment.	relland loaded head; worlded on bringer @ 750	nole with waterked on equipoledge. I
Mov Sar Wor Pul Fi: Wor Pul Dur Plr	ved on and nded to 565 rked pipe a lled pipe a shed pipe, rked and sh lled rest o mped 35 sax ugged well	started of and dinish and finish and droppe worked protection of pipe; at 50' and finish at 50' are started of pipe; at 50' are started of pip	cleaning imped the clear of the	ng cellar sax ceme eaning ou e; started holed bu Pulled well wi hole and bed with	and blowent, work to cellar; dishing a ling	ing down wad pipe and broke off OO'. Spud drock bridge. ment.	relland loaded head; worlded on bringer @ 750	nole with waterked on equipoledge. I
Mov Sar Wor Pul Fi: Wor Pul Dur Plr	ved on and nded to 565 rked pipe a lled pipe a shed pipe, rked and sh lled rest o mped 35 sax ugged well	started of and dinish and finish and droppe worked protection of pipe; at 50' and finish at 50' are started of pipe; at 50' are started of pip	cleaning imped the clear of the	ng cellar sax ceme eaning ou e; started holed bu Pulled well wi hole and bed with elescription is nece Pulling,	and blowent, work to cellar; dishing a ling	ing down wad pipe and broke off OO'. Spud drock bridge. ment.	relland loaded head; worlded on bringer @ 750	nole with waterked on equipoledge. I
Move San Word Pull Fig. Word Pull Dur Pull Dur Plus Dur P	ved on and nded to 565 rked pipe a lled pipe a shed pipe, rked and sh lled rest o mped 35 sax ugged well	started of and dinish and finish and droppe worked protection of pipe; at 50' and finish at 50' are started of pipe; at 50' are started of pip	cleaning imped the clean	ng cellar sax ceme eaning ou e; started holed br Pulled well wi hole and bed with escription is nece Pulling, beand, Ka	and blowent, work to cellar; dishing a ling	ing down wad pipe and broke off OO'. Spud drock bridge. ment.	relland loaded head; worlded on bringer @ 750	nole with waterked on equipoledge. I
Move San Word Pull Fig. Word Pull Dur Pull Dur Plus Dur P	ved on and nded to 565 rked pipe a lled pipe a shed pipe, rked and sh lled rest o mped 35 sax ugged well contractor	started of and dinish and finish or pipe of pipe; at 50' and finish at 50' and finish at 50'	cleaning imped in the desired and capp additional dasing Great COUNTY	ng cellar sax ceme eaning ou e; started holed br Pulled well wi hole and bed with escription is nece Pulling, Bend, Ka	and blowent, work to cellar; defishing fidge fight fidge fid	ing down wad pipe and broke off. Oo!. Spuded rock bridge. ment.	relland loaded head; worlded on bringe @ 750	nole with waterked on equipolidge. I
Move San Wood Pull Fig. Wood Pull Dun Plum Plum Plum Plum Plum Plum Plum Plum	ved on and nded to 565 rked pipe a lled pipe a shed pipe, rked and sh lled rest o mped 35 sax ugged well contractor Kansas W. J.	started of and divided and finish and droppe worked protection of pipe; at 50' are started of pipe; at 50' are sta	cleaning imped in the clean in	ng cellar sax ceme eaning ou e; started holed bu Pulled well wi d hole and bed with description is nece Pulling, t Bend, Ka	and blowers of work to cellar; to cellar; to fishing and pipe the mud and rock broken to sax cells. Seary, use BACK Inc. Seary of work to cell to ce	ing down wad pipe and broke off 00'. Spud drock bridge. ment. of this sheet)	rell. Id loaded head; worded on bridge @ 750 AVE COR	of the above-describ
Move Sair Wood Pui. Fig. Wood Pui. Dui. Plant Pl	ved on and nded to 565 rked pipe a lled pipe a shed pipe, rked and sh lled rest o mped 35 sax ugged well contractor Kansas W. J.	started of and divided finish and droppe worked protection of pipe; at 50' are started	cleaning imped in the clean in	ng cellar sax ceme eaning ou e; started holed by Pulled well wi hole and bed with description is nece Pulling, Bend, Ka	and blowers of states, statement of the state of the stat	ing down was pipe and broke off this sheet)	rell. Id loaded head; worded on bridge @ 750 AVE COR	nole with waterked on equipolidge. I
Move San Wood Pull Fig. Wood Pull Dun Plum Plum Plum Plum Plum Plum Plum Plum	ved on and nded to 565 rked pipe a lled pipe a shed pipe, rked and sh lled rest o mped 35 sax ugged well contractor Kansas W. J.	started of and divided finish and droppe worked protection of pipe; at 50' are started	cleaning imped in the clean in	ng cellar sax ceme eaning ou e; started holed by Pulled well wi hole and bed with Rescription is nece Pulling, t Bend, Ka	and blowers of states, statement of the state of the stat	ing down was pipe and broke off this sheet)	rell. Id loaded head; worded on bridge @ 750 AVE COR	of the above-describ
Move Sail Wood Pui. Fig. Wood Pui. Dur. Plant Pl	ved on and nded to 565 rked pipe a lled pipe a shed pipe, rked and sh lled rest o mped 35 sax ugged well contractor Kansas W. J.	started of and divided finish and droppe worked protection of pipe; at 50' are started	cleaning imped in the clean in	ng cellar sax ceme eaning ou e; started holed by Pulled well wi hole and bed with description is nece Pulling, Bend, Ka	and blowers of states, statement of the state of the stat	ing down was pipe and broke off this sheet)	rell. Id loaded head; worded on bridge @ 750 AVE COR	of the above-describ
Move Sage Wood Pull Fig. Wood Pull Dur Plus Dur Plus Plus Plus Plus Plus Plus Plus Plus	ved on and nded to 565 rked pipe a lled pipe a shed pipe, rked and sh lled rest o mped 35 sax ugged well contractor Kansas W. J.	started of and divided finish and droppe worked protection of pipe; at 50' are started	cleaning imped in the clean in	ng cellar sax ceme eaning ou e; started holed by Pulled well wi hole and bed with Rescription is nece Pulling, t Bend, Ka	and blowers of states, statement of the state of the stat	ing down was pipe and broke off oo!. Spud of rock bridge. ment. of this sheet)	relland loaded head; work ded on bridge @ 750 AVE COR	of the above-describ
Move-described well	wed on and nded to 565 rked pipe a lled pipe a shed pipe, rked and shed rest omped 35 sax ugged well contractor Kansas W. J.	started of and digital districts of and droppe worked protect pipe of pipe; at 50' at	cleaning imped in the cleaning and capp in the capp in	ng cellar sax ceme eaning ou e; started holed br Pulled well wi hole and bed with Rend, Ka NTY OF wledge of the correct. So Signature)	and blowent, work to cellar; defishing ridge @ lid pipe the mud and rock brook	ing down wad pipe and broke off Oo'. Spud of rock bridge. ment. of this sheet)	relland loaded head; worked on bridge @ 750 AVE COR	of the above-described and the log of the
Move-described well	ved on and nded to 565 rked pipe a lled pipe a shed pipe, rked and sh lled rest o mped 35 sax ugged well contractor Kansas W. J.	started of and digital districts of and droppe worked protect pipe of pipe; at 50' at	cleaning imped in the clean in	ng cellar sax ceme eaning ou e; started holed by Pulled well wi hole and bed with Rescription is nece Pulling, t Bend, Ka	and blowent, work to cellar; defishing ridge @ lid pipe the mud and rock brook	ing down wad pipe and broke off Oo'. Spud of rock bridge. ment. of this sheet)	relland loaded head; work ded on bridge @ 750 AVE COR	of the above-describ
Move-described well	wed on and nded to 565 rked pipe a lled pipe a shed pipe, rked and shed rest omped 35 sax ugged well contractor Kansas W. J.	started of and digital districts of and droppe worked protect pipe of pipe; at 50' at	cleaning imped in the cleaning and capp in the capp in	ng cellar sax ceme eaning ou e; started holed br Pulled well wi hole and bed with Rend, Ka NTY OF wledge of the correct. So Signature)	and blowent, work to cellar; defishing ridge @ lid pipe the mud and rock brook	ing down wad pipe and broke off Oo'. Spud of rock bridge. ment. of this sheet)	relland loaded head; worked on bridge @ 750 AVE COR	of the above-described and the log of the

MEYER #1 NE NW SEC Mosdo County, Kansas

Rigged up Retary Tools 11/8/62

Ran 45 Jts. (1461.84°) of 8-5/8° 24# New Cosing. Set 0 1458° and comented with 425 sacks Posmix w/2% cc and 400 sacks Common w/2% cc. Ran 37 Jts. of 9.5# J-55 and 45 Jts. of 10.5# J-55 (5618.99°) new Casing. Set 0 5000° w/150 sacks Posmix.

FORMATION	FROM	TO	
S and	0	2501 *	
Sand & Red Beds	250	1030°	an.
Red Bed & Shells	1030	1458 MATE CORPORATION	
Shale	1458	2604 COME	15.
Shale & Lime	2604	2836	
Lime	2836	2836 JAN 9 1963	
Lime & Shale	2936	3060*	
Lime	3960	4080 CONSERVATION DIVIS	
Lime & Shele	4080	4461° Wichita, Kansas	ię. Pi
Lime	4461	4541	
Lime & Shale	4541	4567*	
Line	4567	4655*	
Lime & Chert	4655	4670°	
Lime	4670	4840°	
Lime & Shale	4840	5022*	
Shale	5022	5 068 °	
Lime & Shale	5068	5119'	
Lime	5119	5242'	
Lime & Chert	5242	53641	
Lime	5364	5652*	
Sand & Shale	5652	5700'	
Lime	5700	6225 TD	

STATE OF KANSAS

COUNTY OF SEDGNICK

I, Don S. Packer, do hereby certify that the foregoing is true and correct to the best of my knowledge and belief.

Don S. Packer

Subscribed and swarn to before me this 6th day of December, 1962.

Helen Y. Langston, Notary Public

My Commission Expires: March 26, 1963