	4-21-88 15-119-10033-000
1 020138	API NUMBER 15- Docket #E-4924
STATE CORPORATION COMMISSION	
CONSERVATION DIVISION - PLUGGING SECTION 200 COLORADO DERBY BUILDING WICHITA, KANSAS 67202	C SE NW , SEC. 35 , T 33 S, R 30 W/ \times
FECHNICIAN'S PLUGGING REPORT	
Operator License # 5447	Lease Name Novinger Unit Well # 801W
Operator: <u>Cities Service Oil & Gas Corp.</u>	County Meade 193.
Address 3545 N.W. 58th Street Oklahoma City, OK 73112	Well Total Depthfeet
	Surface Casing: Size 9 5/8 feet 2708
Abandoned Oll Well X Gas Well	Input WellSWD WellX D&A
Other well as hereinafter indicated	
Plugging Contractor Sargent's Casing Pul.	ling License Number 6547
Address Box 506, Liberal, KS 67901	
\QQF85\$	
	18 Month: 4 Years 10 88
company to plug at: Hour: 4 p.m. Day:	18 Month: 4 Year:19 88
Company to plug at: Hour: 4 p.m. Day:	ton
Company to plug at: Hour: 4 p.m. Day: Plugging proposal received from Don Hore Company name) Sargent's Casing Pulling	(phone)316-624-7455
Company to plug at: Hour: 4 p.m. Day: lugging proposal received from Don Hore company name) Sargent's Casing Pulling ere: 55" at 5850' PBTD 5347' Perfs at	(phone)316-624-7455 _5326-43*
Company to plug at: Hour: 4 p.m. Day: Plugging proposal received from Don Hore Company name) Sargent's Casing Pulling Dere: 5½" at 5850' PBTD 5347' Perfs at 1st plug set CIBP at 4300' with 2 sx cements.	(phone)316-624-7455 _5326-43*
Company to plug at: Hour: 4 p.m. Day: "lugging proposal received from Don Horn company name) Sargent's Casing Pulling ere: 5½" at 5850' PBTD 5347' Perfs at 1st plug set CIBP at 4300' with 2 sx ceme 2nd plug pump 50 sx cement at 2715',	(phone)316-624-7455 _5326-43*
Company to plug at: Hour: 4 p.m. Day: Plugging proposal received from Don Hore company name) Sargent's Casing Pulling ere: 5½" at 5850' PBTD 5347' Perfs at 1st plug set CIBP at 4300' with 2 sx ceme 2nd plug pump 50 sx cement at 2715',	(phone)316-624-7455 _5326-43*
Company to plug at: Hour: 4 p.m. Day: Plugging proposal received from Don Hore company name) Sargent's Casing Pulling ere: 5½" at 5850' PBTD 5347' Perfs at lst plug set CIBP at 4300' with 2 sx ceme 2nd plug pump 50 sx cement at 2715', 3rd plug pump 50 sx cement at 505', 4th plug pump 20 sx cement at 40-0'.	(phone) ³¹⁶⁻⁶²⁴⁻⁷⁴⁵⁵ -5326-43' ent on top,
Company to plug at: Hour: 4 p.m. Day: Plugging proposal received from Don Hore Company name) Sargent's Casing Pulling Dere: 5½" at 5850' PBTD 5347' Perfs at 1st plug set CIBP at 4300' with 2 sx ceme 2nd plug pump 50 sx cement at 2715', 3rd plug pump 50 sx cement at 505', 4th plug pump 20 sx cement at 40-0'.	(phone)316-624-7455 5326-43' ent on top, Glenn Barlow
Company to plug at: Hour: 4 p.m. Day: Plugging proposal received from Don Horn company name) Sargent's Casing Pulling ere: 5½" at 5850' PBTD 5347' Perfs at lst plug set CIBP at 4300' with 2 sx ceme 2nd plug pump 50 sx cement at 2715', 3rd plug pump 50 sx cement at 505', 4th plug pump 20 sx cement at 40-0'. Plugging Pro	
Company to plug at: Hour: 4 p.m. Day: Plugging proposal received from Don Horn company name) Sargent's Casing Pulling ere: 5½" at 5850' PBTD 5347' Perfs at lst plug set CIBP at 4300' with 2 sx ceme 2nd plug pump 50 sx cement at 2715'. 3rd plug pump 50 sx cement at 505', 4th plug pump 20 sx cement at 40-0'. Plugging Pro	
Company to plug at: Hour: 4 p.m. Day: Plugging proposal received from Don Horn Company name) Sargent's Casing Pulling Dere: 5½" at 5850' PBTD 5347' Perfs at 1st plug set CIBP at 4300' with 2 sx cement at 2715'. By a company name of the plug pump 50 sx cement at 2715'. Casing Pulling Perfs at 4300' with 2 sx cement at 2715'. Casing Pulling Sargent's Casing Pulling Proposed to the plug set CIBP at 4300' with 2 sx cement at 2715'. Casing Pulling Sargent's Casing Pulling Perfs at 4300' with 2 sx cement at 2715'. Casing Pulling Perfs at 4300' with 2 sx cement at 2715'. Casing Pulling Perfs at 4300' with 2 sx cement at 2715'. Casing Pulling Perfs at 4300' with 2 sx cement at 2715'. Casing Pulling Perfs at 4300' with 2 sx cement at 2715'. Casing Pulling Perfs at 4300' with 2 sx cement at 2715'. Casing Pulling Perfs at 4300' with 2 sx cement at 2715'. Casing Pulling Perfs at 4300' with 2 sx cement at 2715'. Casing Pulling Perfs at 4300' with 2 sx cement at 2715'. Casing Pulling Perfs at 4300' with 2 sx cement at 2715'. Casing Pulling Perfs at 4300' with 2 sx cement at 2715'. Casing Pulling Perfs at 4300' with 2 sx cement at 2715'. Casing Pulling Perfs at 4300' with 2 sx cement at 2715'. Casing Pulling Perfs at 4300' with 2 sx cement at 2715'. Casing Pulling Pulling Perfs at 4300' with 2 sx cement at 2715'. Casing Pulling P	(phone)316-624-7455 _5326-43' ent on top, posal Received by Glenn Barlow (TECHNICIAN) All X Part None
ompany to plug at: Hour: 4 p.m. Day: lugging proposal received from Don Horn company name) Sargent's Casing Pulling ere: 5½" at 5850' PBTD 5347' Perfs at lst plug set CIBP at 4300' with 2 sx ceme 2nd plug pump 50 sx cement at 2715'. Brd plug pump 50 sx cement at 505', 4th plug pump 20 sx cement at 40-0'. Plugging Pro lugging Operations attended by Agent?: perations Completed: Hour: 11 a.m. Day: CTUAL PLUGGING REPORT 1st plug set CIBP	(phone)316-624-7455 _5326-43' ent on top, posal Received by Glenn Barlow (TECHNICIAN) All X Part None
Company to plug at: Hour: 4 p.m. Day: Plugging proposal received from Don Horn company name) Sargent's Casing Pulling dere: 5%" at 5850' PBTD 5347' Perfs at lst plug set CIBP at 4300' with 2 sx ceme 2nd plug pump 50 sx cement at 2715', 3rd plug pump 50 sx cement at 505', 4th plug pump 20 sx cement at 40-0'. Plugging Pro Plugging Operations attended by Agent?: Operations Completed: Hour: 11 a.m. Day: ACTUAL PLUGGING REPORT 1st plug set CIBP	(phone)316-624-7455 _5326-43' ent on top, posal Received by Glenn Barlow (TECHNICIAN) All X Part None
company to plug at: Hour: 4 p.m. Day: lugging proposal received from Don Horn company name) Sargent's Casing Pulling ere: 5½" at 5850' PBTD 5347' Perfs at lst plug set CIBP at 4300' with 2 sx ceme 2nd plug pump 50 sx cement at 2715', 3rd plug pump 50 sx cement at 505', 4th plug pump 20 sx cement at 40-0'. Plugging Pro lugging Operations attended by Agent?: crual Plugging Report 1st plug set CIBP 2nd plug pumped 50 sx cement at 2715',	(phone)316-624-7455 5326-43' ent on top, Posal Received by Glenn Barlow (TECHNICIAN) All X Part None 21 Month: 4 Year:19 88 at 4300' with 2 sx cement on top,
Company to plug at: Hour: 4 p.m. Day: Plugging proposal received from Don Hore Company name) Sargent's Casing Pulling Pere: 5%" at 5850' PBTD 5347' Perfs at 1st plug set CIBP at 4300' with 2 sx ceme 2nd plug pump 50 sx cement at 2715', 3rd plug pump 50 sx cement at 505', 4th plug pump 20 sx cement at 40-0'. Plugging Pro Plugging Operations attended by Agent?: Operations Completed: Hour: 11 a.m. Day: ACTUAL PLUGGING REPORT 1st plug set CIBP 2nd plug pumped 50 sx cement at 2715', 3rd plug loaded hole with mud and shot at	(phone)316-624-7455 5326-43' ent on top, Glenn Barlow (TECHNICIAN) AllXPartNone
Company to plug at: Hour: 4 p.m. Day: Don Hore Plugging proposal received from Don Hore Company name) Sargent's Casing Pulling Pere: 5½" at 5850' PBTD 5347' Perfs at 1st plug set CIBP at 4300' with 2 sx cemes 2nd plug pump 50 sx cement at 2715', 3rd plug pump 50 sx cement at 505', 4th plug pump 20 sx cement at 40-0'. Plugging Operations attended by Agent?: Operations Completed: Hour: 11 a.m. Day: ACTUAL PLUGGING REPORT 1st plug set CIBP 2nd plug pumped 50 sx cement at 2715', 3rd plug loaded hole with mud and shot at 50 sx cement at 505',	
Company to plug at: Hour: 4 p.m. Day: Plugging proposal received from Don Horn (company name) Sargent's Casing Pulling Were: 5½" at 5850' PBTD 5347' Perfs at 1st plug set CIBP at 4300' with 2 sx ceme 2nd plug pump 50 sx cement at 2715', 3rd plug pump 50 sx cement at 505', 4th plug pump 20 sx cement at 40-0'. Plugging Pro Plugging Operations attended by Agent?: Operations Completed: Hour: 11 a.m. Day: ACTUAL PLUGGING REPORT 1st plug set CIBP 2nd plug pumped 50 sx cement at 2715',	(phone)316-624-7455 5326-43' ent on top, Posal Received by Glenn Barlow (TECHNICIAN) All X Part None 21 Month: 4 Year:19 88 at 4300' with 2 sx cement on top, t 700', in cement, shot off at 51P[=famd/spumped STATE COMPORATION COMMISSION]

FORM CP-2/3 Rev.01-84