## STATE OF KANSAS STATE CORPORATION COMMISSION

Give All Information Completely
Make Required Affidavit
Mail or Deliver Report to:
Conservation Division
State Corporation Commission

WELL	PLUCGING	RECORD	15-0
------	----------	--------	------

5-077-00969-0000

· Mindeline Address on

P. O. Box 17027 Vichita, Kansas 67217 NONTH	Location as "N	Harper County. Sec. $\frac{25}{\text{C-E}}$ Twp. $\frac{31}{2-\text{SE}}$ Rge. $\frac{9}{4-\text{SW/4}}$ (E) (W) Location as "NE/CNWKSWK" or footage from lines $\frac{25}{2-\text{SE}}$ (L-SW/4)					
NONTA	Lease Owner_	Mull Drlg	. Co., I	nc.			
	Lease Name _	Antrim-Ca Box 328	wbpeTT	Kanese A	7009	_ Weil No	
					<del>. · · · · · · · · · · · · · · · · · · ·</del>		
			as Oil, Gas o	- ·			
i   i	Date well com		-			10	
	Application for	plugging appro	ved		Au	19	
i l i	Plugging comm	nenced					
	Plugging comp	oleted				igust 21, <sub>19</sub> 72	
	Reason for aba	Reason for abandonment of well or producing formation Depleted					
	If a producing well is abandoned, date of last production						
				_		ore plugging was co	
Locate well correctly on above Section Plat	menced?			vation Division	or its agents ber	ore budging was co	
e of Conservation Agent who su	pervised plugging of th	is well G.	R. Biber	stein		1	
neing formation		Depth to top	Botto:	m	Total Depth of	Well 43631 F	
depth and thickness of all water	er, oil and gas formatio	ons.					
L, CAS OR WATER RECOR	ens				1	CASING RECORD	
IL, GAS OR WATER RECOI	1	<del></del>	<del></del>	·	1	† · · · · · · · · · · · · · · · · · · ·	
FORMATION	CONTENT	FROM	TO	SIZE	PUT IN	PULLED OUT	
		<u> </u>	<del> </del>	8 5/8	158	None	
<del></del>	<del>-  </del>		<del>                                     </del>	5 1/2	4363	2566.491	
	<del></del>		+	<del>                                     </del>		ļ	
	<del>                                     </del>	·· <del> </del> ·	<del>                                     </del>	<del> </del>	<del> </del>	<del> </del>	
	<del> </del>	·	<b>†</b>	<del> </del>			
Measured T.	D. Dumped sa	and to 4325	and 5	of same and deposition	nt. Shot o	casing at	
roducing it into the hole. If ce- feet for each plug Measured T.	D. Dumped sa	and to 4325	and 5	of same and deposition	nt. Shot o	casing at	
Measured T.  3300', 2300', 31  of 82 jts. of 5	D. Dumped sa	and to 4325	and 5	of same and deposition	nt. Shot o	casing at	
Measured T.  3300', 2300', 31  of 82 jts. of 5	D. Dumped sa	and to 4325	and 5	of same and deposition	nt. Shot o	casing at	
Measured T.  3300', 2300', 31  of 82 jts. of 5	D. Dumped sa	and to 4325	and 5	of same and deposition	nt. Shot o	casing at	
Measured T.  3300', 2300', 31  of 82 jts. of 5	D. Dumped sa	and to 4325	and 5	of same and deposition	nt. Shot o	casing at	
Measured T.  3300', 2300', 31  of 82 jts. of 5	D. Dumped sa	and to 4325	and 5	of same and deposition	nt. Shot o	casing at	
Measured T.  3300', 2300', 31  of 82 jts. of 5	D. Dumped sa	and to 4325	and 5	of same and deposition	nt. Shot o	casing at	
Measured T.  3300', 2300', 31  of 82 jts. of 5	D. Dumped sa Oo', 3000', 29 1/2" casing.	and to 4325 000', 2800' Built a ro	and 5 , 2700', ck bridg	sacks ceme 2600', an e at 175'.	nt. Shot o	casing at	
Measured T.  3300', 2300', 31 of 82 jts. of 5 readymix concret	D. Dumped sa Oo', 3000', 29 1/2" casing.	al description is nec	and 5 , 2700', ck bridg	sacks ceme 2600', an e at 175'.	nt. Shot o	casing at	
Measured T.  3300', 2300', 31 of 82 jts. of 5 readymix concret	D. Dumped sa Oo', 3000', 29 1/2" casing.	al description is nec	and 5  2700', ck bridg	sacks ceme 2600', an e at 175'.	nt. Shot o	casing at	
Measured T.  3300', 2300', 31 of 82 jts. of 5 readymix concret	D. Dumped sa Oo', 3000', 29 1/2" casing. e.  (If addition. Rockhold En Box 698 Gr	al description is need gineering, eat Bend,	and 5 , 2700', ck bridge	sacks ceme 2600', an e at 175'.  K of this sheet)	nt. Shot of 2550'. F	casing at	
Measured T.  3300'. 2300', 31 of 82 jts. of 5 readymix concret	D. Dumped sa Oo', 3000', 29 1/2" casing. e.  (If addition Rockhold En Box 698 Gr	al description is neglineering, eat Bend,	essary, use BAC Inc. Kansas Bart	sacks ceme 2600', an e at 175'.  K of this sheet) 67530 on	nt. Shot of 2550'. F Plugged w	casing at Pulled a tota vith h yards	
Measured T.  3300', 2300', 31  of 82 jts. of 5  readymix concret  of Plugging Contractor  E OF Kansas  James W.	D. Dumped sa Oo', 3000', 29 1/2" casing. e.  (If addition. Rockhold En Box 698 Gr	al description is need gineering, eat Bend,	essary, we BAC Inc. Kansas Bart (employee of	sacks ceme 2600', an e at 175'.  K of this sheet) 67530  on cowner) or (ow	nt. Shot of 2550's F Plugged w	easing at Pulled a tota with L yards	
Measured T.  3300', 2300', 31  of 82 jts. of 5  readymix concret  e of Plugging Contractor  ESS  TE OF Kansas  James W.  being first duly sworn on oath	D. Dumped sa Oo', 3000', 29 1/2" casing. e.  (If addition. Rockhold En Box 698 Gr  , CO Rockhold , says: That I have k	al description is necessary and to 4325 000', 2800' Built a ro	essary, use BAC Inc. Kansas  Bart (employee of facts, statem	sacks ceme 2600', an e at 175'.  K of this sheet) 67530  on cowner) or (ownerts, and matt	nt. Shot of 2550's F Plugged w	easing at Pulled a tota with L yards	
Measured T.  3300'. 2300', 31 of 82 jts. of 5 readymix concret  e of Plugging Contractor  ESS  TE OF Kansas  James W. being first duly sworn on oath	D. Dumped sa Oo', 3000', 29 1/2" casing. e.  (If addition Rockhold En Box 698 Gr  Rockhold , says: That I have k	al description is neglineering, eat Bend,	essary, use BAC Inc. Kansas  Bart (employee of facts, statem help me God	sacks ceme 2600', an e at 175'.  K of this sheet) 67530  on cowner) or (ownerts, and matt	nt. Shot of 2550's F Plugged w	easing at Pulled a tota with L yards	
Measured T.  3300'. 2300', 31 of 82 jts. of 5 readymix concret  e of Plugging Contractor  ss.  TE OF Kansas  James W. being first duly sworn on oath	D. Dumped sa Oo', 3000', 29 1/2" casing. e.  (If addition Rockhold En Box 698 Gr  Rockhold , says: That I have k	al description is necessary and correct. So (Signature)	essary, use BAC Inc. Kansas  Bart (employee of a facts, statem help me Gook x 698	sacks ceme 2600', an e at 175'.  K of this sheet) 67530 on cowner) or (ownents, and mattel.	nt. Shot of d 2550'. F Plugged w	of the above-described and the log of	
Measured T.  3300'. 2300', 31 of 82 jts. of 5 readymix concret  e of Plugging Contractor  ESS  TE OF Kansas  James W. being first duly sworn on oath	D. Dumped sa Oo', 3000', 29 1/2" casing. e.  (If addition Rockhold En Box 698 Gr  Rockhold , says: That I have k	al description is necessary and correct. So (Signature)	essary, use BAC Inc. Kansas  Bart (employee of a facts, statem help me Gook x 698	sacks ceme 2600', an e at 175'.  K of this sheet) 67530  on cowner) or (ownerts, and matt	nt. Shot of d 2550'. F Plugged w	casing at Pulled a tota with h yards	
Measured T.  3300', 2300', 31 of 82 jts. of 5 readymix concret  e of Plugging Contractor  ESS  TE OF Kansas  James W.  being first duly sworn on oath edgscribed well as filled and the contractor of the contract	D. Dumped sa Oo', 3000', 29 1/2" casing. e.  (If addition Rockhold En Box 698 Gr  Rockhold , says: That I have k at the same are true said. Ke.	al description is necessary and correct. So  (Signature)  (Signature)  (Signature)	essary, use BAC Inc. Kansas  Bart (employee of facts, statem help me Good at Bend	sacks ceme 2600', an e at 175'.  K of this sheet) 67530 on cowner) or (ownents, and mattel.	nt. Shot of d 2550'. F Plugged w	of the above-described and the log of	
Measured T.  3300'. 2300', 31 of 82 jts. of 5 readymix concret  e of Plugging Contractor  ESS  TE OF Kansas  James W. being first duly sworn on oath	D. Dumped sa Oo', 3000', 29 1/2" casing. e.  (If addition Rockhold En Box 698 Gr  Rockhold , says: That I have k at the same are true said. Ke.	al description is necessary and correct. So (Signature)	essary, use BAC Inc. Kansas  Bart (employee of facts, statem help me Good at Bend	sacks ceme 2600', an e at 175'.  K of this sheet) 67530  on on owner) or (ownents, and matth.  Ames (c), , Ks. 6753	nt. Shot of d 2550'. F Plugged w	of the above-described and the log of	
Measured T.  3300', 2300', 31 of 82 jts. of 5 readymix concret  e of Plugging Contractor  ESS  TE OF Kansas  James W.  being first duly sworn on oath edgscribed well as filled and the contractor of the contract	D. Dumped sa Oo', 3000', 29 1/2" casing. e.  (If addition Rockhold En Box 698 Gr  Rockhold , says: That I have k at the same are true said. Ke.	al description is necessary and correct. So  (Signature)  (Signature)  (Signature)	essary, use BAC Inc. Kansas  Bart (employee of facts, statem help me Good at Bend	sacks ceme 2600', an e at 175'.  K of this sheet) 67530 on cowner) or (ownents, and mattel.	nt. Shot of d 2550'. F Plugged w	of the above-described and the log of	

15-077-60969-0000

## ROTARY DRILLERS LOG

COMPANY

: PURCELL-MULL DRILLING CO., INC.

ROTARY DRILLING COMMENCED: 8-28-55

WICHITA, KANSAS

CONTRACTOR

: Purcell-Mull Drilling Co., Inc.

ROTARY DRILLING COMPLETED: 9-10-55

Wichits, Kensas

CASING RECORD : Set 8 5/8" @ 158' cemented

LOCATION: ANTE IM-CAMPBELL #1

with 150 sacks cement

C (E/2) SE/L SW/L Sec. 25-315-971

Set 52" @ 1363' cemented

Harper County, Kansas

with 150 sacks coment

(Figures indicate bottom of formation - measurements from top of Rotary Bushing)

Sand Red Bed & Shells Shale & Shells Shale & Lime Lime & Shale Lime & Shale Lime & Shale Lime & Shale Shale & Lime	20 158 500 1250 1495 1615 1825 2610 2735	Lime & Shale Shale & Idmo Lime & Shale State Corrock   1157 Lime & Shale Shale & Lime Shale & Lime Lime (Miss) CONSERVATION COMMISSION Wichite Kanses
Shale & Lime	3096	Kansas DIVISION

I hereby certify that this is a true and correct copy of the above log to the best of my knowledge.

Purcell-Mull Drilling Co., Inc.

SECRETARY

STATE OF KANSAS

COUNTY OF SEDOWICK

Subscribed and sworn to before me this 19th day of September, 1955

MI CONTISSION EXPIRES: JANUARY 28, 1957.

STATE CORPORATION COMMISSION 1261472

CONSERVATION DIVISION Wichite, Kenses