To: 7	1 051588 10-2	7	025-20 051	5/0 /
STATE COF	RPORATION COMMISSION	7 API NUMBER 15-	023-20,931-22	o co ro
	TION DIVISION - PLUGGING SECTION RADO DERBY BUILDING	NE NE SW , SEC.	<u>27</u> , T <u>3</u>	<u>4</u> s, R <u>24</u> w≯
	KANSAS 67202	2310	feet from	S section line
TECHNICIA	AN'S PLUGGING REPORT			E section line
	License / 8802	Lease Name Iser	ıbart 27 Wel	1 1
Operator:	Cobra Oil & Gas Corporation	CountyClark	:	188.50
Name& Address	P.O. Box 1929	Well Total Dept	h5800	fee
	Woodward, OK 73802-1929	Conductor Pipe:		
	· · · · · · · · · · · · · · · · · · ·	Surface Casing:		
Abandonec	d Oll Woll Gas WellX			
	It as hereinafter indicated		_ 0	
	Contractor Sargent's Casing Pulling			
			_ LICONSO NUMB	er
	P.O. Box 596, Liberal, KS 67905		10	
	to plug at: Hour: 10 a.m. Day:		Y	ear:19
Plugging	proposal received from Kirl	by Lillard		
(company	name) Sargent's Casing Pulling		(phone	316-624-7455
	" at 5799' w/250 sx cement, PBTD 5			
1st plug s	set CIBP at 5380' and dump 2 sx.:ceme	ent on top,		
	pump 50 sx cement at 1000', 3rd plu		at 760',	
4th plug r	pump 10 sx cement at 40.		-	
1 - 0 1				
· ·			Richard	Locar
	Plugging Prop	osal Received by		ICIAN)
• •	:	•		
Plugging	Operations attended by Agent?: A	II X Part		n a
	Operations attended by Agent?: A		No	
Operation	ns Completed: Hour: 4 p.m. Day:	27 Month:	No	@ar:19 <u>92</u>
Operation	ns Completed: Hour: 4 p.m. Day:	27 Month:	No	@ar:19 <u>92</u>
Operation ACTUAL PL 2nd plug p	LUGGING REPORT 1st plug set CIBP at pumped 50 sx cement at 1000',	27 Month:	No	@ar:19 <u>92</u>
Operation ACTUAL PL 2nd plug p 3rd plug p	LUGGING REPORT 1st plug set CIBP at pumped 50 sx cement at 1000', pumped 50 sx cement at 760',	27 Month: t 5380' and dumped 2	No	ear:19 <u>92</u> top,
Operation ACTUAL PL 2nd plug p 3rd plug p	LUGGING REPORT 1st plug set CIBP at pumped 50 sx cement at 1000',	27 Month: t 5380' and dumped 2	10 Y	ear:19 <u>92</u> top,
Operation ACTUAL PL 2nd plug p 3rd plug p	LUGGING REPORT 1st plug set CIBP at pumped 50 sx cement at 1000', pumped 50 sx cement at 760',	27 Month: t 5380' and dumped 2	10 Y	ear:19 92 top,
Operation ACTUAL PL 2nd plug p 3rd plug p	LUGGING REPORT 1st plug set CIBP at pumped 50 sx cement at 1000', pumped 50 sx cement at 760',	27 Month: t 5380' and dumped 2	10 Y	ear:19 <u>92</u> top,
Operation ACTUAL PL 2nd plug p 3rd plug p 4th plug p	LUGGING REPORT 1st plug set CIBP at pumped 50 sx cement at 1000', pumped 50 sx cement at 760', pumped 10 sx cement at 40'.	27 Month: t 5380' and dumped 2	10 Y	ear:19 92 top,
Operation ACTUAL PL 2nd plug p 3rd plug p 4th plug p	LUGGING REPORT 1st plug set CIBP at pumped 50 sx cement at 1000', pumped 50 sx cement at 760',	27 Month: t 5380' and dumped 2 Recovered 3800' of	10 Y sx cement on	top, STATE GORYDOA TON
Operation ACTUAL PL 2nd plug p 3rd plug p 4th plug p	LUGGING REPORT 1st plug set CIBP at pumped 50 sx cement at 1000', pumped 50 sx cement at 760', pumped 10 sx cement at 40'. Used common cement by Sargent's.	27 Month: t 5380' and dumped 2 Recovered 3800' of	10 Y sx cement on	top, STATE GORYDOA TON

FORM CP-2/3