

15-175-20165-0000

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
P. O. BOX 17027
Wichita, Kansas 67217

Rev. 3-15-72
FORM CP-1

RECEIVED
STATE CORPORATION COMMISSION

JAN 2 1974

CONSERVATION DIVISION
Wichita, Kansas

WELL PLUGGING APPLICATION FORM
File One Copy

Lease Owner Alpar Resources, Inc
Address Box 906 Perryton, Texas 79070
Lease (Farm Name) Wright Well No. 1
Well Location N.E. - S.E. Sec. 23 Twp. 34S Rge. 33 (E) (W) X
County Seward Total Depth 6700 Field Name Condit
Oil Well Gas Well Input Well _____ SWD Well _____ Rotary D & A _____
Well Log filed with application as required Yes
Date and hour plugging is desired to begin Upon Approval

PLUGGING OF THIS WELL WILL BE DONE IN ACCORDANCE WITH K.S.A. 55-128 OF THE RULES AND REGULATIONS OF THE STATE CORPORATION COMMISSION.

Name of company representative authorized to be in charge of plugging operations:

Bill Hair Address Box 906 Perryton, Texas 79070

Plugging Contractor Sargeants Casing Pulling Serv. License No. 511

Address Box 506 Liberal, Kansas 67901

Invoice covering assessment for plugging this well should be sent to:

Name Alpar Resources, Inc.

Address Box 906 Perryton, Texas 79070

and payment will be guaranteed by applicant or acting agent.

Signed: Robert Sargeant
Applicant or Acting Agent

Date: Dec 28 - 73

State of Kansas



State Corporation Commission
CONSERVATION DIVISION
(Oil, Gas and Water)
P. O. Box 17027 3830 S. Meridian
WICHITA, KANSAS 67217

January 2, 1974

WELL PLUGGING AUTHORITY

Well No.	1
Lease	Wright
Description	NE SE 23-34-33W
County	Seward
Total Depth	6700'
Plugging Contractor	Sargents Casing Pulling

Alpar Resources, Inc.
Box 906
Perryton, Texas 79070

Gentlemen:

This is your authority to plug the above subject well in accordance with the Rules and Regulations of the State Corporation Commission.

This authority is void after 90 days from the above date.

Yours very truly,

J. Lewis Brock
J. Lewis Brock, Administrator

Mr. Edgar Eves, P. O. Box "F", Sublette, Kansas 67866
is hereby assigned to supervise the plugging of the above named well.