To:	1020479 7-a4	API NUMBER 15- Docket #E-23,598 /90 P
STATE COR	PORATION COMMISSION TION DIVISION - PLUGGING SECTION	NW SE , SEC. 6 .T 33 S, R 40 WX
	RADO DERBY BUILDING KANSAS 67202	1980 feet from S section line
	AN'S PLUGGING REPORT	
	License #4549	Lease Name Santa Fe Trail Unit A 2-1
Name& Address	Anadarko Petroleum Corporation P.O. Box 351	County Morton
		Well Total Dopth 5988 194.61 feet
	Liberal, KS 67905-0351	Conductor Pipe: Sizefeet
		Surface Casing: Size 8 5/8 feet 1606
Abandonad	Oli Weil Gas Well	ENHR Well X SHD Well D&A
	1 as hereinafter indicated	
Plugging	Contractor Sargent's Casing Pull	ling Service License Number 6547
Address	620 S. Lincoln, Liberal, KS 67901	
Company †	o plug at: Hour: 2:30 p.m. Day:	22 Month: 7 Year: 19 92
	proposal received from Don Hort	
	•	(phone) 316-624-7455
	at 5546' w/500 sx cement, PBTD 5	
ist ping	set CIBP at 5300', run 10 sx cement	on top or CIBP with tubing,
2nd plug	pump 50 sx cement at 1656',	
3rd_plug	pump 50 sx cement at 8001,	
4th plug	pump 15 sx cement at 50-0'.	
	Plugging Propo	Glenn Barlow
•	÷	(TECHNICIAN)
Plugging (Operations attended by Agent?: Al	Part X None
Operation	s Completed: Hour: 11:30 a.mpay:	24 Month: 7 Year:19 92
		5300', run 10 sx cement on top of CIBP with tubi
ACTUAL PL		5300', run 10 sx cement on top of CIBP with tubi
2nd plug	UGGING REPORT 1st plug set CIBP at	5300', run 10 sx cement on top of CIBP with tubi
2nd plug 3rd plug	ugging report 1st plug set CIBP at pump 50 sx cement at 1656',	5300', run 10 sx cement on top of CIBP with tubi
2nd plug 3rd plug 4th plug	pump 50 sx cement at 1656', pump 50 sx cement at 800', pump 15 sx cement at 50-0'.	5300', run 10 sx cement on top of CIBP with tubi
2nd plug 3rd plug 4th plug	pump 50 sx cement at 1656', pump 50 sx cement at 800',	5300', run 10 sx cement on top of CIBP with tubi
2nd plug 3rd plug 4th plug Heavy mud	pump 50 sx cement at 1656', pump 50 sx cement at 800', pump 15 sx cement at 50-0'. I between all plugs.	5300', run 10 sx cement on top of CIBP with tubi
2nd plug 3rd plug 4th plug Heavy mud	pump 50 sx cement at 1656', pump 50 sx cement at 800', pump 15 sx cement at 50-0'. I between all plugs. Used common cement by Sargent's. If	STATE CORPORATION COMMISSION
2nd plug 3rd plug 4th plug Heavy mud	pump 50 sx cement at 1656', pump 50 sx cement at 800', pump 15 sx cement at 50-0'. I between all plugs. Used common cement by Sargent's. I	5300', run 10 sx cement on top of CIBP with tubi
2nd plug 3rd plug 4th plug Heavy mud Remarks:	pump 50 sx cement at 1656', pump 50 sx cement at 800', pump 15 sx cement at 50-0'. I between all plugs. Used common cement by Sargent's. I	STATE CORPORATION COMMISSION OF STATE CORPORATION COMMISSION OF 4½" casing.
2nd plug 3rd plug 4th plug Heavy mud Remarks:	pump 50 sx cement at 1656', pump 50 sx cement at 800', pump 15 sx cement at 50-0'. I between all plugs. Used common cement by Sargent's. I	STATE CORPORATION COMMISSION