STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
211 NORTH EROADWAY
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM File One Copy

(Applicant) Lease (Farm Nam	ıe) Subera	Well No. 1
Well Location		Sec.21 Twp. 34SRge. 3W (E) -
County	Sumner	Field Name (if any)
Total Depth	4977 Oil	Gas Dry Hole X
Was well log fi	led with application	on? Yes If not, explain:
Date and hour p	lugging is desired	to begin 8-11-55
Plugging of the	well will be done	in accordance with the Rules and Regulation
of the State Co	rporation Commissio	on.
Name of the per	son on the lease in	charge of well for owner
Tom Elliott		Address Council Grove, Kansas
Plugging Contra	ctor	Herndon Drilling Company
D7	ctor's License No.	none required - rotary drilled dry hole
ringging Contra	~ · · · · · · · · · · · · · · · · · · ·	Monageduried - 10 far A dirition of Monage
	_	roit, Tulsa, Oklahoma
Address	823 S. Detr	
Address	823 S. Detr	roit, Tulsa, Oklahoma .ugging this well should be sent to
Address Invoice covering Herndon Drilling	823 S. Detr g assessment for pl	roit, Tulsa, Oklahoma
Address Invoice covering Herndon Drillin	823 S. Detr g assessment for pl	roit, Tulsa, Oklahoma .ugging this well should be sent to
Address Invoice covering Herndon Drilling and payment wil	823 S. Detr g assessment for pl	roit, Tulsa, Oklahoma Lugging this well should be sent to Address823 S. Detroit, Tulsa, Oklahom applicant.



STATE OF KANSAS

STATE CORPORATION COMMISSION

CONSERVATION DIVISION 211 NORTH BROADWAY WICHITA, KANSAS

August 15, 1955

Well No.

1

Lease

Subera

Description

SV SE SE 21-34-3W

County File No. Summor 11:2-20

Herndon Drilling Company Box 459 Tulsa, Oklahoma

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. W. G. Buffington, R.R. #2, Geuda Springs, Kansas.

STATE CORPORATION COMMISSION CONSERVATION DIVISION

Y (/

S.S. Greider

co:

District Plugging Supervisor

WELL PLUGGING SUPERVISOR