## STATE OF KANSAS STATE CORPORATION COMMISSION

Form CP-4

Give All Information Completely
Make Required Affidavit
Mail or Deliver Report to:
Conservation Division
State Corporation Commissio
· · · · · · · · · · · · · · · · · · ·

## WELL PLUGGING RECORD

212 No. Market Wichita, Kansas 67202	Meade		Count	y. Sec. 20	Twp.345 Rge.	30W (E)_	(W)
NORTH	Location as "NE	C/CNW#SW#"	or footage fro	m lines	<u>CSW-SW</u>		
	Lease Owner		<u>&amp; Parker</u>	<u></u>			<del></del>
	Lease Name Office Address	Holmes Box 906	Perryt	on, Texa		_ Well No	
<u> </u>	Character of W	ell (completed	as Oil Cas o	Dry Hole)	Dry Hol	<del></del> е	
	Date well comp	oleted 1	<u>0-12</u>				1970
	Application for						_19
	Application for p			<u> 12</u> _			<u> 19 70</u>
	Plugging comme		0-12			<del></del>	<u> 19 70</u>
	Plugging comple Reason for aban			<b>-</b> form atten	Drv		_19 <u>_70</u>
	Meason for aban	dominent of we	or producing	g 101manon —			
	If a producing v	well is abando	ned, date of la	st production_			19
Locate well correctly on above			n the Conserv	ation Division	or its agents befo	ore plugging	was com-
Locate well correctly on above Section Plat Name of Conservation Agent who sup	menced?	res Tes	Tves- @	Sublette	Kansas		
Producing formation.	ervised plugging of this	enth to ton	Botton	DRDTEGO	Total Depth of	Well 4550	O Feet
Show depth and thickness of all water					z rotar Depth Gr	*********	
-						OLCING DE	CORD
OIL, CAS OR WATER RECOR	1	· · · · · · · · · · · · · · · · · · ·	<del></del>			CASING RE	CORD
FORMATION	CONTENT CONTENT	FROM	400 es	8 5/8	1313	None	
Ogalda Permian Carbonatesx	fresh water Salt Water	2550	3710	50 5/0	<del>  <u>+</u>)+/</del> -	10116	<del></del>
Toronto	Salt water	4343	4405			·	
Lansing	Salt water	4460		. D .	STATE REC	TONED	
		<u> </u>			STATE CORPORA	FONED	·
		_			007	2 O 4	354014
Describe in detail the manner in					PONSERVATE	9 1970	
Describe in detail the manner in		!			Wichya	PN PIVISIO	71.7
(33 joints) 1007 fe Drilling Mud. Rigg cement and pumped d out and layed down Halliburton 8 5/8 p cement by Halliburt level. Dug out well 8 5/8" casing. Cemented plugs fr	ed Halliburt own drill pi drill pipe a lug down wit on and pumpe head and cu	on and me and on fille h Kelly d in 8 5/8 up to 89 up to 4	nixed an hisplace ed hole to 44 f 5/8. Fi off 4*	d spotted cement with muce eet. Milled up below Ceround	t with much up to 45 xed 15 satured 15 satured 15 satured 15 xed 4 feet 15.L. and w	ks commod. Pull feet. acks com below	on Led Pushe mmon ground
	(Hadditional alliburton iberal, Kans	description is nec	essary, use BACK	of this sheet)			
STATE OF Texas  Bill Hai  well, being first duly sworn on oath,	<u>r</u>	NTY OF OC	(employee of	owner) or (XX)	tilekor operatox)	of the above	-described
above-described well as filed and tha	t the same are true an	d correct. So (Signature)	help me God.	ill,	Hair		
			Box	<u>906, Per</u>	ryton, Te	xas 79	9070
Subscribed and Sworn to befo	ore me this 27t	hday of	Octo Viole	ber	(Address)		
My commission expires June 1,	1971			<del>, , , , , , , , , , , , , , , , , , , </del>		Notary	Public.