

# PRODUCTIVITY TEST BARREL TEST

CS

15-189-20760-  
0000

\*\* RULE 82-3-202 of the General Rules and Regulations of the State of Kansas:

Productivities, when to be taken. (f) Pool tests. Pool tests shall be taken as ordered by the Commission at twelve month intervals thereafter.

COUNTY <u>Seward</u>	EFFECTIVE DATE _____ (Office use only)
FIELD <u>Ray Green</u>	PURCHASER _____
PRODUCING FORMATION <u>L. Chester</u>	ADDRESS _____ (if new operator)
OPERATOR <u>Cities Service</u>	_____
LEASE <u>Hedkins B</u>	_____

* WELL NO.	SEC.	TWP.	RGE.	BOPD	WATER %	DATE TAKEN
1. <u>1</u>	<u>24</u>	<u>34</u>	<u>35</u>	<u>37</u>	<u>36.7%</u>	<u>7/10/85</u> 250414
2. <u>2</u>	<u>24</u>	<u>34</u>	<u>35</u>	<u>7</u>	<u>83.7%</u>	<u>7/10/85</u> 222414
3. _____	_____	_____	_____	_____	_____	_____
4. _____	_____	_____	_____	_____	_____	_____
5. _____	_____	_____	_____	_____	_____	_____
6. _____	_____	_____	_____	_____	_____	_____
7. _____	_____	_____	_____	_____	_____	_____
8. _____	_____	_____	_____	_____	_____	_____
9. _____	_____	_____	_____	_____	_____	_____
10. _____	_____	_____	_____	_____	_____	_____

FIELDMAN'S REMARKS: \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

WITNESSES:

<u>James R. Kapp</u> FOR STATE	<u>LG Hooper</u> FOR OPERATOR	_____ FOR OFFSET
-----------------------------------	----------------------------------	---------------------

\*NOTE: IF THE WELL IS TEMPORARILY ABANDONED AT TIME OF TEST, BUT AT A LATER DATE IS PUT ON PUMP, PLEASE HAVE IT TESTED AT THAT TIME. THIS PREVENTS OVERPRODUCTION ON THE TABLE "B" REPORT. TO SCHEDULE A TEST CALL: DISTRICT OFFICE #6, 1014 CODY, HAYS, KANSAS 67601 (913) 628-1200.

## STATE CORPORATION COMMISSION OF KANSAS. CONSERVATION DIVISION

RECEIVED  
STATE CORPORATION COMMISSION  
AUG 5 1985  
08-05-85  
CONSERVATION DIVISION  
Wichita, Kansas

Operate

- sig W.M. Guernerwald #8- 4-35-30 FB Watertank Lease  
200 lb on Castor locust good Adam
- sig ~~W.M. Guernerwald # 4-35-30 Wood water tanks~~
- Gasometer ~~rent~~ 1" on diffuser
- sig W.M. Guernerwald # <sup>FD Adam</sup> 1- 2-35-30 FB Watertank 210 } open pit Adam <sup>sw + oil</sup>
- W.M. Guernerwald For #1 - 3-35-30 FB water tank 210 } open pit salt w + oil
- sig W.M. Guernerwald Adam #. 4-67 - 11-35-30 gas compressed open water well  
at well # 4
- sig W.M. Guernerwald Adam #5- 3-35-30 salt water deepnd Wood water tank overflow into open  
pit with water + oil in pit

Beadle AS No  
c 52 7-23-47