4-14-88 15-173-01636-006 2 040403 API NUMBER 15- 5-30-64 To: STATE CORPORATION COMMISSION CONSERVATION DIVISION - PLUGGING SECTION SW SW SE, SEC. 15, T 29 S, R 1 200 COLORADO DERBY BUILDING WICHITA, KANSAS 67202 S section line TECHNICIAN'S PLUGGING REPORT \_\_\_\_\_\_2310 \_ feet from E section line Lease Name 0.S.A. Hell # Operator License 8 Operator: W.D. Short County Sedgwick 121.65 Name& Address Well Total Depth 3743 Gonductor Pipe: Size  $5\frac{1}{2}$ " feet / 3728 \_\_Oxford\_KS\_67119\_ Surface Casing: Size 8 5/8 feet 325 Abandoned Oll Well\_\_\_\_ Gas Well\_\_\_\_ Input Well\_X\_\_ SWD Well\_\_\_\_ D&A\_\_\_\_ Other well as hereinafter indicated Plugging Contractor Gressel Corporation License Number 5822 Address Box 322 Haysville KS 67060 Company to plug at: Hour: Day: Month: Year:19 Plugging proposal received from <u>Bill Short</u> (company name) W.D. Short were: 30 sxs on bottom, redimix top Plugging Proposal Received by District #2 Office (TECHNICIAN) Plugging Operations attended by Agent?: All\_\_\_\_\_\_ Part\_\_\_\_ None\_ Operations Completed: Hour: Day: 14 Month: 4 Year:1988 ACTUAL PLUGGING REPORT A 30 sk plug was pumped down the  $5\frac{1}{2}$ " casing to 3225' on 4-5-88 <u>by United Cementing Co. The pumping pressure was 500# and the shut in pressure was </u> 350#, completed at 14:36 yours. The  $5\frac{1}{2}$ " casing was shot off and recovered from 2011'. The 5½" was pulled to 410'. Redimix was dumped inside the 5½" and circulated to surface. Hillary STATE CORPOSATION COMMISSION ADD D 6 fore 4-210-88 Remarks: Wellington Redimix. (if additional description necessary, use BACK of this form.) I (did / dld not) observe this plugging.

Signed

DATE 5-5-88 WC

FORM CP-2/3 Rev. 01-84